	PHONE CALL DISCUSION CHECK TRIP CONFERENCE		
RECORD OF COMMUNICATION	OTHER (SPECIFY)		
	(Record of item checked above)		
JIM EVENTS	FROM: Bu LEWIS DATE 1:30 any		
Ting CIGOS	NATIONAL ELECTRIC GIL TIME /		
HATTONIA ESCHOLECO	509-535-875/ 5/13/87		
PCB INSPECTION			
SUMMARY OF COMMUNICATION			
Mr. LEWIS CALLED TO SAIN HE HAD RECENTED DOTIFICATED THAT HIS WASTE OIL CONTAINED PCBS. HE MSKED WHAT NEEDED TO BE DONE & FUD HIM IT SHOULD BE DISPOSED OF AT A CHEMICAL WASTE LANDFILL SUCH AS CHEM SECURITY SYSTEMS IN ARLINGTON ONEGON ON ENVIROSAFE LINE IN SDAFO. DALSO TOLD HIM THAT HE NEEDED TO KEEP RECONS, LAISEL THE BARREL OF PCB CONTAMINATED OIL AND THE STORE THE OIL IN A LOCATION THAT MET EPA'S STORAGE FACILITY REQUIREMENTS & ALSO			
	HE WORLD BE RECEIONA A		
	L SHONTLY WHICH WOULD OUTLING		
THE ULOCATIONS	DHICH DE FOUND.		
CONCLUSIONS, ACTION TAKEN OR REQUIRED			
я			
8			
INFORMATION COPIES	¥		
то:			

M/S 524

Certified Mail

PUPY 10 MOD

Laboratory Analysis Notice

Bill N. Lewis, Plant Manager National Electric Coil Spokane Service Center 415 N. Fammher Road Spokane, WA 99220

Dear Mr. Lewis:

On 3/12/82, samples were obtained as part of an inspection at National Electric Coil, Spokane, Washington. These samples have been analyzed for polychlorinated biphenyl (PCB) by the Environmental Protection Agency analytical laboratory. A copy of that lab report is being forwarded to you with this letter.

The analysis involves testing of the sample for seven characteristic and distinct types of PCB. They are: Aroclor 1221, 1232, 1242, 1248, 1254, 1260 and 1016. Only the types of Aroclor found will be reported. Aroclor 1254 was detected at 134 ppm in Sample 10035 (Sub B) which was taken from a 55 gallongdeum of waste oil.

Inquiries or correspondence should be directed to Jim Everts, EPA Region 10, Permits and Compliance Branch, M/S 524, 1200 Sixth Avenue, Seattle, Washington 98101; telephone: (206) 442-2632.

Sincerely,

5 1982 MAY Donald A. Donaldson, Chief Compliance Section Date

Enclosure

MPartridge:wmh 5/5/82

CONCURRENCES							
SYMBOL	}						
SURNAME	A.I						
DATE			- 1				
EPA Form 1320-1 (12-70) OFFICIAL FILE COPY							

MAY 1 3 1982 UNITED TATES ENVIRONMENTAL PROTECTION AGENCY

DATE

300

Violation Assessment National Electric Coil

SUBJECT:

Spokane Service Center 415 N. Fancher Road Spokane, WA 99220

FROM

Margo Partridge, EPS

TO

Donald Donaldson, Compliance Section Chief

Thru: Jim Everts, Toxic Substances Team Leader

On March 12, 1982 an EPA inspection was conducted by Michael Watson at the National Electric Coil facility in Spokane, Washington. The inspection was carried out to determine compliance with the PCB Regulations adopted by EPA pursuant to the Toxic Substances Control Act (TSCA). The inspection disclosed violations of these regulations as follows:

Records & Monitoring

40 CFR 761.45(a) requires that beginning July 2, 1978 owners or operators of a facility using or storing at one time at least 45 kilograms (99.4 pounds) of PCBs in PCB Containers shall develop and maintain records on the disposition of PCBs and PCB Items. These records shall form the basis of an annual document prepared for each facility by July 1 covering the previous calendar year. The annual document shall include:

- 1) a) The dates when PCBs and PCB Items are:
 - removed from service,
 - ii) placed into storage for disposal,
 - iii) placed into transport for disposal; and
 - b) the quantities of PCBs and PCB Items removed from service, including:
 - total weight in kilograms of PCBs contained in Containers, with the identification of content on the containers,
 - ii) total number of PCB Transformers and total weight in kilograms of PCBs contained in the transformers,
 - iii) total number of PCB Large High or Low Voltage Capacitors;
 - the location of the initial disposal or storage facility for PCBs and PCB Items removed from service;

2) Total quantities of PCBs and PCB Items remaining in service at the end of the calendar year, including:

total weight in kilograms of any PCBs and PCB Items in PCB Containers with the identification of content on the container.

b) total number of PCB Transformers and total weight in kilograms of PCBs in the transformers,

total number of PCB Large High or Low Voltage Capacitors.

There were no records or annual documents concerning the waste oil which contained 134 ppm PCBs. The term PCB is used to refer to any chemical substance or combination of substances that contain 50ppm (on a dry weight basis) or greater of PCBs, including any byproduct, intermediate, or impurity manufactured at any point in a process. The 55 gallon drum of contaminated waste oil was approximately one-third full and contained more than 10 gallons of liquid (over 99.4 pounds).

The firm has had the waste oil for some time but it is not known whether they have exceeded the thirty day temporary storage provision.

Marking

I. 40 CFR 761.20(a)(1) requires that after July 1, 1978 PCB Containers, defined as any package, barrel, drum ... or other device that contains PCBs or PCB Articles whose surface has been in direct contact with the PCBs, shall be marked as illustrated in Annex V (761.44(a)).

The barrel with waste oil contaminated at 134 ppm PCB was not marked as required in 761.20(a)(1) and 761.44(a).

II. 40 CFR 761.42(c)(3) requires that the storage area used for temporary storage of PCBs be marked as illustrated in Annex V (761.44(a)).

The area where the drum containing waste oil contaminated with PCBs was located was not marked.

This assessment is being referred for your evaluation and determination of further regulatory action.

U.S. ENVIRONMENTAL PROTECTION AGENCY



REGION X

1200 SIXTH AVENUE SEATTLE, WASHINGTON 98101

REPLY TO M/S 524 MAY 1 3 1982

Certified Mail

Notice of Warning

Bill N. Lewis, Plant Manager National Electric Coil Spokane Service Center 415 N. Fancher Road Spokane, WA 99220

Dear Mr. Lewis:

On March 12, 1982 an EPA inspection was conducted by Michael Watson at the National Electric Coil facility in Spokane, Washington. The inspection was carried out to determine compliance with the PCB Regulations adopted by EPA pursuant to the Toxic Substances Control Act (TSCA).

During the inspection violations of the regulations were noted. You should be aware that violations of TSCA may be subject to administrative civil penalties. The following identifies in detail the violations observed during the inspections:

Records & Monitoring

40 CFR 761.45(a) requires that beginning July 2, 1978 owners or operators of a facility using or storing at one time at least 45 kilograms (99.4 pounds) of PCBs in PCB Containers shall develop and maintain records on the disposition of PCBs and PCB Items. These records shall form the basis of an annual document prepared for each facility by July 1 covering the previous calendar year. The annual document shall include:

- 1) a) The dates when PCBs and PCB Items are:
 - removed from service,
 - ii) placed into storage for disposal,
 - iii) placed into transport for disposal; and
 - b) the quantities of PCBs and PCB Items removed from service, including:
 - total weight in kilograms of PCBs contained in Containers, with the identification of content on the containers,
 - ii) total number of PCB Transformers and total weight in kilograms of PCBs contained in the transformers,
 - iii) total number of PCB Large High or Low Voltage Capacitors;

- the location of the initial disposal or storage facility for PCBs and PCB Items removed from service;
- 2) Total quantities of PCBs and PCB Items remaining in service at the end of the calendar year, including:
 - a) total weight in kilograms of any PCBs and PCB Items in PCB Containers with the identification of content on the container,
 - total number of PCB Transformers and total weight in kilograms of PCBs in the transformers,
 - c) total number of PCB Large High or Low Voltage Capacitors.

There were no records or annual documents concerning the waste oil which contained 134 ppm PCBs. Records and annual documents must be maintained for at least five years after a facility ceases using or storing PCBs (at least 99.4 pounds) and PCB Items. The term PCB is used to refer to any chemical substance or combination of substances that contain 50ppm (on a dry weight basis) or greater of PCBs, including any byproduct, intermediate, or impurity manufactured at any point in a process. The 55 gallon drum of contaminated waste oil was approximately one-third full and contained more than 10 gallons of liquid (over 99.4 pounds).

<u>Marking</u>

I. 40 CFR 761.20(a)(1) requires that after July 1, 1978 PCB Containers, defined as any package, barrel, drum ... or other device that contains PCBs or PCB Articles whose surface has been in direct contact with the PCBs, shall be marked as illustrated in Annex V (761.44(a)).

The barrel with waste oil contaminated at 134 ppm PCB was not marked as required in 761.20(a)(1) and 761.44(a).

II. 40 CFR 761.42(c)(3) requires that the storage area used for temporary storage of PCBs be marked as illustrated in Annex V (761.44(a)). Temporary storage of PCBs between 50-500 ppm in PCB Containers is allowed for up to thirty days from the date removed from service.

If the 30 day temporary storage allowance is exceeded, PCBs and PCB Items must be stored in a facility which meets the requirements of 761.42(a)(1), including:

- adequate roof and walls to prevent rainwater from reaching the stored PCBs;
- adequate floor with continuous curbing a minimum of six inches high, constructed of continuous smooth and impervious materials;
- 3) no valves, drains or other openings that would permit liquids to flow from the curbed area.

Temporary storage of liquid PCBs between 50-500 ppm requires that a Spill Prevention Control and Countermeasure Plan be prepared for the temporary storage area in accordance with 40 CFR 112. PCBs and PCB Containers in storage must be dated on the article or container when they are placed in storage, according to 40 CFR 761.42(c)(8). The container must bear a notation that indicates the liquids in the drum do not exceed 500 ppm PCB.

You should be aware that mineral oil or other liquids containing a PCB concentration of 50 ppm or greater, but less than 500 ppm, must be disposed of: 1) in an incinerator which complies with Annex I (761.40); 2) a chemical waste landfill which complies with Annex II (761.41); 3) in a high efficiency boiler; or 4) in a facility that is approved in accordance with 761.10(e), which has a combustion process that destroys PCBs as efficiently as does a high efficiency boiler.

Within 30 days of your receipt of this letter, please advise us of the corrective action which you will take to bring your facility into compliance with the PCB Regulations. A copy of the May 31, 1979 Federal Register has been enclosed for your information. Inquiries and correspondence should be directed to Donald A. Donaldson, EPA Region 10, Permits and Compliance Branch M/S 524, 1200 Sixth Ave., Seattle, WA 98101; telephone (206) 442-2871.

Sincerely,

Alexandra B. Smith, Director

Air & Waste Management Division

Date

INSPECTION EVALUATION-

ames III Everto

Name & title evaluator

RCRA	TSCA	FIFRA
ACTION TAKEN No Action Indicated Violation Assessment Letter of Non-Compliance Referral for Admin. Civil Penalty Referral for Criminal Action Refer to State		Name of inspector Name of inspector Date of inspection Mathematical Electric Coulty of the Special Relation Establishment Name & Address
COMMENTS: Visibations marking area,	of: 761,45(2)) seemble, 761.20(e)(1) .42(c)(3) marking storage

PCB INSPECTION:

National Electric Coil Div. McGraw-Edison Co. Spokane Service Center 415 N. Fancher Rd. Spokane, WA 99220 (509) 535-8751 Michael Watson 3-12-82

I visited the above company at 2:30 PM on the above date. I was referred by the secretary-receptionist to Mr. Bill N. Lewis, Plant Manager. I presented him with my credentials and we went to his office to chat. I then gave him a Notice of Inspection and explained the basis for my inspection.

Mr. Lewis had been with the plant for only about 6 months, and knew little about past activities prior to his arrival. His secretary was also relatively new, and was not much aware of past practices. The company repairs transformers, also various kinds of electric devices which McGraw-Edison manufactures. Various kinds of electric motors, pumps, regulators, and so forth are evident in the large building housing the service center.

According to Mr. Lewis, company policy for all the McGraw-Edison service centers is to NOT accept any PCB transformers for repair. If a transformer is PCB, they will not work on it or repair it. Then I inquired as to how they know whether or not the transformer is PCB. Mr. Lewis was unable to provide assurance in terms of whether or not lab analysis was required, etc. I then asked about record keeping. Mr. Lewis indicated that they did not keep such records. I reminded him of the general recordkeeping provisions of TSCA for PCB etc., but he was pretty much at a loss in that department, having no records and stating as mentioned previously that the company simply won't work on PCB type equipment.

I then met Mr. Jon Holm, Plant Superintendant, and Mr. Laurence A. Martin, Shop Foreman, and began my inspection of the premises.

According to Mr. Lewis, two transformers were being rebuilt at the moment in the plant. One of these was a large transformer form Boise-Cascade. Potlatch. The other was a smaller regulating type transformer (voltage regulator?) of uncertain lineage and without an i.d. plate, but labelled "R&A COOP 1904." The large transformer had had the oil removed, and it was being stored in 55 gal drums just inside the building. The smaller transformer still had its oil intact, but the top had been removed. As for waste, several 55 gallon drums of waste oil were inside the bldg. They were filled with various waste oils which had come from electric motors, vertical hollow shaft pumps, gear motors, sleeve bearing motors, etc. These were not PCB according to the staff on hand. The bldg was clean and well organized, and resembled a large machine shop, rather than a facility that was very oriented toward oils and oil wastes. Lots of metal-related work was going on. A small amount of oily dirt was evident in the back of the plant, but I did not sample it. Several barrels of waste were also stored outside. I inquired to Mr. Lewis as to their nature and was told they were resins. Apparently they had thus far been unable to dispose of them for various technical reasons. I noted no leaks, and the storage yard seemed neat and in order, etc.

I collected the following samples, took photos, etc.:

Sample #225157, Sub A (EPA LAB NO. 10034): approx. 10 ml clear, yellowish oil from regulating type transformer labelled "R&A COOP 1904." No nameplate was evident.

#225157, Sub B: approx. 10 ml blackish waste oil, which was a composite of used oils taken from various electric motors and pumps (gear motors, vertical hollowshaft pumps and sleeve bearing motors.) The drum contained more than 10 gallons of liquid (about 1/3 full).

#225157, Sub C: approx. 10 ml clear yellowish oil from 750 kva Alyce Chalmers tranformer being rebuilt, from Boise Cascade, Potlatch. The nameplate and oil had been removed, but Mr. Martin produced the plate, I photographed it and noted S.N. 3394967. The oil was taken from 55 gal drum picked out by Mr. Martin, which he indicated contained the drained oil from that particular apparatus. Samples were taken by dipping clean, individual "dixie cup" containers into fluid, and pouring into my EPA glass vials. From what I could tell, no labels for "PCB" were noted anywhere in the plant. I doubt if the facility is an avid labeler. However, I did note that their main business is NOT oil oriented. I gave Mr. Lewis a R/S, 2 copies of N/C (explaining same) and left. I mailed Mr. Jon Holm a copy (certified) of N/C on 3-18-82.

Michael Watson, 3-18-82



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY WASHINGTON, D.C. 20460

10034-10037	3/12/82		
3. REGION	4. EPA REG. NO.		

CAL MODIFICE	REPORT OF ANALYSIS	5. ESTABLISHME	NT NO.
6. DESCRIPTI	ON OF SAMPLE 3 X 16 ml vials of oil and 1 em	pty vial (blank)	
7. NAME AND	ADDRESS OF ESTABLISHMENT WHERE SAMPLE WAS	COLLECTED(Include ZIP code)	8. PRODUCT NAME
٦	National Electric Coil Spokane Service Center, McGraw-Ed 415 N. Fanchez Rd. Spokane, WA 99220	lison	9. LOT OR CODE NUMBER(S)
L	-	٦	
10. NAME AND	DADDRESS OF PRODUCER (If different from 7 above)		

11. RESULTS OF ANALYSIS

Analyzed three oil samples and one empty vial for PCBs including 1221, 1232, 1242, 1248, 1254, 1260 and 1016 by GC/EC with dWal column confirmaton:

#10034 (Sub A) - <1 ppm Aroclor 1254

10035 (Sub B) - 134 ppm Aroclor 1254

10036 (Sub C) - <1 ppm Aroclor 1254

10037 (empty vial) - Not Detected

Analyst: R. H. Rieck, Chemist & W. P. D

12. LABORATORY COMMENTS

13. SIGNATURE OF LAB SUPERVISOR A P Da Do

14. LABORATORY

15. DATE

EPA Region 10

REGIONAL OFFICE COPY





















§ 750.41

- (2) The persons to be cross-examined on each issue;
- (3) The persons to be allowed to conduct cross-examination; and
- (4) Time limits for the examination of each witness by each cross-examiner.
- (c) In issuing this ruling, the panel may determine that one or more participants who have requested cross-examination have the same or similar interests and should be required to choose a single representative for purposes of cross-examination by that single representative without identifying the representative further. Subpoenas for witnesses may be issued where necessary.
- (d) Within one week after the insertion into the record of the ruling under paragraph (b), the hearing at which the cross-examination will be conducted will begin. One or more members of the original panel will preside for EPA. The panel will have authority to conduct cross-examination on behalf of any participant, although as a general rule this right will not be exercised. The panel will also have authority to modify the governing ruling in any respect and to make new rulings on group representation under section 6(c)(3)(C) of TSCA. A verbatim transcript of the hearing will be made.
- (e)(1) No later than the time set for requesting cross-examination, a hearing participant may request that other alternative methods of clarifying the record (such as informal conferences or the submittal of additional information) be used. Such requests may be submitted either in lieu of cross-examination requests, or in conjunction with them.
- (2) The panel in passing on a cross-examination request may, as a precondition to ruling on its merits, require that alternative means of clarifying the record be used whether or not that has been requested under paragraph (e)(1) of this section. In such a case, the results of the use of such alternative means will be made available to the person requesting cross-examination for a one-week comment period, and the panel will make a final ruling on cross-examination within one week thereafter.

Title 40—Protection of Environment

(f) Waivers or extensions of any deadline in this section applicable to persons other than EPA may be granted on the record of the hearing by the person chairing it or in writing by the Hearing Chairman.

§ 750.41 Final rule.

- (a) As soon as feasible after the deadline for submittal of reply comments. EPA will issue a final rule. EPA will also publish at that time:
- (1) A list of all material added to the record (other than public comments and material from the hearing record) which has not previously been listed in a FEDERAL REGISTER document, and
 - (2) The effective date of the rule.
- (b) Pursuant to the delegation of authority made in the Preamble to the Final Regulation for the PCB Manufacturing. Processing. Distribution in Commerce and Use Prohibitions, the Assistant Administrator for Toxic Substances will grant or deny petitions under section 6(e)(3)(B) of TSCA submitted pursuant to § 750.31. The Assistant Administrator will act on such petitions subsequent to opportunity for an informal hearing pursuant to this rule.
- (c) In determining whether to grant an exemption to the PCB ban. EPA will apply the two standards enunciated in section 6(e)(3)(B) of TSCA.

PART 761—POLYCHLORINATED BI-PHENYLS (PCBs) MANUFACTUR-ING, PROCESSING, DISTRIBUTION IN COMMERCE, AND USE PROHIBI-TIONS

Subpart A-General

Sec. 761.1 Applicability. 761.3 Definitions. 761.19 References.

Subpart B—Manufacturing, Processing, Distribution in Commerce, and Use of PCBs and PCB Items

761.20 Prohibitions. 761.30 Authorizations.

Subpart C-Marking of PCBs and PCB Items

761.40 Marking requirements. 761.45 Marking formats. Sec

Subpart D-Storage and Disposal

761.60 Disposal requirements.761.65 Storage for disposal.

761.70 Incineration.

761.75 Chemical waste landfills.

761.79 Decontamination.

Subparts E-I---[Reserved]

Subpart J—Records and Reports

761.180 Records and Monitoring.
761.185 Certification program and retention of special records by persons gener-

ating PCBs in closed manufacturing processes and controlled waste manufacturing processes.

turning processes.

AUTHORITY Secs. 6, 8, and 12, Toxic Substances Control Act, 15 U.S.C. 2605, 2607, and 2611.

Source: 44 FR 31542, May 31, 1979, unless otherwise noted.

Subpart A-General

§ 761.1 Applicability.

(a) This part establishes prohibitions of, and requirements for, the manufacture, processing, distribution in commerce, use, disposal, storage, and marking of PCBs and PCB Items.

(b) This part applies to all persons who manufacture, process, distribute in commerce, use, or dispose of PCBs or PCB Items. Unless it is otherwise specifically provided, the terms PCB and PCBs are used in this rule to refer to any chemical substances and combinations of substances that contain 50 ppm (on a dry weight basis) or greater of PCBs. as defined in § 761.3(s). including any byproduct, intermediate. or impurity manufactured at any point in a process. Any chemical substances and combinations of substances that contain less than 50 ppm PCBs because of any dilution, shall be included as PCB and PCBs unless otherwise specifically provided. Substances that are regulated by this rule include, but are not limited to, dielectric fluids, contaminated solvents, oils, waste oils, heat transfer fluids, hydraulic fluids, paints, sludges, slurries, dredge spoils, soils, materials contaminated as a result of spills, and other chemical substances or combination of substances, including impurities and byproducts.

(c) Definitions of the terms used in these regulations are in Subpart A. The basic requirements applicable to disposal and marking of PCBs and PCB Items are set forth in Subpart D-Disposal of PCBs and PCB Items and in Subpart C-Marking of PCBs and PCB Items. Prohibitions applicable to PCB activities are set forth in Subpart B-Manufacture, Processing, Distribution in Commerce, and Use of PCBs and PCB Items. Subpart B also includes authorizations from the prohibitions. Subparts C and D set forth the specific requirements for disposal and marking of PCBs and PCB Items.

(d) Section 15 of the Toxic Substances Control Act (TSCA) states that failure to comply with these regulations is unlawful. Section 16 imposes liability for civil penalties upon any person who violates these regulations, and the Administrator can establish appropriate remedies for any violations subject to any limitations included in section 16 of TSCA. Section 16 also subjects a person to criminal prosecution for a violation which is knowing or willful. In addition, section 17 authorizes Federal district courts to enjoin activities prohibited by these regulations, compel the taking of actions required by these regulations, and issue orders to seize PCBs and PCB Items manufactured, processed or distributed in violation of these regulations.

(e) These regulations do not preempt other more stringent Federal statutes and regulations.

(f) Persons who manufacture, process, distribute in commerce, or use PCBs generated as byproducts, impurities or intermediates in closed and controlled waste manufacturing processes (as defined in § 761.3 (jj) and (kk)) are exempt from the requirements of Subpart B. To qualify for this exclusion, such processes must also fully comply with § 761.185.

[44 FR 31542, May 31, 1979, as amended at 47 FR 46995, Oct. 21, 1982]

§ 761.3 Definitions.

For the purpose of this part:

(a) "Administrator" means the Administrator of the Environmental Protection Agency, or any employee of

the Agency to whom the Administrator may either herein or by order delegate his authority to carry out his functions, or any person who shall by operation of law be authorized to carry out such functions.

(b) "Agency" means the United States Environmental Protection Agency.

(c) "Byproduct" means a chemical substance produced without separate commercial intent during the manufacturing or processing of another chemical substance(s) or mixture(s).

(d) "Capacitor" means a device for accumulating and holding a charge of electricity and consisting of conducting surfaces separated by a dielectric. Types of capacitors are as follows:

(1) "Small capacitor" means a capacitor which contains less than 1.36 kg (3 lbs.) of dielectric fluid. The following assumptions may be used if the actual weight of the dielectric fluid is unknown. A capacitor whose total volume is less than 1,639 cubic centimeters (100 cubic inches) may be considered to contain less than 1.36 kg (3 lbs.) of dielectric fluid and a capacitor whose total volume is more than 3.278 cubic centimeters (200 cubic inches) must be considered to contain more than 1.36 kg (3 lbs.) of dielectric fluid. A capacitor whose volume is between 1,639 and 3,278 cubic centimeters may be considered to contain less than 1.36 kg (3 lbs.) of dielectric fluid if the total weight of the capacitor is less than 4.08 kg (9 lbs.).

(2) "Large high voltage capacitor" means a capacitor which contains 1.36 kg (3 lbs.) or more of dielectric fluid and which operates at 2000 volts (a.c. or d.c.)

or above.

(3) "Large low voltage capacitor" means a capacitor which contains 1.36 kg (3 lbs.) or more of dielectric fluid and which operates below 2000 volts (a.c. or d.c.).

(e)(1) "Chemical substance", except as provided in paragraph (e)(2) of this section, means any organic or inorganic substance of a particular molecular identity, including:

(i) Any combination of such substances occurring in whole or part as a result of a chemical reaction or occurring in nature, and

- (ii) Any element or uncombined radical.
 - (2) Such term does not include:

(i) Any mixture.

(ii) Any pesticide (as defined in the Federal Insecticide. Fungicide, and Rodenticide Act) when manufactured, processed, or distributed in commerce for use as a pesticide.

(iii) Tobacco or any tobacco product. (iv) Any source material, special nuclear material, or by product material (as such terms are defined in the Atomic Energy Act of 1954 and regula-

tions issued under such Act).

(v) Any article the sale of which is subject to the tax imposed by section 4181 of the Internal Revenue Code of 1954 (determined without regard to any exemptions from such tax provided by section 4182 or section 4221 or any provisions of such Code), and

(vi) Any food, food additive, drug, cosmetic, or device (as such terms are defined in section 201 of the Federal Food, Drug, and Cosmetic Act) when manufactured, processed, or distributed in commerce for use as a food, food additive, drug, cosmetic, or device.

(f) "Chemical waste landfill" means a landfill at which protection against risk of injury to health or the environment from migration of PCBs to land, water, or the atmosphere is provided from PCBs and PCB Items deposited therein by locating, engineering, and operating the landfill as specified in § 761.75.

(g) "Commerce" means trade, traffic, transportation, or other commerce: (1) Between a place in a State and

any place outside of such State, or

(2) Which affects trade, traffic, transportation, or commerce described in paragraph (g)(1) of this section.

- (h) "Disposal" means intentionally or accidentally to discard, throw away, or otherwise complete or terminate the useful life of PCBs and PCB Items. Disposal includes spills, leaks, and other uncontrolled discharges of PCBs as well as actions related to containing, transporting, destroying, degrading, decontaminating, or confining PCBs and PCB Items.
- (i) "Distribute in commerce" and "Distribution in Commerce" when used to describe an action taken with respect to a chemical substance, mix-

ture, or article containing a substance or mixture means to sell, or the sale of, the substance, mixture, or article in commerce; to introduce or deliver for introduction into commerce, or the introduction or delivery for introduction into commerce of the substance, mixture, or article; or to hold or the holding of, the substance, mixture, or article after its introduction into commerce.

(j) "Fluorescent light ballast" means a device that electrically controls fluorescent light fixtures and that includes a capacitor containing 0.1 kg or less of dielectic.

(k) "Impurity" means a chemical substance which is unintentionally present with another chemical substance.

(1) "Incinerator" means an engineered device using controlled flame combustion to thermally degrade PCBs and PCB Items. Examples of devices used for incineration include rotary kilns. liquid injection incinerators. cement kilns, and high temperature boilers.

(m) "Leak" or "leaking" means any instance in which a PCB Article. PCB Container, or PCB Equipment has any PCBs on any portion of its external

(n) "Manufacture" means to produce, manufacture, or import into the customs territory of the United States.

(o) "Mark" means the descriptive name, instructions, cautions, or other information applied to PCBs and PCB Items, or other objects subject to these regulations.

(p) "Marked" means the marking of PCB Items and PCB storage areas and transport vehicles by means of applying a legible mark by painting, fixation of an adhesive label, or by any other method that meets the requirements of these regulations.

(q) "Mixture" means any combination of two or more chemical substances if the combination does not occur in nature and is not, in whole or in part, the result of a chemical reaction: except that such term does in clude any combination which occurs, in whole or in part, as a result of a chemical reaction if none of the chemical substances comprising the combination is a new chemical sub-

stance and if the combination could have been manufactured for commercial purposes without a chemical reaction at the time the chemical substances comprising the combination were combined.

(r) "Municipal solid wastes" means garbage, refuse, sludges, wastes, and other discarded materials resulting from residential and non-industrial operations and activities, such as household activities, office functions, and commercial housekeeping wastes.

(s) "PCB" and "PCBs" means any chemical substance that is limited to the biphenyl molecule that has been chlorinated to varying degrees or any combination of substances which contains such substance. (See § 761.1(b) Applicability for applicable concentrations of PCBs). PCB and PCBs as contained in PCB Items are defined in § 761.3(x).

(t) "PCB Article" means any manufactured article, other than a PCB Container, that contains PCBs and whose surface(s) has been in direct contact with PCBs. "PCB Article" includes capacitors, transformers, electric motors, pumps, pipes and any other manufactured item (1) which is formed to a specific shape or design during manufacture. (2) which has end use function(s) dependent in whole or in part upon its shape or design during end use, and (3) which has either no change of chemical composition during its end use or only those changes of composition which have no commerical purpose separate from that of the PCB Article.

(u) "PCB Article Container" means any package, can, bottle, bag, barrel, drum, tank or other device used to contain PCB Articles or PCB Equipment, and whose surface(s) has not been in direct contact with PCBs.

(v) "PCB Container" means any package, can, bottle, bag, barrel, drum, tank, or other device that contains PCBs or PCB Articles and whose surface(s) has been in direct contact with PCBs.

(w) "PCB Equipment" means any manufactured item, other than a PCB Container or a PCB Article Container, which contains a PCB Article or other PCB Equipment, and includes microwave ovens, electronic equipment, and fluorescent light ballasts and fixtures.

(x) "PCB Item" is defined as any PCB Article. PCB Article Container. PCB Container, or PCB Equipment. that deliberately or unintentionally contains or has as a part of it any PCB or PCBs at a concentration of 50 ppm or greater.

(y) "PCB Transformer" means any transformer that contains 500 ppm PCB or greater.

(z) "PCB-Contaminated Electrical Equipment" means any electrical equipment, including but not limited to transformers (including those used in railway locomotives and self-propelled cars), capacitors, circuit breakers, reclosers, voltage regulators. switches (including sectionalizers and motor starters), electromagnets, and cable, that contain 50 ppm or greater PCB, but less than 500 ppm PCB. Oilfilled electrical equipment other than circuit breakers, reclosers, and cable whose PCB concentration is unknown must be assumed to be PCB-Contaminated Electrical Equipment. (See § 761.30(a) and (h) for provisions permitting reclassification of electrical equipment containing 500 ppm or greater PCBs to PCB-Contaminated Electrical Equipment).

(aa) "Person" means any natural or judicial person including any individual, corporation, partnership, or association; any State or political subdivision thereof; any interstate body; and any department, agency, or instrumentality of the Federal Government.

(bb) "Process" means the preparation of a chemical substance or mixture, after its manufacture, for distribution in commerce:

(1) In the same form or physical state as, or in a different form or physical state from, that in which it was received by the person so preparing such substance or mixture, or

(2) As part of an article containing the chemical substance or mixture.

(cc) "Sale for purposes other than resale" means sale of PCBs for purposes of disposal and for purposes of use, except where use involves sale for distribution in commerce. PCB Equipment which is first leased for purposes of use any time before July 1, 1979,

will be considered sold for purposes other than resale.

.(dd) "Significant exposure" means any exposure of human beings or the environment to PCBs as measured or detected by any scientifically acceptable analytical method.

(ee) "Small quantities for research and development" means any quantity of PCBs (1) that is originally packaged in one or more hermetically sealed containers of a volume of no more than five (5.0) milliliters, and (2) that is used only for purposes of scientific experimentation or analysis, or chemical research on, or analysis of, PCBs, but not for research or analysis for the development of a PCB product.

(ff) "Storage for disposal" means temporary storage of PCBs that have been designated for disposal.

(gg) "Transport vehicle" means a motor vehicle or rail car used for the transportation of cargo by any mode. Each cargo-carrying body (e.g., trailer, railroad freight car) is a separate transport vehicle.

(hh) "Totally enclosed manner" means any manner that will ensure that any exposure of human beings or the environment to any concentration of PCBs will be insignificant: that is, not measurable or detectable by any scientifically acceptable analytical method.

(ii) "Waste oil" means used products primarily derived from petroleum, which include, but are not limited to, fuel oils, motor oils, gear oils, cutting oils, transmission fluids, hydraulic fluids, and dielectric fluids.

(jj) "Closed manufacturing process" means a manufacturing process in which PCBs are generated but from which less than 10 micrograms per cubic meter from any resolvable gas chromatographic peak are contained in any release to air: less than 100 micrograms per liter from any resolvable gas chromatographic peak are contained in any release to water: and less than 2 micrograms per gram from any resolvable gas chromatographic peak are contained in any product. or any process waste.

(kk) "Controlled waste manufacturing process" means a manufacturing process in which PCBs are generated but from which less than 10 micro-

grams per cubic meter from any resolvable gas chromatographic peak are contained in any release to air; less than 100 micrograms per liter from any resolvable gas chromatographic peak are contained in any release to water: less than 2 micrograms per gram from any resolvable gas chromatographic peak are contained in any product, and the remainder of PCBs generated are incinerated in a qualified incinerator, landfilled in a landfill approved under the provisions of § 761.75. or stored for such incineration or landfilling in accordance with the requirements of § 761.65(b)(1).

(ll) "Posing an exposure risk to food or feed" means being in any location where human food or animal feed products could be exposed to PCBs released from a PCB Item. A PCB Item poses an exposure risk to food or feed if PCBs released in any way from the PCB Item have a potential pathway to human food or animal feed. EPA considers human food or animal feed to include items regulated by the U.S. Department of Agriculture or the Food and Drug Administration as human food or animal feed: this includes direct additives. Food or feed is excluded from this definition if it is used or stored in private homes.

process" "Manufacturing (mm) means all of a series of unit operations operating at a site, resulting in the production of a product.

(nn) "Qualified incinerator" means one of the following:

(1) An incinerator approved under the provisions of § 761.70. Any concentration of PCBs can be destroyed in an incinerator approved under § 761.70.

(2) A high efficiency boiler approved under the provisions of § 761.60(a)(3). Only PCBs in concentrations below 500 ppm can be destroyed in a high-efcoiler approved ficiency

§ 761.60(a)(3). (3) An incinerator approved under section 3005(c) of the Resource Conservation and Recovery Act (42 U.S.C. 6925(c)) (RCRA). Only PCBs in concentrations below 50 ppm can be destroyed in a RCRA-approved incinerator. The manufacturer seeking to qualify a process as a controlled waste process by disposing of wastes in a incinerator .must RCRA-approved

make a determination that the incinerator is capable of destroying less readily burned compounds than the PCB homologs to be destroyed. The manufacturer may use the same guidance used by EPA in making such a determination when issuing an approval under section 3005(c) of RCRA. The manufacturer is also responsible for obtaining a reasonable assurance that the incinerator, when burning PCB wastes, will be operated under conditions which have been shown to enable the incinerator to destroy the less readily burned compounds.

[44 FR 31542, May 31, 1979. Redesignated at 47 FR 19527. May 6, 1982, and amended at 47 FR 37356. Aug. 25, 1982; 47 FR 46995. Oct. 21, 1982; 47 FR 54437, Dec. 3, 1982; 48 FR 4467, Feb. 1, 1983]

§ 761.19 References.

(a) [Reserved]

(b) Incorporations by reference. The following material is incorporated by reference, and is available for inspection at the Office of the Federal Register Information Center. Rm. 8301. 1100 L St. NW., Washington, DC 20408. These incorporations by reference were approved by the Director of the Office of the Federal Register. These materials are incorporated as they exist on the date of approval and a notice of any change in these materials will be published in the FEDERAL REGISTER. Copies of the incorporated material may be obtained from the Environmental Protection Agency Document Control Officer (TS-793). Office of Pesticides and Toxic Substances. EPA. Rm. 106, 401 M St., SW., Washington, D.C. 20460, and from the American Society for Testing and Materials (ASTM), 1916 Race Street, Philadelphia, PA 1910

CFR Citation

ASTM D93-77 Standard Test § 761.60(a)(3)(iii)(B)(6), Method for Flash Point by Pensky-Martens

ASTM D129-64 (Reapproved Standard 1978) Method for Sultur in Petroleum Products (General Bomb Method)

§ 761,60(a)(3)(m)(B)(6)

Subpart B—Manufacturing, Processing, Distribution in Commerce, and Use of PCBs and PCB Items

§ 761.20 Prohibitions.

Except as authorized in § 761.30 the activities listed in paragraphs (a) and (d) of this section are prohibited pursuant to section 6(e)(2) of TSCA. The requirements set forth in paragraphs (b) and (c) of this section concerning export and import of PCBs for purposes of disposal and PCB Items for purposes of disposal are established pursuant to section 6(e)(1) of TSCA. Subject to any exemptions granted pursuant to section 6(e)(3)(B) of TSCA, the activities listed in paragraphs (b) and (c) of this section are prohibited pursuant to section 6(e)(3)(A) of TSCA. In addition, the Administrator hereby finds, under the authority of section 12(a)(2) of TSCA, that the manufacture, processing, and distribution in commerce of PCBs and PCB Items for export from the United States presents an unreasonable risk of injury to health within the United States. This finding is based upon the well-documented human health and environmental hazard of PCB exposure: the high probability of human and environmental exposure to PCBs and PCB Items from manufacturing. processing, or distribution activities; the potential hazard of PCB exposure posed by the transportation of PCBs or PCB Items within the United States: and the evidence that contamination of the environment by PCBs is spread far beyond the areas where they are used. In addition, the Administrator hereby finds that any exposure of human beings or the environment to PCBs as measured or detected by any scientifically acceptable analytical method is a significant exposure. as defined in § 761.3(dd). Section 761.3(hh) and TSCA section 6(e)(2)(C) define the term totally enclosed manner as "any manner which will ensure that any exposure of human beings or the environment to a polychlorinated biphenyl will be insignifi-cant ... Since any exposure to PCBs is found to be a significant exposure, a totally enclosed manner is a manner that results in no exposure of

	CFR Citation
ASTM D240-76 (Reapproved	
1980) Standard Test	•
Method for Heat of Com- bustion of Liquid Hydrocar-	
bon Fuel by Bomb Calon-	
meter	1
ASTM D482-74 Standard	\$ 761.60(a)(3)(iii)(B)(6).
Test Method for Ash from	1
Petrolum Products	İ
	. § 761.60(a)(3)(m)(B)(6)
Test Method for Ramsbot- tom Carbon Residue of Pe-	į.
troleum Products	
	§ 761,60(a)(3)(m)(B)(6)
Test Method for Chlorine in	
New and Used Petroleum	7
Products (Bomb Method).	
ASTM D-923-81 Standard	
Test Method for Sampling	§ 761.60(g)(2)(ii)
Electrical Insulating Liquids, ASTM D1266-70 (Reap-	§ 761.60(a)(3)(m)(B)(6)
proved 1975) Standard	
Test Method for Sulfur in	
Petrolum Products (Lamp	50
Method).	
	\$ 761.60(a)(3)(m)(B)(6)
proved 1977) Standard	
Test Methods for Water	
and Sediment in Crude Oils and Fuel Oils by Centrifuge	
ASTM D2158-65 (Reap-	\$ 761 60(a)(3)(m)(B)(6)
proved 1975) Standard	3 . 0 . 00101/01/01/01/01
Test Method for Residues	
in Liquefied Petroleum (LP)	
Gas	
ASTM D2709-68 (Reap-	§ 761,60(a)(3)(a)(9)(6)
proved 1977) Stangard Test Method for Water and	
Segment in Distillate Fuel	
by Centrifuge	
ASTM D2784-70 (Reap-	\$ 761 60(a)(3)(m)(B)(6)
proved 1975) Slandard	
Test Method for Sulfur in	
Liquefied Petroleum Gases	
(Oxyhydrogen Burner or Lamp)	
ASTM D3178-73 (Reap-	§ 761.60(a)(3)(m)(B)(6)
proved 1979) Slandard	3 . o . colettatimi(Bito)
Test Methods for Carbon	
and Hydrogen in the Analy-	
sis Sample of Coke and	
Coal	
ASTM D3278-73 Standard	§ 761 75(b)(8)(m)
Test Methods for Flash	
Point of Liquid by Setallash Closed Taster	
ASTM E258-67 (Reapproved	្ទ 761 60(a)(3)(m)(B)(ស
1977) Standard Test	3 saladahudakhi
Method for Total Nitrogen	
Inorganic Material by Modi-	
fied KJELDAHL Method:	

CFR Citation

humans or the environment to PCBs. The following activities are considered totally enclosed: distribution in commerce of intact, nonleaking electrical equipment such as transformers (including transformers used in railway locomotives and self-propelled cars), capacitors, electromagnets, voltage regulators, switches (including sectionalizers and motor starters), circuit breakers, reclosers, and cable that contain PCBs at any concentration and processing and distribution in commerce of PCB Equipment containing an intact, nonleaking PCB Capacitor. See paragraph (c) (1) of this section for provisions allowing the distribution in commerce of PCBs and PCB

wal No person may process, distribute in commerce, or use any PCB or PCB Item in any manner other than in a totally enclosed manner within the United States or export any such PCB or PCB Item from the United States unless authorized under § 701.30 of this subpart. Paragraph (a) of this section is superseded by paragraph (c) for processing and distribution in commerce of PCBs and PCB Items on the dates when that section becomes effective.

(b) No person may manufacture PCBs for use within the United States or manufacture PCBs for export from the United States without an exemption except that:

(1) PCBs or PCB Items may be imported for purposes of disposal until May 1, 1980, provided that the disposal is in accordance with § 761.60:and

(2) PCBs or PCB Items may be exported for disposal until May 1, 1980, in accordance with the requirements of paragraph (c)(3) of this section.

(c) Effective July 1, 1979, no person may process or distribute in commerce any PCB or PCB Item for use within the United States or for export from the United States without an exemption except that:

(1) PCBs or PCB Items sold before July 1, 1979, for purposes other than resale may be distributed in commerce only in a totally enclosed manner after that date:

(2) PCBs or PCB Items may be processed and distributed in commerce in compliance with the requirements of

this part for purposes of disposal in accordance with the requirements of

(3) PCBs or PCB Items may be exported for disposal until May 1, 1980, if an export notice is submitted at least thirty (30) days before the first shipment in any calendar year leaves the customs territory of the United States. Export notices must be submitted to the Document Control Officer (TS-793). Office of Toxic Substances. Environmental Protection Agency, 401 M Street, S.W., Washington, D.C. 20460. The generator of the PCB waste material intended for disposal, or an agent acting on his behalf. must certify to the best of his knowledge and belief that the information is complete and accurate. Each notice should contain the following information:

(i) Name, company name, address, and telephone number of the owner of the PCB waste material to be exported and the name and address of any person or agent acting on his behalf;

(ii) Estimated quantity of wastes to be shipped during the calendar year and the estimated number of shipments to be made and the dates when such shipments are expected to leave the customs territory of the United States:

 (iii) Description of the PCBs or PCB Items being exported;

(iv) Country(s) of destination for the shipments:

(v) Name and address of facility(s) receiving the shipment and person(s) responsible for receiving the shipment(s).

(vi) Method(s) of disposal and precautions taken to control release into the environment.

(vii) No less than 30 days after the end of each calendar quarter (March 31. June 30. September 30. and December 31) during which PCBs were exported for disposal, each person exporting the PCBs must submit a report to the Document Control Officer (TS-793), Office of Toxic Substances, U.S. Environmental Protection Agency, 401 M Street, S.W., Washington, D.C. 20460. The report shall list the quantity of PCB wastes in each shipment made during the quarter and include the date when

each shipment left the customs territory of the United States and the information specified in paragraphs (c)(3)(i) and (iii) through (vi) of this section. If the quantity of wastes shipped during the calendar year exceeds by 25 percent or more the estimated quantities reported in paragraph (c)(3)(ii) of this section, a special export notice must be submitted to the Document Control Officer (TS-793) at the address given in paragraph (c)(3) at least 30 days before any additional shipments leave the customs territory of the United States and the notice shall include the information specified in paragraphs (c)(3) (i) through (vi) of this section.

(viii) Any person expecting to export PCB wastes for disposal in calendar year 1980 must submit an export notice at least thirty (30) days before the first shipment leaves the customs territory of the United States to the Document Control Officer (TS-793) at the address given in paragraph (c)(3) of this section, and the notice shall contain the information listed in paragraphs (c)(3) (i) through (vi) of this section.

(d) The use of waste oil that contains any detectable concentration of PCB as a sealant, coating, or dust control agent is prohibited. Prohibited uses include, but are not limited to, road oiling, general dust control, use as a pesticide or herbicide carrier, and use as a rust preventative on pipes.

[44 FR 31542, May 31, 1979, Redesignated at 47 FR 19527, May 6, 1982, and amended at 47 FR 37356, Aug. 25, 1982]

§ 761.30 Authorizations.

The following non-totally enclosed PCB activities are authorized pursuant to section 6(e)(2)(B) of TSCA:

(a) Use in and servicing of transformers (other than railroad transformers). PCBs at any concentration may be used in transformers (other than transformers for railroad locomotives and self-propelled railroad cars) and may be used for purposes of servicing including rebuilding these transformers for the remainder of their useful lives, subject to the following conditions:

(1) Use conditions. (i) After October 1, 1985, the use and storage for reuse

of PCB Transformers that pose an exposure risk to food or feed is prohibited.

(ii) A visual inspection of each PCB Transformer (as defined in § 761.3(y)) in use or stored for reuse shall be performed at least once every three months. These inspections may take place any time during the three month periods: January-March, April-June. July-September. and October-December as long as there is a minimum of 30 days between inspections. The visual inspection must include investigation for any leak of dielectric fluid on or around the transformer. The extent of the visual inspections will depend on the physical constraints of each transformer installation and should not require an electrical shutdown of the transformer being inspected.

(iii) If a PCB Transformer is found to have a leak which results in any quantity of PCBs running off or about to run off the external surface of the transformer, then the transformer must be repaired or replaced to eliminate the source of the leak. In all cases any leaking material must be cleaned up and properly disposed of according to disposal requirements of § 761.60. Cleanup of the released PCBs must be initiated as soon as possible. but in no case later than 48 hours of its discovery. Until appropriate action is completed, any active leak of PCBs must be contained to prevent exposure of humans or the environment and inspected daily to verify containment of the leak. Trenches, dikes, buckets, and pans are examples of proper containment measures.

(iv) Records of inspection and maintenance history shall be maintained at least 3 years after disposing of the transformer and shall be made available for inspection, upon request, by EPA (OMB Control Number: 2070-0003). Such records shall contain the following information for each PCB Transformer:

(A) Its location.

(B) The date of each visual inspection and the date that a leak was discovered, if different from the inspection date.

(C) The person performing the inspection.

(D) The location of any leak(s).

(E) An estimate of the amount of dielectric fluid released from any leak.

(F) The date of any cleanup, containment, repair, or replacement.

(G) A description of any cleanup, containment, or repair performed.

(H) The results of any containment and daily inspection required for uncorrected active leaks.

(v) A reduced visual inspection frequency of at least once every 12 months applies to PCB Transformers that utilize either of the following risk reduction measures. These inspections may take place any time during the calendar year as long as there is a minimum of 180 days between inspec-

(A) a PCB Transformer which has impervious, undrained, secondary containment capacity of at least 100 percent of the total dielectric fluid volume of all transformers so contained, or

(B) A PCB Transformer which has been tested and found to contain less than 60.000 ppm PCBs (after three months of inservice use if the transformer has been serviced for purposes of reducing the PCB concentration).

(vi) An increased visual inspection frequency of at least once every week applies to any PCB Transformer in use or stored for reuse which poses an exposure risk to food or feed. The user of a PCB Transformer posing an exposure risk to food or feed is responsible for the inspection, recordkeeping, and maintenance requirements under this section until the user notifies the owner that the transformer may pose an exposure risk to food or feed. Following such notification, it is the owner's ultimate responsibility to determine whether the PCB Transformer poses an exposure risk to food or feed.

(2) Servicing conditions. (i) Transformers classified as PCB-Contaminated Electrical Equipment (as defined in § 761.3(z)) may be serviced (including rebuilding) only with dielectric fluid containing less than 500 ppm PCB.

(ii) Any servicing (including rebuilding) of PCB Transformers (as defined in § 761.3(y)) that requires the removal of the transformer coil from the transformer casing is prohibited. PCB

Transformers may be serviced (including topping off) with dielectric fluid at any PCB concentration.

(iii) PCBs removed during any servicing activity must be captured and either reused as dielectric fluid or disposed of in accordance with the requirements of § 761.60. PCBs from PCB Transformers must not be mixed with or added to dielectric fluid from PCB-Contaminated Electrical Equipment.

(iv) Regardless of its PCB concentration, dielectric fluids containing less than 500 ppm PCB that are mixed with fluids that contain 500 ppm or greater PCB must not be used as dielectric fluid in any electrical equipment. The entire mixture of dielectric fluid must be considered to be greater than 500 ppm PCB and must be disposed of in an incinerator that meets the requirements in § 761.70.

(v) A PCB Transformer may be converted to PCB-Contaminated Electrical Equipment or to a non-PCB Transformer and a transformer that is classified as PCB-Contaminated Electrical Equipment may be reclassified to a non-PCB Transformer by draining, refilling and/or otherwise servicing the transformer. In order to reclassify, the transformer's dielectric fluid must contain less than 500 ppm PCB (for conversion to PCB-Contaminated Electrical Equipment) or less than 50 ppm PCB (for conversion to a non-PCB Transfomer) after a minimum of three months of in-service use subsequent to the last servicing conducted for the purpose of reducing the PCB concentration in the transformer. In-service means that the transformer is used electrically under loaded conditions that raise the temperature of the dielectric fluid to at least 50° Centigrade. The Assistant Administrator may grant, without further rulemaking, approval for the use of alternative methods that simulate the loaded conditions of in-service use. All PCBs removed from transformers for purposes of reducing PCB concentrations are subject to the disposal requirements of

(vi) Any dielectric fluid containing 50 ppm or greater PCB used for servicing transformers must be stored in accordance with the storage for disposal requirements of § 761.65.

(vii) Processing and distribution in commerce of PCBsfor purposes of servicing transformers is permitted only for persons who are granted an exemption under TSCA 6(e)(3)(B).

(b) Use in and servicing of railroad transformers. PCBs may be used in transformers in railroad locomotives or railroad self-propelled cars ("railroad transformers") and may be processed and distributed in commerce for purposes of servicing these transformers in a manner other than a totally enclosed manner subject to the following conditions:

(1) Use restrictions. (i) After July 1. 1983, the number of railroad transformers containing a PCB concentration greater than 60.000 ppm (6.0 percent on a dry weight basis) in use by any affected railroad organization may not exceed two-thirds of the total railroad transformers containing PCBs in use by that organization on January 1. 1982.

(ii) After January 1, 1984, the number of railroad transformers containing a PCB concentration greater than 60,000 ppm in use by any affected railroad organization may not exceed one-third of the total railroad transformers containing PCBs in use by that organization on January 1, 1982.

(iii) After July 1, 1984, use of railroad transformers that contain dielectric fluids with a PCB concentration greater than 60,000 ppm is prohibited.

(iv) After July 1. 1985, the number of railroad transformers containing a PCB concentration greater than 1.000 ppm (0.1 percent on a dry weight basis) in use by any affected railroad organization may not exceed two-thirds of the total railroad transformers containing PCBs in use by that organization on July 1. 1984.

(v) After January 1, 1986, the number of railroad transformers containing a PCB concentration greater than 1,000 ppm in use by any affected railroad organization may not exceed one-third of the total railroad transformers containing PCBs in use by that organization on July 1, 1984.

(vi) After July 1, 1986, use of railroad transformers that contain dielec-

tric fluids with a PCB concentration greater than 1.000 ppm is prohibited.

(vii) The concentration of PCBs in the dielectric fluid contained in railroad transformers must be measured:

(A) Immediately upon completion of any authorized servicing of a railroad transformer conducted for the purpose of reducing the PCB concentration in the dielectric fluid in the transformer, and

(B) Between 12 and 24 months after each servicing conducted in accordance with paragraph (b)(1)(vii)(A) of this section:

(C) The data obtained as a result of paragraphs (b)(1)(vii) (A) and (B) of this section shall be retained until January 1, 1991.

(2) Servicing restrictions. (i) If the coil is removed from the casing of a railroad transformer (e.g., the transformer is rebuilt), after January 1, 1982, the railroad transformer may not be refilled with dielectric fluid containing a PCB concentration greater than 50 ppm;

(ii) After January 1. 1982. railroad transformers may only be serviced with dielectric fluid containing less than 60.000 ppm PCBs. except as provided in paragraph (b)(2)(i) of this section.

(iii) After January 1, 1984, railroad transformers may only be serviced with dielectric fluid containing less than 1000 ppm PCB, except as provided in paragraph (b)(2)(i) of this section:

(iv) Dielectric fluid may be filtered through activated carbon or otherwise industrially processed for the purpose of reducing the PCB concentration in the fluid:

(v) Any PCB dielectric fluid that is used to service PCB railroad transformers must be stored in accordance with the storage for disposal requirements of § 761.65:

(vi) After July 1, 1979, processing and distribution in commerce of PCBs for purposes of servicing railroad transformers is permitted only for persons who are granted an exemption under TSCA section 6(e)(3)(B).

(vii) A PCB Transformer may be converted to a PCB-Contaminated Transformer or to a non-PCB Transformer by draining, refilling, and/or

otherwise servicing the railroad transformer. In order to reclassify, the railroad transformer's dielectric fluid must contain less than 500 ppm (for conversion to PCB-Contaminated Transformer) or less than 50 ppm PCB (for conversion to a non-PCB Transformer) after a minimum of three months of inservice use subsequent to the last servicing conducted for the purpose of reducing the PCB concentration in the transformer.

(c) Use in and servicing of mining equipment. PCBs may be used in mining equipment and may be processed and distributed in commerce for purposes of servicing mining equipment in a manner other than a totally enclosed manner until January 1, 1982, subject to the following condi-

tions:

(1) PCBs may be added to motors in mining equipment in mines or mining

areas until January 1, 1982;

(2) PCB motors in loader-type mining equipment must be rebuilt as air-cooled or other non-PCB-containing motors whenever the motor is returned to a service shop for servicing:

(3) PCB motors in continuous minertype equipment may be rebuilt as PCB

motors until January 1, 1980;

(4) Any PCBs that are on hand to service or repair mining equipment must be stored in accordance with the storage for disposal requirements of

§ 761.65:
(5) After July 1, 1979, processing and distribution in commerce of PCBs for purposes of servicing mining equipment is permitted only for persons who are granted an exemption under

TSCA section 6(e)(3)(B).

(d) Use in heat transfer systems. PCBs may be used in heat transfer systems in a manner other than a totally enclosed manner until July 1, 1984, subject to the following conditions:

(1) Each person who owns a heat transfer system that ever contained PCBs must test for the concentration of PCBs in the heat transfer fluid of such a system no later than November 1, 1979, and at least annually thereafter. All test sampling must be performed at least three months after the most recent fluid refilling. When a test shows that the PCB concentration

is less than 50 ppm, testing under this paragraph is no longer required;

(2) Within six (6) months of a test performed under paragraph (d)(1) that indicates that a system's fluid contains 50 ppm or greater PCB (0.005% on a dry weight basis), the system must be drained of the PCBs and refilled with fluid containing less than 50 ppm PCB. Topping-off with non-PCB heat transfer fluids to reduce PCB concentrations is permitted:

(3) After November 1, 1979, no heat transfer system that is used in the manufacture or processing of any food, drug, cosmetic, or device, as defined in section 201 of the Federal Food, Drug, and Cosmetic Act, may contain heat transfer fluid with 50 ppm or greater PCB (0.005% on a dry

weight basis);

(4) Addition of PCBs to a heat trans-

fer system is prohibited.

(5) Data obtained as a result of paragraph (d)(1) must be retained for five(5) years after the heat transfer

system reaches 50 ppm PCB:

(e) Use in hydraulic systems. PCBs may be used in hydraulic systems and may be processed and distributed in commerce for purposes of filtering, distilling, or otherwise reducing the concentration of PCBs in hydraulic fluids in a manner other than a totally enclosed manner until July 1, 1984, subject to the following conditions:

(1) Each person who owns a hydraulic system that ever contained PCBs must test for the concentration of PCBs in the hydraulic fluid of each such system no later than November 1, 1979, and at least annually thereafter. All test sampling must be performed at least three months after the most recent fluid refilling. When a test shows that the PCB concentration is less than 50 ppm, testing under this subparagraph is no longer required:

(2) Within six (6) months of a test under paragraph (e)(1) that indicates that a system's fluid contains 50 ppm or greater PCB (0.005% on a dry weight basis), the system must be drained of the PCBs and refilled with fluid containing less than 50 ppm PCB. Topping-off with non-PCB hydraulic fluids to reduce PCB concen-

trations is permitted;

(3) Addition of PCBs to a hydraulic system is prohibited:

(4) Hydraulic fluid may be drained from a hydraulic system and filtered. distilled, or otherwise serviced in order to reduce the PCB concentration below 50 ppm:

(5) After July 1, 1979, processing and distribution in commerce of PCBs for purposes of servicing hydraulic systems is permitted only for persons who are granted an exemption under TSCA section 6(e)(3)(B);

(6) Data obtained as a result of paragraph (e)(1) above must be retained for five years after the hydraulic system reaches 50 ppm.

(f) Use in carbonless copy paper. Carbonless copy paper containing PCBs may be used in a manner other than a totally enclosed manner indefinitely.

(g) Pigments. Diarylide and Phthalocyanin pigments that contain 50 ppm or greater PCB may be processed, distributed in commerce, and used in a manner other than a totally enclosed manner until January 1, 1982, except that after July 1, 1979, processing and distribution in commerce of diarylide or phthalocyanin pigments that contain 50 ppm or greater PCB is permitted only for persons who are granted an exemption under TSCA section 6(e)(3)(B).

(h) Use in and servicing of electromagnets, switches and voltage regulators. PCBs at any concentration may be used in electromagnets, switches (including sectionalizers and motor starters), and voltage regulators and may be used for purposes of servicing this equipment (including rebuilding) for the remainder of their useful lives, subject to the following conditions:

(1) Use conditions. (i) After October 1, 1985, the use and storage for reuse of any electromagnet which poses an exposure risk to food or feed is prohibited if the electromagnet contains greater tha 500 ppm PCBs.

(ii) A visual inspection of each electromagnet subject to paragraph (h)(1)(i) shall be performed at least once every week according to the conditions contained in § 761.30(a)(1)(iii) and (iv).

(2) Servicing conditions. (i) Servicing (including rebuilding) any electro-

magnet, switch, or voltage regulator with a PCB concentration of 500 ppm or greater which requires the removal and rework of the internal components is prohibited.

(ii) Electromagnets, switches, and voltage regulators classified as PCB-Contaminated Electrical Equipment (as defined in § 761.3(z)) may be serviced (including rebuilding) only with dielectric fluid containing less than 500 ppm PCB.

(iii) PCBs removed during any servicing activity must be captured and either reused as dielectric fluid or disposed of in accordance with the requirements of § 761.60. PCBs from electromagnets switches, and voltage regulators with a PCB concentration of at least 500 ppm must not be mixed with or added to dielectric fluid from PCB-Contaminated Electrical Equipment.

(iv) Regardless of its PCB (concentration, dielectric fluids containing less than 500 ppm PCB) that are mixed with fluids that contain 500 ppm or greater PCB must not be used as dielectric fluid in any electrical equipment. The entire mixture of dielectric fluid must be considered to be greater than 500 ppm PCB and must be disposed of in an incinerator that meets the requirements of \$ 761.70.

(v) An electromagnet, switch or voltage regulator with a PCB concentration of at least 500 ppm may be converted to PCB-Contaminated Electrical Equipment or to a non-PCB classification and PCB-Contaminated Electrical Equipment may be reclassified to a non-PCB classification by draining, refilling and/or otherwise servicing the equipment. In order to be reclassified, the equipment's dielectric fluid must contain less than 500 ppm PCB (for conversion to PCB-Contaminated Electrical Equipment) or less than 50 ppm PCB (for conversion to a non-PCB classification) after a minimum of three months of in-service use subsequent to the last servicing conducted for the purpose of reducing the PCB concentration in the equipment. In-service use means the equipment is used electrically under loaded conditions. The Assistant Administrator may grant, without further rulemaking, approval for the use of alternative methods that simulate the loaded conditions of in service use. All PCBs removed from this equipment for purposes of reducing PCB concentrations are subject to the disposal requirements of § 761.60.

(vi) Any dielectric fluid containing 50 ppm or greater PCB used for servicing electromagnets, switches, or voltage regulators must be stored in accordance with the storage for disposal

requirements of § 761.65.

(vii) Processing and distribution in commerce of PCBs for purposes of servicing electromagnets, switches or voltage regulators is permitted only for persons who are granted an exemption under TSCA 6(e)(3)(B).

(i) Use in natural gas pipeline compressors. PCBs may be used in natural gas pipeline compressors until May 1, 1980, in a manner other than a totally

enclosed manner.

- (j) Small quantities for research and development. PCBs may be processed. distributed in commerce, and used in small quantities for research and development, as defined in § 761.3(ee), in a manner other than a totally enclosed manner until July 1, 1984, except that after July 1, 1979, processing and distribution in commerce of PCBs in small quantities for research and development is permitted only for persons who have been granted an ex-TSCA section under emption 6(e)(3)(B).
- (k) Microscopy mounting medium. PCBs may be processed, distributed in commerce, and used as a mounting medium in microscopy in a manner other than a totally enclosed manner until July 1, 1984, except that after July 1, 1979, processing and distribution in commerce of PCBs for purposes of use as a mounting medium in microscopy are permitted only for persons who are granted an exemption under TSCA section 6(e)(3)(B).

(1) Use in capacitors. PCBs at any concentration may be used in capacitors. subject to the following conditions:

(1) Use conditions. (i) After October 1. 1988. the use and storage for reuse of PCB Large High Voltage Capacitors and PCB Large Low Voltage Capacitors which pose an exposure risk to food or feed is prohibited.

- (ii) After October 1, 1988, the use of PCB Large High Voltage Capacitors and PCB Large Low Voltage Capacitors is prohibited unless the capacitor is used within a restricted-access electrical substation or in a contained and restricted-access indoor installation. A restricted-access electrical substation is an outdoor, fenced or walled-in facility that restricts public access and is used in the transmission or distribution of electric power. A contained and restricted-access indoor installation does not have public access and has an adequate roof, walls, and floor to contain any release of PCBs within the indoor location.
 - (m) Use in and servicing of circuit breakers, reclosers and cable. PCBs at any concentration may be used in circuit breakers, reclosers, and cable and may be used for purposes of servicing this electrical equipment (including rebuilding) for the remainder of their useful lives, subject to the following conditions:
 - (1) Servicing conditions. (i) Circuit breakers, reclosers, and cable may be serviced (including rebuilding) only with dielectric fluid containing less than 50 ppm PCB.
 - (ii) Any circuit breaker, recloser or cable found to contain at least 50 ppm PCBs may be serviced only in accordance with the conditions contained in 40 CFR 761.30(h)(2).

[44 FR 31542, May 31, 1979, Redesignated at 47 FR 19527, May 6, 1982, and amended at 47 FR 37357, Aug. 25, 1983; 48 FR 135, Jan. 3, 1983]

Subpart C—Marking of PCBs and PCB Items

§ 761.40 Marking requirements.

- (a) Each of the following items in existence on or after July 1, 1978 shall be marked as illustrated in Figure 1 in § 761.44(a): The mark illustrated in Figure 1 is referred to as M_L throughout this subpart.
 - (1) PCB Containers:
- (2) PCB Transformers at the time of manufacture, at the time of distribution in commerce if not already marked, and at the time of removal from use if not already marked.

[Marking of PCB-Contaminated Electrical Equipment is not required];

(3) PCB Large High Voltage Capacitors at the time of manufacture, at the time of distribution in commerce if not already marked, and at the time of removal from use if not already marked;

(4) Equipment containing a PCB Transformer or a PCB Large High Voltage Capacitor at the time of manufacture, at the time of distribution in commerce if not already marked, and at the time of removal of the equipment from use if not already marked;

(5) PCB Large Low Voltage Capacitors at the time of removal from use: (6) Electric motors using PCB cool-

ants (See also paragraph (e) of this section).

(7) Hydraulic systems using PCB hydraulic fluid (See also paragraph (e) of this section):

(8) Heat transfer systems (other than PCB Transformers) using PCBs (See also paragraph (e) of this section):

(9) PCB Article Containers containing articles or equipment that must be marked under paragraph (a) (1) through (8) above:

(10) Each storage area used to store PCBs and PCB Items for disposal.

(b) As of October 1, 1978, each transport vehicle shall be marked on each end and side with M_L as described in § 761.45(a) if it is loaded with PCB Containers that contain more than 45 kg (99.4 lbs.) of PCBs in the liquid phase or with one or more PCB Transformers (See also paragraph (e) of this section).

(c) As of January 1, 1979, the following PCB Articles shall be marked with mark M_L as described in § 761.45(a):

(1) All PCB Transformers not marked under paragraph (a) of this section (marking of PCB-Contaminated Electrical Equipment is not reouired):

(2) All PCB Large High Voltage Capacitors not marked under paragraph (a) of this section

(i) Will be marked individually with

mark M_L, or

(ii) If one or more PCB Large High Voltage Capacitors are installed in a protected location such as on a power pole, or structure, or behind a fence; the pole, structure, or fence shall be

marked with mark M1, and a record or procedure identifying the PCB Capacitors shall be maintained by the owner or operator at the protected location.

(d) As of January 1, 1979, all PCB Equipment containing a PCB Small Capacitor shall be marked at the time of manufacture with the statement, equipment contains PCB Capacitor(s)". The mark shall be of the same size as the mark M_t .

(e) As of October 1, 1979, applicable PCB Items in paragraph (a) (1). (6). (7), and (8) containing PCBs in concentrations of 50 to 500 ppm and applicable transport vehicles in paragraph (b) loaded with PCB Containers that contain more than 45 kg (99.4 lbs.) of liquid PCBs in concentrations. of 50 ppm to 500 ppm shall be marked with mark M_t as described in § 761.45(a).

(f) Where mark M_L is specified but the PCB Article or PCB Equipment is too small to accomodate the smallest permissible size of mark Mt. mark Ms as described in §761.45(b), may be used instead of mark M_L.

(g) Each large low voltage capacitor, each small capacitor normally used in alternating current circuits, and each fluorescent light ballast manufactured ("manufactured", for purposes of this sentence, means built) between July 1. 1978 and July 1, 1998 that do not contain PCBs shall be marked by the manufacturer at the time of manufacture with the statement. "No PCBs". The mark shall be of similar durability and readability as other marking that indicate electrical information, part numbers, or the manufacturer's name. For purposes of this paragraph marking requirement only is applicable to items built domestically or abroad after June 30, 1978.

(h) All marks required by this subpart must be placed in a position on the exterior of the PCB Items or transport vehicles so that the marks can be easily read by any persons inspecting or servicing the marked PCB Items or transport vehicles.

(i) Any chemical substance or mixture that is manufactured after the effective date of this rule and that contains less than 500 ppm PCB (0.05% on a dry weight basis), including PCB that is a byproduct or impurity, must be marked in accordance with any requirements contained in the exemption granted by EPA to permit such manufacture and is not subject to any other requirement in this subpart unless so specified in the exemption. This paragraph applies only to containers of chemical substances or mixtures. PCB articles and equipment into which the chemical substances or mixtures are processed, are subject to the marking requirements contained elsewhere in this subpart.

[44 FR 31542, May 31, 1979, Redesignated at 47 FR 19527, May 6, 1982, and amended at 47 FR 37359, Aug. 25, 1982]

\$ 761.45 Marking formats.

The following formats shall be used for marking:

(a) Large PCB Mark—Mi. Mark Mi shall be as shown in Figure 1. letters and striping on a white or yellow background and shall be sufficiently durable to equal or exceed the life (including storage for disposal) of the PCB Article. PCB Equipment, or PCB Container. The size of the mark shall be at least 15.25 cm (6 inches) on each side. If the PCB Article or PCB Equipment is too small to accommodate this size, the mark may be reduced in size proportionately down to a minimum of 5 cm (2 inches) on each side.

(b) Small PCB Mark—M. Mark M, shall be as shown in Figure 2. letters and striping on a white or yellow background. and shall be sufficiently durable to equal or exceed the life (including storage for disposal) of the PCB Article. PCB Equipment. or PCB Container. The mark shall be a rectangle 2.5 by 5 cm (1 inch by 2 inches). If the PCB Article or PCB Equipment is too small to accommodate this size, the mark may be reduced in size proportionately down to a minimum of 1 by 2 cm (.4 by .8 inches).

CAUTION CONTAINS PCBS

(Polychlorinated Biphenyls)

A taxic environmental contaminant requiring special handling and dispusal in accordance with U.S. Environmental Protection Agency Regulations 40 CFR 761—For Disposal Information contact the nearest U.S. E.P.A. Office

In case of accident or spill coil toil free the U.S. Coast Guard National Response Center 800 424-8802

Also Contact Tel No

Figure 1

CAUTION CONTAINS PCBs

(Polychlorinated Biphenyls)
FOR PROPER DISPOSAL INFORMATION
CONTACT U.S. ENVIRONMENTAL
PROTECTION AGENCY

Figure 2

[44 FR 31542, May 31, 1979, Redesignated at 47 FR 19527, May 6, 1982]

Subpart D—Storage and Disposal

NOTE: This subpart does not require removal of PCBs and PCB Items from service and disposal earlier than would normally be the case. However, when PCBs and PCB Items are removed from service and disposed of, disposal must be undertaken in accordance with these regulations. PCBs (including soils and debris) and PCB Items

which have been placed in a disposal site are considered to be "in service" for purposes of the applicability of this subpart. This subpart does not require PCBs and PCB Items landfilled prior to February 17, 1978 to be removed for disposal. However, if such PCBs or PCB Items are removed from the disposal site, they must be disposed of in accordance with this subpart. Other subparts are directed to the manufacture, processing, distribution in commerce, and use of PCBs and may result in some cases in disposal at an earlier date than would otherwise occur.

§ 761.60 Disposal requirements.

(a) PCBs. (1) Except as provided in paragraph (a) (2), (3), (4), and (5) of this section, PCBs must be disposed of in an incinerator which complies with § 761.70.

(2) Mineral oil dielectric fluid from PCB-Contaminated Electrical Equipment containing a PCB concentration of 50 ppm or greater, but less than 500 ppm, must be disposed of in one of the following:

(i) In an incinerator that complies

with § 761.70;

(ii) In a chemical waste landfill that complies with § 761.75 if information is provided to the owner or operator of the chemical waste landfill that shows that the mineral oil dielectric fluid does not exceed 500 ppm PCB and is not an ignitable waste as described in § 761.75(b) (8) (iii);

(iii) In a high efficiency boiler pro-

vided that:

(A) The boiler complies with the following criteria:

(1) The boiler is rated at a minimum

of 50 million BTU hours:

(2) If the boiler uses natural gas or oil as the primary fuel, the carbon monoxide concentration in the stack is 50 ppm or less and the excess oxygen is at least three (3) percent when PCBs are being burned:

(3) If the boiler uses coal as the primary fuel, the carbon monoxide concentration in the stack is 100 ppm or less and the excess oxygen is at least three (3) percent when PCBs are being

burned:

(4) The mineral oil dielectric fluid does not comprise more than ten (10) percent (on a volume basis) of the total fuel feed rate:

(5) The mineral oil dielectric fluid is not fed into the boiler unless the boiler is operating at its normal oper-

ating temperature (this prohibits feeding these fluids during either start up or shut down operations):

(6) The owner or operator of the

boiler:

Continuously monitors and (i) records the carbon monoxide concentration and excess oxygen percentage in the stack gas while burning mineral

oil dielectric fluid: or

(ii) If the boiler will burn less than 30,000 gallons of mineral oil dielectric fluid per year, measures and records the carbon monoxide concentration and excess oxygen percentage in the stack gas at regular intervals of no longer than 60 minutes while burning mineral oil dielectric fluid.

(7) The primary fuel feed rates, mineral oil dielectric fluid feed rates, and. total quantities of both primary fuel and mineral oil dielectric fluid fed to the boiler are measured and recorded at regular intervals of no longer than 15 minutes while burning mineral oil

dielectric fluid.

(8) The carbon monoxide concentration and the excess oxygen percentage are checked at least once every hour that mineral oil dielectric fluid is burned. If either measurement falls below the levels specified in this rule, the flow of mineral oil dielectric fluid to the boiler shall be stopped immediately.

(B) Thirty days before any person burns mineral oil dielectric fluid in the boiler, the person gives written notice to the EPA Regional Administrator for the EPA Region in which the boiler is located and that the notice contains the following information:

(1) The name and address of the owner or operator of the boiler and

the address of the boiler:

(2) The boiler rating in units of BTU/hour:

- (3) The carbon monoxide concentration and the excess oxygen percentage in the stack of the boiler when it is operated in a manner similar to the manner in which it will be operated when mineral oil dielectric fluid is burned: and
- (4) The type of equipment, apparatus, and procedures to be used to control the feed of mineral oil dielectric fluid to the boiler and to monitor and record the carbon monoxide concen-

tration and excess oxygen percentage in the stack.

(C) When burning mineral oil dielectric fluid, the boiler must operate at a level of output no less than the output at which the measurements required under paragraph (b)(2)(iii)(B)(3) of this section were taken.

(D) Any person burning mineral oil dielectric fluid in a boiler obtains the following information and retains the information for five years at the boiler location:

(1) The data required to be collected under paragraphs (a)(2)(A) (6) and (7) of this section: and

(2) The quantity of mineral oil dielectric fluid burned in the boiler each month:

(iv) In a facility that is approved in accordance with § 761.60(e). For the purpose of burning mineral oil dielectric fluid, an applicant under § 761.60(e) must show that his combustion process destroys PCBs as efficiently as does a high efficiency boiler, as defined in paragraph (b)(2)(iii) of this section, or a § 761.70 approved incinerator.

(3) Liquids, other than mineral oil dielectric fluid, containing a PCB concentration of 50 ppm or greater, but less than 500 ppm, shall be disposed

(i) In an incinerator which complies with § 761.70:

(ii) In a chemical waste landfill which complies with § 761.75 if information is provided to the owner or operator of the chemical waste landfill that shows that the waste does not exceed 500 ppm PCB and is not an ignitable waste as described in § 761.75(b)(8)(iii);

(iii) In a high efficiency boiler provided that.

(A) The boiler complies with the following criteria:

(1) The boiler is rated at a minimum of 50 million BTU/hour;

(2) If the boiler uses natural gas or oil as the primary fuel, the carbon monoxide concentration in the stack is 50 ppm or less and the excess oxygen is at least three (3) percent when PCBs are being burned;

(3) If the boiler uses coal as the primary fuel, the carbon monoxide concentration in the stack is 100 ppm or

less and the excess oxygen is at least three (3) percent when PCBs are being burned:

(4) The waste does not comprise more than ten (10) percent (on a volume basis) of the total fuel feed rate:

(5) The waste is not fed into the boiler unless the boiler is operating at its normal operating temperature (this prohibits feeding these fluids during either start up or shut down operations):

(6) The owner or operator of the boiler must:

(i) Continuously monitor and record the carbon monoxide concentration and excess oxygen percentage in the stack gas while burning waste fluid; or

(ii) If the boiler will burn less than 30.000 gallons of waste fluid per year, measure and record the carbon monoxide concentration and excess oxygen percentage in the stack gas at regular intervals of no longer than 60 minutes while burning waste fluid:

(7) The primary fuel feed rate, waste fluid feed rate, and total quantities of both primary fuel and waste fluid fed to the boiler must be measured and recorded at regular intervals of no longer than 15 minutes while burning waste fluid; and

(8) The carbon monoxide concentration and the excess oxygen percentage must be checked at least once every hour that the waste is burned. If either measurement falls below the levels specified in this rule, the flow of waste to the boiler shall be stopped immediately.

(B) Prior to any person burning these liquids in the boiler, approval must be obtained from the EPA Regional Administrator for the EPA Region in which the boiler is located and any persons seeking such approval must submit to the EPA Regional Administrator a request containing at least the following information:

(1) The name and address of the owner or operator of the boiler and the address of the boiler;

(2) The boiler rating in units of BTU/hour:

(3) The carbon monoxide concentration and the excess oxygen percentage in the stack of the boiler when it is operated in a manner similar to the manner in which it will be operated when low concentration PCB liquid is burned:

(4) The type of equipment, apparatus, and procedures to be used to control the feed of mineral oil dielectric fluid to the boiler and to monitor and record the carbon monoxide concentration and excess oxygen percentage in the stack:

(5) The type of waste to be burned (e.g., hydraulic fluid, contaminated fuel oil, heat transfer fluid, etc.):

(6) The concentration of PCBs and of any other chlorinated hydrocarbon in the waste and the results of analyses using the American Society of Testing and Materials (ASTM) methods as follows: carbon and hydrogen content using ASTM D-3178-73 (reapproved 1979), nitrogen content using ASTM E-258-67, sulfur content using ASTM D-2784-80, D-1266-80, or D-129-64, chlorine content using ASTM D-808-81, water and sediment content using either ASTM D-2709-68 or D-1796-68, ash content using D-482-80, calorific value using ASTM D-240-76 (reapproved 1980), carbon residue using either ASTM D-2158-80 or -D-524-81, and flash point using ASTM

(7) The quantity of wastes estimated to be burned in a thirty (30) day period:

(8) An explanation of the procedures to be followed to insure that burning the waste will not adversely affect the operation of the boiler such that combustion efficiency will decrease.

(C) On the basis of the information in paragraph (a)(3)(iii)(B) of this section and any other available information, the Regional Administrator may, at his discretion, find that the alternate disposal method will not present an unreasonable risk of injury to health or the environment and approve the use of the boiler:

(D) When burning PCB wastes, the boiler must operate at a level of output no less than the output at which the measurements required under paragraph (a)(3)(iii)(B)(3) of this section were taken; and

(E) Any person burning liquids in boilers approved as provided in paragraph (a)(3)(iii)(C) of this section, must obtain the following information

and retain the information for five years at the boiler location:

(1) The data required to be collected in paragraphs (a)(3)(iii)(A) (6) and (7) of this section:

(2) The quantity of low concentration PCB liquid burned in the boiler each month.

(3) The analysis of the waste required by paragraph (a)(3)(iii)(B)(6) of this section taken once a month for each month during which low concentration PCB liquid is burned in the boiler.

(iv) In a facility that is approved in accordance with § 761.60(e). For the purpose of burning liquids, other than mineral oil dielectric fluid. containing 50 ppm or greater PCB, but less than 500 ppm PCB, an applicant under § 761.60(e) must show that his combustion process destroys PCBs as efficiently as does a high efficiency boiler, as defined in § 761.60(a)(2)(iii), or a § 761.70 incinerator.

(4) Any non-liquid PCBs in the form of contaminated soil. rags. or other debris shall be disposed of:

(i) In an incinerator which complies with § 761.70; or

(ii) In a chemical waste landfill which complies with § 761.75.

Note: Except as provided in § 761.75(b)(8)(ii), liquid PCBs shall not be processed into non-liquid forms to circumvent the high temperature incineration requirements of § 761.60(a).

(5) All dredged materials and municipal sewage treatment sludges that contain PCBs shall be disposed of:

(i) In an incinerator which complies with § 761.70.

(ii) In a chemical waste landfill which complies with § 761.65; or

(iii) Upon application, using a disposal method to be approved by the Agency's Regional Administrator in the EPA Region in which the PCBs are located. Applications for disposal in a manner other than prescribed in (i) or (ii) above must be made in writing to the Regional Administrator. The application must contain information that, based on technical, environmental, and economic considerations, indicates that disposal in an incinerator or chemical waste landfill is not reasonable and appropriate, and that the al-

ternate disposal method will provide adequate protection to health and the environment. The Regional Administrator may request other information that he or she believes to be necessary for evaluation of the alternate disposal method. Any approval by the Regional Administrator shall be in writing and may contain any appropriate limitations on the approved alternate method for disposal. In addition to these regulations, the Regional Administrator shall consider other applicable Agency guidelines, criteria, and regulations to ensure that the discharges of dredged material and sludges that contain PCBs and other contaminants are adequately controlled to protect the environment. The person to whom such approval is issued must comply with all limitations contained in the approval.

(6) When storage is desired prior to disposal. PCBs shall be stored in a facility which complies with § 761.65.

(b) PCB Articles—(1) Transformers.
(i) PCB Transformers shall be disposed of in accordance with either of the following:

(A) In an incinerator that complies

with § 761.70; or

(B) In a chemical waste landfill which complies with § 761.75: Pro-vided. That the transformer is first drained of all free flowing liquid, filled with solvent, allowed to stand for at least 18 hours, and then drained thoroughly. PCB liquids that are removed shall be disposed of in accordance with paragraph (a) of this section. Solvents may include kerosene, xylene, toluene and other solvents in which PCBs are readily soluble. Precautionary measures should be taken, however, that the solvent flushing procedure is conducted in accordance with applicable safety and health standards as required by Federal or State regulations.

(2) PCB Capacitors. (i) The disposal of any capacitor shall comply with all requirements of this subpart unless it is known from label or nameplate information. manufacturer's literature (including documented communications with the manufacturer). or chemical analysis that the capacitor

does not contain PCBs.

(ii) Any person may dispose of PCB Small Capacitors as municipal solid

waste, unless that person is subject to the requirements of paragraph (b)(2)(iv) of this section.

(iii) Any PCB Large High or Low Voltage Capacitor which contains 500 ppm or greater PCBs, owned by any person, shall be disposed of in accordance-with either of the following:

(A) Disposal in an incinerator that

complies with § 761.70; or

(B) Until March 1, 1981, disposal in a chemical waste landfill that complies with § 761.75.

(iv) Any PCB Small Capacitor owned by any person who manufactures or at any time manufactured PCB Capacitors or PCB Equipment and acquired the PCB Capacitors in the course of such manufacturing shall be disposed of in accordance with either of the following:

(A) Disposal in an incinerator which

complies with § 761.70; or

(B) Until March 1, 1981, disposal in a chemical waste landfill which complies

with § 761.75.

(v) Notwithstanding the restrictions imposed by paragraph (b)(2)(iii)(B) or (b)(2)(iv)(B) of this section, PCB capacitors may be disposed of in PCB chemical waste landfills that comply with § 761.75 subsequent to March 1. 1981, if the Assistant Administrator for Pesticides and Toxic Substances publishes a notice in the FEDERAL REG-ISTER declaring that those landfills are available for such disposal and explaining the reasons for the extension or reopening. An extension or reopening for disposal of PCB capacitors that is granted under this subsection shall be subject to such terms and conditions as the Assistant Administrator may prescribe and shall be in effect for such period as the Assistant Administrator may prescribe. The Assistant Administrator may permit disposal of PCB capacitors in EPA approved chemical waste landfills after March 1, 1981, if in his opinion,

(1) Adequate incineration capability for PCB capacitors is not available, or

(2) The incineration of PCB capacitors will significantly interfere with the incineration of liquid PCBs, or

(3) There is other good cause shown.

As part of this evaluation, the Assistant Administrator will consider the

impact of his action on the incentives to construct or expand PCB incinerators.

(vi) Prior to disposal in a § 761.75 chemical waste landfill, all large PCB capacitors, and all small PCB capacitors described in paragraph (b)(2)(iv) of this section, shall be placed in one of the Department of Transportation specification containers identified in § 761.65(c)(6) or in containers that comply with 49 CFR 178.118 (specification 17H containers). Large PCB capacitors which are too big to fit inside one of these containers shall be placed in a container with strength and durability equivalent to the DOT specification containers. In all cases, interstitial space in the container shall be filled with sufficient absorbent material (such as sawdust or soil) to absorb any liquid PCBs remaining in the capacitors.

(3) PCB hydraulic machines. PCB hydraulic machines such as die casting machines may be disposed of as municipal solid waste or salvage provided that the machines are drained of all free-flowing liquid and the liquid is disposed of in accordance with the provisions of paragraph (a) of this section. If the PCB liquid contains 1000 ppm PCB or greater, then the hydraulic machine must be flushed prior to disposal with a solvent containing less than 50 ppm PCB (see transformer solvents at paragraph (b)(1)(i)(B) of this section) and the solvent disposed of in accordance with paragraph (a) of this section.

(4) PCB-Contaminated Electrical Equipment. All PCB-Contaminated Electrical Equipment except capacitors shall be disposed of by draining all free flowing liquid from the electrical equipment and disposing of the liquid in accordance with paragraph (a)(2) or (3) of this section. The disposal of the drained electrical equipment is not regulated by this rule. Capacitors that contain between 50 and 500 ppm PCBs shall be disposed of in an incinerator that complies with § 761.70 or in a chemical waste landfill that complies with § 761.75.

(5) Other PCB Articles. (i) PCB Articles with a PCB concentration of 500 ppm or greater must be disposed of:

(A) In an incinerator that complies with § 761.70; or

(B) In a chemical waste landfill that complies with \$761.75, provided that all free-flowing liquid PCBs have been thoroughly drained from any articles before the articles are placed in the chemical waste landfill and that the drained liquids are disposed of in an incinerator, that complies with \$761.70.

(ii) PCB Articles with a PCB concentration between 50 and 500 ppm must be disposed of by draining all free flowing liquid from the article and disposing of the liquid in accordance with paragraph (a)(2) or (3) of this section. The disposal of the drained article is not regulated by this rule.

(6) Storage of PCB Articles: Except for a PCB Article described in paragraph (b)(2)(ii) of this section and hydraulic machines that comply with the municipal solid waste disposal provisions described in paragraph (b)(3) of this section, any PCB Article shall be stored in accordance with § 761.65 prior to disposal.

(c) PCB Containers. (1) Unless decontaminated in compliance with \$761.79 or as provided in (c)(2) of this section, a PCB Container shall be disposed of:

(i) In an incinerator which complies with § 761.70, or

(ii) In a chemical waste landfill that complies with § 761.75; provided that if there are PCBs in a liquid state, the PCB Container shall first be drained and the PCB liquid disposed of in accordance with paragraph (a) of this section.

(2) Any PCB Container used to contain only PCBs at a concentration less than 500 ppm shall be disposed of as municipal solid wastes; provided that if the PCBs are in a liquid state, the PCB Container shall first be drained and the PCB liquid shall be disposed of in accordance with paragraph (a) of this section.

(3) Prior to disposal, a PCB container shall be stored in a facility which complies with § 761.65.

(d) Spills. (1) Spills, leaks, and other uncontrolled discharges of PCBs constitute the disposal of PCBs.

(2) PCBs resulting from the clean-up and removal of spills, leaks, or other

uncontrolled discharges, must be stored and disposed of in accordance with paragraph (a) of this section.

(3) These regulations do not exempt any person from any actions or liability under other statutory authorities, including but not limited to the Clean Water Act, the Resource Conservation and Recovery Act, and the Comprehensive Environmental Response, Compensation, and Liability Act of 1980.

(e) Any person who is required to incinerate any PCBs and PCB Items under this subpart and who can demonstrate that an alternative method of destroying PCBs and PCB Items exists and that this alternative method can achieve a level of performance equivalent to § 761.70 incinerators or high efficiency boilers as provided in paragraph (a)(2)(iv) and (a)(3)(iv) of this section, may submit a written request to either the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances for an exemption from the incineration requirements of § 761.70 or § 761.60. Requests for approval of alternate methods that will be operated in more than one region must be submitted to the Assistant Administrator for Pesticides and Toxic Substances except for research and development involving less than 500 pounds of PCB material (see paragraph (i)(2)). Requests for approval of alternate methods that will be operated in only one region must be submitted to the appropriate Regional Administrator. The applicant must show that his method of destroying PCBs will not present an unreasonable risk of injury to health or the environment. On the basis of such information and any available information, the Regional Administrator or Assistant Administrator for Pesticides and Toxic Substances may, in his discretion, approve the use of the alternate method if he finds that the alternate disposal method provides PCB destruction equivalent to disposal in a § 761.70 incinerator or a § 761.60 high efficiency boiler and will not present an unreasonable risk of injury to health or the environment. Any approval must be stated in writing and may contain such conditions and provisions as the Regional Administrator

or Assistant Administrator for Pesticides and Toxic Substances deems appropriate. The person to whom such waiver is issued must comply with all limitations contained in such determination.

(f)(1) Each operator of a chemical waste landfill, incinerator, or alternative to incineration approved under paragraph (e) of this section shall give the following written notices to the state and local governments within whose jurisdiction the disposal facility is located:

(i) Notice at least thirty (30) days before a facility is first used for disposal of PCBs required by these regulations; and

(ii) At the request of any state or local government, annual notice of the quantities and general description of PCBs disposed of during the year. This annual notice shall be given no more than thirty (30) days after the end of the year covered.

(iii) The Regional Administrator may reduce the notice period required by paragraph (f)(1)(i) of this section from thirty days to a period of no less than five days in order to expedite interim approval of the chemical waste landfill located in Sedgwick County, Kansas.

(2) Any person who disposes of PCBs under a paragraph (a)(5)(iii) of this section incineration or chemical waste landfilling waiver shall give written notice at least thirty (30) days prior to conducting the disposal activities to the state and local governments within whose jurisdiction the disposal is to take place.

(g) Testing procedures. (1) Owners or users of mineral oil dielectric fluid electrical equipment may use the following procedures to determine the concentration of PCBs in the dielectric fluid:

(i) Dielectric fluid removed from mineral oil dielectric fluid electrical equipment may be collected in a common container, provided that no other chemical substances or mixtures are added to the container. This common container option does not permit dilution of the collected oil. Mineral oil that is assumed or known to contain at least 50 ppm PCBs must not be mixed with mineral oil that is

known or assumed to contain less than 50 ppm PCBs to reduce the concentration of PCBs in the common container. If dielectric fluid from untested, oil-filled circuit breakers, reclosers, or cable is collected in a common container with dielectric fluid from other oil-filled electrical equipment, the entire contents of the container must be treated as PCBs at a concentration of at least 50 ppm, unless all of the fluid from the other oil-filled electrical equipment has been tested and shown to contain less than 50 ppm PCBs.

(ii) For purposes of complying with the marking and disposal requirements, representative samples may be taken from either the common containers or the individual electrical equipment to determine the PCB concentration, except that if any PCBs at a concentration of 500 ppm or greater have been added to the container or equipment then the total container contents must be considered as having a PCB concentration of 500 ppm or greater for purposes of complying with the disposal requirements of this subpart. For purposes of this subparagraph, representative samples of mineral oil dielectric fluid are either samples taken in accordance with American Society of Testing and Materials method D-923 or samples taken from a container that has been thoroughly mixed in a manner such that any PCBs in the container are uniformly distributed throughout the liquid in the container.

(2) Owners or users of waste oil may use the following procedures to determine the PCB concentration of waste

(i) Waste oil from more than one source may be collected in a common container, provided that no other chemical substances or mixtures, such as non-waste oils, are added to the container.

(ii) For purposes of complying with the marking and disposal requirements, representative samples may be taken from either the common containers or the individual electrical equipment to determine the PCB concentration. Except. That if any PCBs at a concentration of 500 ppm or greater have been added to the container or equipment then the total

container contents must be considered as having a PCB concentration of 500 ppm or greater for purposes of complying with the disposal requirements of the Subpart. For purposes of this paragraph, representative samples of mineral oil dielectric fluid are either samples taken in accordance with American Society of Testing and Materials method D-923-81 or samples taken from a container that has been thoroughly mixed in a manner such that any PCBs in the container are uniformly distributed throughout the liquid in the container.

(h) Requirements for export and import of PCBs for purposes of disposal and PCB Items for purposes of disposal are found in § 761.20.

(i) Approval authority for disposal methods. (1) The officials (the Assistant Administrator for Pesticides and Toxic Substances and the Regional designated Administrators) \$\$ 761.60 (e) and 761.70 (a) and (b) to receive requests for approval of PCB disposal activities are the primary approval authorities for these activities. Notwithstanding, the Assistant Administrator for Pesticides and Toxic Substances may, at his her discretion. assign the authority to review and approve any aspect of a disposal system to the Office of Pesticides and Toxic Substances or to a Regional Administrator.

(2) Except for activity authorized under § 761.30(j), research and development (R and D) into PCB disposal methods using a total of less than 500 pounds of PCB material (regardless of PCB concentration) will be reviewed and approved by the appropriate EPA Regional Administrator and research and development using 500 pounds or more of PCB material (regardless of PCB concentration) will be reviewed by the approval authorities set out in § 761.60(e) and 761.70 (a) and (b).

[44 FR 31542, May 31, 1979, as amended at 44 FR 54297, Sept. 19, 1979; 45 FR 20475, Mar. 28, 1980, Redesignated at 47 FR 19527, May 6, 1982, and amended at 47 FR 37359, Aug. 25, 1982; 48 FR 5730, Feb. 8, 1983; 48 FR 13185, Mar. 30, 1983; 48 FR 15125, Apr. 7, 1983]

§ 761.65 Storage for disposal.

(a) Any PCB Article or PCB Container stored for disposal before January 1, 1983, shall be removed from storage and disposed of as required by this part before January 1, 1984. Any PCB Article or PCB Container stored for disposal after January 1, 1983. shall be removed from storage and disposed of as required by Subpart D within one year from the date when it was first placed into storage.

(b) Except as provided in paragraph (c) of this section, after July 1, 1978, owners or operators of any facilities used for the storage of PCBs and PCB Items designated for disposal shall comply with the following require-

ments:

(1) The facilities shall meet the fol-

lowing criteria:

(i) Adequate roof and walls to prevent rain water from reaching the

stored PCBs and PCB Items:

(ii) An adequate floor which has continuous curbing with a minimum six inch high curb. The floor and curbing must provide a containment volume equal to at least two times the internal volume of the largest PCB Article or PCB Container stored therein or 25 percent of the total internal volume of all PCB Articles or PCB Containers stored therein, whichever is greater:

(iii) No drain valves, floor drains, expansion joints, sewer lines, or other openings that would permit liquids to

flow from the curbed area;

(iv) Floors and curbing constructed of continuous smooth and impervious materials, such as Portland cement concrete or steel, to prevent or minimize penetration of PCBs; and

(v) Not located at a site that is below the 100-year flood water elevation.

(c)(1) The following PCB Items may be stored temporarily in an area that does not comply with the requirements of paragraph (b) of this section for up to thirty days from the date of their removal from service, provided that a notation is attached to the PCB Item or a PCB Container (containing the item) indicating the date the item was removed from service:

(i) Non-leaking PCB Articles and

PCB Equipment:

(ii) Leaking PCB Articles and PCB Equipment if the PCB Items are

placed in a non-leaking PCB Container that contains sufficient sorbent materials to absorb any liquid PCBs remaining in the PCB Items;

(iii) PCB Containers containing nonliquid PCBs such as contaminated soil,

rags, and debris; and

(iv) PCB Containers containing liquid PCBs at a concentration between 50 and 500 ppm, provided a Spill Prevention, Control and Countermeasure Plan has been prepared for the temporary storage area in accordance with 40 CFR Part 112. In addition, each container must bear a notation that indicates that the liquids in the drum do not exceed 500 ppm PCB.

(2) Non-leaking and structurally undamaged PCB Large High Voltage Capacitors and PCB-Contaminated Electrical Equipment that have not been drained of free flowing dielectric fluid may be stored on pallets next to a storage facility that meets the requirements of paragraph (b) of this section. PCB-Contaminated Electrical Equipment that has been drained of free flowing dielectric fluid is not subject to the storage provisions of § 761.65. Storage under this subparagraph will be permitted only when the storage facility has immediately available unfilled storage space equal to 10 percent of the volume of capacitors and equipment stored outside the facility. The capacitors and equipment temporarily stored outside the facility shall be checked for leaks weekly.

(3) Any storage area subject to the requirements of paragraph (b) or paragraph (c)(1) of this section shall be marked as required in Subpart C-

1

§ 761.40(a)(10).

(4) No item of movable equipment that is used for handling PCBs and PCB Items in the storage facilities and that comes in direct contact with PCBs shall be removed from the storage facility area unless it has been decontaminated as specified in § 761.79.

(5) All PCB Articles and PCB Containers in storage shall be checked for leaks at least once every 30 days. Any leaking PCB Articles and PCB Containers and their contents shall be transferred immediately to properly marked non-leaking containers. Any spilled or leaked materials shall be immediately cleaned up, using sorbents or other adequate means, and the PCB-contaminated materials and residues shall be disposed of in accordance with § 761.60(a)(4).

(6) Except as provided in paragraph (c)(7) of this section, any container used for the storage of liquid PCBs shall comply with the Shipping Container Specification of the Department of Transportation (DOT), 49 CFR 178.80 (Specification 5 container without removable head), 178.82 (Specification 5B container without removable head), 178.102 (Specification 6D overpack with Specification 2S(§ 178.35) or 2SL(§ 178.35a) polyethylene containers) or 178.116 (Specification 17E container). Any container used for the storage of non-liquid PCBs shall comply with the specifications of 49 CFR 178.80 (Specification 5 container), 178.82 (Specification 5B container) or 178.115 (Specification 17C container). As an alternate, containers larger than those specified in DOT Specifications 5, 5B, or 17C may be used for non-liquid PCBs if the containers are designed and constructed in a manner that will provide as much protection against leaking and exposure to the environment as the DOT Specification containers, and are of the same relative strength and durability as the DOT Specification containers.

(7) Storage containers for liquid PCBs can be larger than the containers specified in paragraph (c)(6) of this section provided that:

(i) The containers are designed, constructed, and operated in compliance with Occupational Safety and Health Standards, 29 CFR 1910.106, Flammable and combustible liquids. Before using these containers for storing PCBs, the design of the containers must be reviewed to determine the effect on the structural safety of the containers that will result from placing liquids with the specific gravity of PCBs into the containers (see 29 CFR 1910.106(b)(i)(f)).

(ii) The owners or operators of any facility using containers described in paragraph (c)(7)(i) of this section shall prepare and implement a Spill Prevention Control and Countermeasure (SPCC) Plan as described in Part 112 of this title. In complying with 40 CFR

Part 112, the owner or operator shall read "oil(s)" as "PCB(s)" whenever it appears. The exemptions for storage capacity, 40 CFR 112.1cd)(2), and the amendment of SPCC plans by the Regional Administrator, 40 CFR 112.4, shall not apply unless some fraction of the liquids stored in the container are oils as defined by section 311 of the Clean Water Act.

(8) PCB Articles and PCB Containers shall be dated on the article or container when they are placed in storage. The storage shall be managed so that the PCB Articles and PCB Containers can be located by the date they entered storage. Storage containers provided in paragraph (c)(7) of this section shall have a record that includes for each batch of PCBs the quantity of the batch and date the batch was added to the container. The record shall also include the date, quantity, and disposition of any batch of PCBs removed from the container.

(9) Owners or operators of storage facilities shall establish and maintain records as provided in § 761.80.

[44 FR 31542, May 31, 1979, Redesignated at 47 FR 19527, May 6, 1982, and amended at 47 FR 37359, Aug. 8, 1982]

§ 761.70 Incineration.

(a) Liquid PCBs. An incinerator used for incinerating PCBs shall be approved by an EPA Regiona! Administrator or the Assistant Administrator for Pesticides and Toxic Substances pursuant to paragraph (d) of this section. Requests for approval of incinerators to be used in more than one region must be submitted to the Assistant Administrator for Pesticides and Toxic Substances, except for research and development involving less than 500 pounds of PCB material (see section 761.60(i)(2)). Requests for approval of incinerators to be used in only one region must be submitted to the appropriate Regional Administrator. The incinerator shall meet all of the requirements specified in paragraph (a) (1) through (9) of this section, unless a waiver from these requirements is obtained pursuant to paragraph (d)(5) of this section. In addition, the incinerator shall meet any other requirements which may be prescribed pursuant to paragraph (d)(4) of this section.

(1) Combustion criteria shall be

either of the following:

(i) Maintenance of the introduced liquids for a 2-second dwell time at 1200°C(±100°C) and 3 percent excess oxygen in the stack gas; or

(ii) Maintenance of the introduced liquids for a 1½ second dwell time at 1600°C(±100°C) and 2 percent excess

oxygen in the stack gas.

(2) Combustion efficiency shall be at least 99.9 percent computed as follows:

Combustion efficiency = Cco2/Cco2+Cco> 100

Cco = Concentration of carbon dioxide. Cco=Concentration of carbon monoxide.

(3) The rate and quantity of PCBs which are fed to the combustion system shall be measured and recorded at regular intervals of no longer than 15 minutes.

(4) The temperatures of the incineration process shall be continuously measured and recorded. The combustion temperature of the incineration process shall be based on either direct (pyrometer) or indirect (wall thermocouple-pyrometer correlation) temperature readings.

(5) The flow of PCBs to the incinerator shall stop automatically whenever the combustion temperature drops below the temperatures specified in paragraph (a)(1) of this section.

(6) Monitoring of stack emission products shall be conducted:

(i) When an incinerator is first used for the disposal of PCBs under the

provisions of this regulation;

(ii) When an incinerator is first used for the disposal of PCBs after the incinerator has been modified in a manner which may affect the characteristics of the stack emission products: and

(iii) At a minimum such monitoring shall be conducted for the following parameters: (a)O₂: (b) CO; (c) CO₂; (d) Oxides of Nitrogen (NO.); (e) Hydrochloric Acid (HCl); (f) Total Chlorinated Organic Content (RCl); (g) PCBs: and (h) Total Particulate Matter.

(7) At a minimum monitoring and recording of combustion products and incineration operations shall be con-

ducted for the following parameters whenever the incinerator is incinerating PCBs: (i) Oz; (ii) CO; and (iii) COz. The monitoring for O, and CO shall be continuous. The monitoring for CO, shall be periodic, at a frequency specified by the Regional Administrator or Assistant Administrator for Pesticides

and Toxic Substances.

(8) The flow of PCBs to the incinerator shall stop automatically when any one or more of the following conditions occur, unless a contingency plan is submitted by the incinerator owner or operator and approved by the Regional Administrator or Assistant Administrator for Pesticides and Toxic Substances. The contingency plan indicates what alternative measures the incinerator owner or operator would take if any of the following conditions occur:

(i) Failure of monitoring operations specified in paragraph (a)(7) of this

(ii) Failure of the PCB rate and quantity measuring and recording equipment specified in paragraph (a)(3) of this section; or

(iii) Excess oxygen falls below the percentage specified in paragraph

(a)(1) of this section.

(9) Water scrubbers shall be used for HCl control during PCB incineration and shall meet any performance requirements specified by the appropriate EPA Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances. Scrubber effluent shall be monitored and shall comply with applicable effluent or pretreatment standards, and any other State and Federal laws and regulations. An alternate method of HCl control may be used if the alternate method has been approved by the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances. (The HCl neutralizing capability of cement kilns is considered to be an alternate method.)

(b) Nonliquid PCBs. An incinerator used for incinerating nonliquid PCBs, PCB Articles, PCB Equipment, or PCB Containers shall be approved by the appropriate EPA Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances pursuant to paragraph (d) of this section. Requests for approval of incinerators to be used in more than one region must be submitted to the Assistant Administrator for Pesticides and Toxic Substances, except for research and development involving less than 500 pounds of PCB material (see section 761.60(i)(2)). Requests for approval of incinerators to be used in only one region must be submitted to the appropriate Regional Administrator. The incinerator shall meet all of the requirements specified in paragraphs (b) (1) and (2) of this section unless a waiver from these requirements is obtained pursuant to paragraph (d)(5) of this section. In addition, the incinerator shall meet any other requirements that may be prescribed pursu-

ant to paragraph (d)(4) of this section.
(1) The mass air emissions from the incinerator shall be no greater than 0.001g PCB/kg of the PCB introduced

into the incinerator.

(2) The incinerator shall comply with the provisions of paragraphs (a)(2), (3), (4), (6), (7), (8)(i) and (ii), and (9) of this section.

(c) Maintenance of data and records. All data and records required by this section shall be maintained in accordance with § 761.80. Records and moni-

toring.

(d) Approval of incinerators. Prior to the incineration of PCBs and PCB Items the owner or operator of an incinerator shall receive the written approval of the Agency Regional Administrator for the region in which the incinerator is located, or the Assistant Administrator for Pesticides and Toxic Substances. Approval from the Assistant Administrator for Pesticides and Toxic Substances may be effective in all ten EPA regions. Such approval shall be obtained in the following manner:

(1) Application. The owner or operator shall submit to the Regional Administrator or the Assistant Administrator an application which contains:

(i) The location of the incinerator;

(ii) A detailed description of the incinerator including general site plans and design drawings of the incinerator:

(iii) Engineering reports or other information on the anticipated performance of the incinerator; Title 40-Protection of Environment

(iv) Sampling and monitoring equipment and facilities available:

(v) Waste volumes expected to be incinerated:

(vi) Any local, State, or Federal permits or approvals; and

(vii) Schedules and plans for complying with the approval requirements of

this regulation.

(2) Trial burn. (i) Following receipt of the application described in paragraph (d)(1) of this section, the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances shall determine if a trial burn is required and notify the person who submitted the report whether a trial burn of PCBs and PCB Items must be conducted. The Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances may require the submission of any other information that the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances finds to be reasonably necessary to determine the need for a trial burn. Such other information shall be restricted to the types of information required in paragraphs (d)(1) (i) through (vii) of this section.

(ii) If the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances determines that a trial burn must be held, the person who submitted the report described in paragraph (d)(1) of this section shall submit to the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances a detailed plan for conducting and monitoring the trial burn. At a minimum, the plan must include:

(A) Date trial burn is to be conducted:

(B) Quantity and type of PCBs and PCB Items to be incinerated:

(C) Parameters to be monitored and location of sampling points:

(D) Sampling frequency and methods and schedules for sample analyses: and

(E) Name, address, and qualifications of persons who will review analytical results and other pertinent data, and who will perform a technical evaluation of the effectiveness of the trial burn.

Ħ

(iii) Following receipt of the plan described in paragraph (d)(2)(ii) of this section, the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances will approve the plan, require additions or modifications to the plan, or disapprove the plan. If the plan is disapproved, the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances will notify the person who submitted the plan of such disapproval, together with the reasons why it is disapproved. That person may thereafter submit a new plan in accordance with paragraph (d)(2)(ii) of this section. If the plan is approved (with any additions or modifications which the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances may prescribe), the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances will notify the person who submitted the plan of the approval. Thereafter, the trial burn shall take place at a date and time to be agreed upon between the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances and the person who submitted the plan.

(3) Other information. In addition to the information contained in the report and plan described in paragraphs (d) (1) and (2) of this section. the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances may require the owner or operator to submit any other information that the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances finds to be reasonably necessary to determine whether an incinerator shall

be approved.

Note: The Regional Administrator will have available for review and inspection an Agency manual containing information on sampling methods and analytical procedures for the parameters required in § 761.70(a) (3), (4), (6), and (7) plus any other parameters he/she may determine to be appropriate. Owners or operators are encouraged to review this manual prior to submitting any report required in § 761.70.

(4) Contents of approval. (i) Except as provided in paragraph (d)(5) of this section, the Regional Administrator or

the Assistant Administrator for Pesticides and Toxic Substances may not approve an incinerator for the disposal of PCBs and PCB Items unless he finds that the incinerator meets all of the requirements of paragraphs (a) and/or (b) of this section.

(ii) In addition to the requirements of paragraphs (a) and/or (b) of this section, the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances may include in an approval any other requirements that the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances finds are necessary to ensure that operation of the incinerator does not present an unreasonable risk of injury to health or the environment from PCBs. Such requirements may include a fixed period of time for which the

approval is valid.

(5) Waivers. An owner or operator of the incinerator may submit evidence to the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances that operation of the incinerator will not present an unreasonable risk of injury to health or the environment from PCBs, when one or more of the requirements of paragraphs (a) and/or (b) of this section are not met. On the basis of such evidence and any other available information, the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances may in his/her discretion find that any requirement of paragraphs (a) and (b) of this section is not necessary to protect against such a risk, and may waive the requirements in any approval for that incinerator. Any finding and waiver under this paragraph must be stated in writing and included as part of the approval.

(6) Persons approved. An approval will designate the persons who own and who are authorized to operate the incinerator, and will apply only to such persons, except as provided in paragraph (d)(8) of this section.

(7) Final approval. Approval of an incinerator will be in writing and signed by the Regional Administrator or the Assistant Administrator for Pesticides and Toxic Substances. The

approval will state all requirements applicable to the approved incinerator.

(8) Transfer of property. Any person who owns or operates an approved incinerator must notify EPA at least 30 days before transferring ownership in the incinerator or the property it stands upon, or transferring the right to operate the incinerator. The transferor must also submit to EPA, at least 30 days before such transfer, a notarized affidavit signed by the transferee which states that the transferee will abide by the transferor's EPA incinerator approval. Within 30 days of receiving such notification and affidavit. EPA will issue an amended approval substituting the transferee's name for the transferor's name, or EPA may require the transferee to apply for a new incinerator approval. In the latter case, the transferee must abide by the transferor's EPA approval until EPA issues the new approval to the transferee.

[44 FR 31542, May 31, 1979, Redesignated at 47 FR 19527, May 6, 1982, and amended at 48 FR 13185, Mar. 30, 1983]

§ 761.75 Chemical waste landfills.

(a) General. A chemical waste landfill used for the disposal of PCBs and
PCB Items shall be approved by the
Agency Regional Administrator pursuant to paragraph (c) of this section.
The landfill shall meet all of the requirements specified in paragraph (b)
of this section, unless a waiver from
these requirements is obtained pursuant to paragraph (c)(4) of this section.
In addition, the landfill shall meet any
other requirements that may be prescribed pursuant to paragraph (c)(3)
of this section.

(b) Technical requirements. Requirements for chemical waste landfills used for the disposal of PCBs and PCB Items are as follows:

(1) Soils. The landfill site shall be located in thick, relatively impermeable formations such as large-area clay pans. Where this is not possible, the soil shall have a high clay and silt content with the following parameters:

(i) In-place soil thickness, 4 feet or compacted soil liner thickness, 3 feet;

(ii) Permeability (cm/sec), equal to or less than 1×10-7;

(iii) Percent soil passing No. 200 Sieve, >30;

(iv) Liquid Limit, >30; and

(v) Plasticity Index > 15.

(2) Synthetic membrane liners. Synthetic membrane liners shall be used when, in the judgment of the Regional Administrator, the hydrologic or geologic conditions at the landfill require such a liner in order to provide at least a permeability equivalent to the soils paragraph (b)(1) of in section. Whenever a synthetic liner is used at a landfill site, special precautions shall be taken to insure that its integrity is maintained and that it is chemically compatible with PCBs. Adequate soil underlining and soil cover shall be provided to prevent excessive stress on the liner and to prevent rupture of the liner. The liner must have a minimum thickness of 30 mils.

(3) Hydrologic conditions. The bottom of the landfill shall be above the historical high groundwater table as provided below. Floodplains, shorelands, and groundwater recharge areas shall be avoided. There shall be no hydraulic connection between the site and standing or flowing surface water. The site shall have monitoring wells and leachate collection. The bottom of the landfill liner system or natural inplace soil barrier shall be at least fifty feet from the historical high water

table.

(4) Flood protection. (i) If the landfill site is below the 100-year floodwater elevation, the operator shall provide surface water diversion dikes around the perimeter of the landfill site with a minimum height equal to two feet above the 100-year floodwater elevation.

(ii) If the landfill site is above the 100-year floodwater elevation, the operators shall provide diversion structures capable of diverting all of the surface water runoff from a 24-hour.

25-year storm.

(5) Topography. The landfill site shall be located in an area of low to moderate relief to minimize erosion and to help prevent landslides or slumping.

(6) Monitoring systems—(i) Water sampling. (A) For all sites receiving PCBs, the ground and surface water

from the disposal site area shall be sampled prior to commencing operations under an approval provided in paragraph (c) of this section for use as baseline data.

(B) Any surface watercourse designated by the Regional Administrator using the authority provided in paragraph (c)(3)(ii) of this section shall be sampled at least monthly when the landfill is being used for disposal operations.

(C) Any surface watercourse designated by the Regional Administrator using the authority provided in paragraph (c)(3)(ii) of this section shall be sampled for a time period specified by the Regional Administrator on a frequency of no less than once every six months after final closure of the disposal area.

(ii) Groundwater monitor wells. (A) If underlying earth materials are homogenous, impermeable, and uniformly sloping in one direction, only three sampling points shall be necessary. These three points shall be equally spaced on a line through the center of the disposal area and extending from the area of highest water table elevation to the area of the lowest water table elevation on the property.

(B) All monitor wells shall be cased and the annular space between the monitor zone (zone of saturation) and the surface shall be completely backfilled with Portland cement or an equivalent material and plugged with Portland cement to effectively prevent percolation of surface water into the well bore. The well opening at the surface shall have a removable cap to provide access and to prevent entrance of rainfall or stormwater runoff. The well shall be pumped to remove the volume of liquid initially contained in the well before obtaining a sample for analysis. The discharge shall be treated to meet applicable State or Federal discharge standards or recycled to the chemical waste landfill.

(iii) Water analysis. As a minimum, all samples shall be analyzed for the following parameters, and all data and records of the sampling and analysis shall be maintained as required in § 761.80(d)(1). Sampling methods and analytical procedures for these parameters shall comply with those specified

in 40 CFR Part 136 as amended in 41 FR 52779 on December 1, 1976.

(A) PCBs.

(B) pH.

(C) Specific conductance.

(D) Chlorinated organics.

(7) Leachate collection. A leachate collection monitoring system shall be installed above the chemical waste landfill. Leachate collection systems shall be monitored monthly for quantity and physicochemical characteristics of leachate produced. The leachate should be either treated to acceptable limits for discharge in accordance with a State or Federal permit or disposed of by another State or Federally approved method. Water analysis shall be conducted as provided in paragraph (b)(6)(iii) of this section. Acceptable leachate monitoring/collection systems shall be any of the following designs, unless a waiver is obtained pursuant to paragraph (c)(4) of this section.

(i) Simple leachate collection. This system consists of a gravity flow drainfield installed above the waste disposal facility liner. This design is recommended for use when semi-solid or leachable solid wastes are placed in a lined pit excavated into a relatively thick, unsaturated, homogenous layer of low permeability soil.

(ii) Compound leachate collection. This system consists of a gravity flow drainfield installed above the waste disposal facility liner and above a secondary installed liner. This design is recommended for use when semi-liquid or leachable solid wastes are placed in a lined pit excavated into relatively

permeable soil.

(iii) Suction lysimeters. This system consists of a network of porous ceramic cups connected by hoses/tubing to a vacuum pump. The porous ceramic cups or suction lysimeters are installed along the sides and under the bottom of the waste disposal facility liner. This type of system works best when installed in a relatively permeable unsaturated soil immediately adjacent to the bottom and/or sides of the disposal facility.

(8) Chemical waste landfill operations. (i) PCBs and PCB Items shall be placed in a landfill in a manner that will prevent damage to containers

or articles. Other wastes placed in the landfill that are not chemically compatible with PCBs and PCB Items including organic solvents shall be segregated from the PCBs throughout the waste handling and disposal process.

(ii) An operation plan shall be developed and submitted to the Regional Administrator for approval as required in paragraph (c) of this section. This plan shall include detailed explanations of the procedures to be used for recordkeeping, surface water handling procedures, excavation and backfilling, waste segregation burial coordinates. vehicle and equipment movement, use of roadways, leachate collection systems, sampling and monitoring procedures, monitoring wells, environmental emergency contingency plans, and security measures to protect against vandalism and unauthorized waste placements. EPA guidelines entitled "Thermal Processing and Land Disposal of Solid Waste" (39 FR 29337, Aug. 14. 1974) are a useful reference in preparation of this plan. If the facility is to be used to dispose of liquid wastes containing between 50 ppm and 500 ppm PCB, the operations plan must include procedures to determine that liquid PCBs to be disposed of at the landfill do not exceed 500 ppm PCB and meaures to prevent the migration of PCBs from the landfill. Bulk liquids not exceeding 500 ppm PCBs may be disposed of provided such waste is pretreated and/or stabilized (e.g., chemically fixed, evaporated, mixed with dry inert absorbant) to reduce its liquid content or increase its solid content so that a non-flowing consistency is achieved to eliminate the presence of free liquids prior to final disposal in a landfill. PCB Container of liquid PCBs with a concentration between 50 and 500 ppm PCB may be disposed of if each container is surrounded by an amount of inert sorbant material capable of absorbing all of the liquid contents of the container.

(iii) Ignitable wastes shall not be disposed of in chemical waste landfills. Liquid ignitable wastes are wastes that have a flash point less than 60 degrees C (140 degrees F) as determined by the following method or an equivalent method: Flash point of liquids shall be determined by a Pensky-Martens

Closed Cup Tester, using the protocol specified in ASTM Standard D-93-80, or the Setaflash Closed Tester using the protocol specified in ASTM Standard D-3278-78.

(iv) Records shall be maintained for all PCB disposal operations and shall include information on the PCB concentration in liquid wastes and the three dimensional burial coordinates for PCBs and PCB Items. Additional records shall be developed and maintained as required in § 761.80.

(9) Supporting facilities. (i) A six foot woven mesh fence, wall, or similar device shall be placed around the site to prevent unauthorized persons and animals from entering.

(ii) Roads shall be maintained to and within the site which are adequate to support the operation and maintenance of the site without causing safety or nuisance problems or hazardous conditions.

(iii) The site shall be operated and maintained in a manner to prevent safety problems or hazardous conditions resulting from spilled liquids and windblown materials.

(c) Approval of chemical waste landfills. Prior to the disposal of any PCBs and PCB Items in a chemical waste landfill, the owner or operator of the landfill shall receive written approval of the Agency Regional Administrator for the Region in which the landfill is located. The approval shall be obtained in the following manner:

(1) Initial report. The owner or operator shall submit to the Regional Administrator an initial report which contains:

(i) The location of the landfill:

(ii) A detailed description of the landfill including general site plans and design drawings;

(iii) An engineering report describing the manner is which the landfill complies with the requirements for chemical waste landfills specified in paragraph (b) of this section:

(iv) Sampling and monitoring equipment and facilities available;

(v) Expected waste volumes of PCBs: (vi) General description of waste materials other than PCBs that are ex-

pected to be disposed of in the landfill:
(vii) Landfill operations plan as required in paragraph (b) of this section:

(viii) Any local, State, or Federal permits or approvals; and

(ix) Any schedules or plans for complying with the approval requirements

of these regulations.

(2) Other information. In addition to the information contained in the report described in paragraph (c)(1) of this section, the Regional Administrator may require the owner or operator to submit any other information that the Regional Administrator finds to be reasonably necessary to determine whether a chemical waste landfill should be approved. Such other information shall be restricted to the types of information required in paragraphs (c)(1) (i) through (ix) of this section.

(3) Contents of approval. (i) Except as provided in paragraph (c)(4) of this section the Regional Administrator may not approve a chemical waste landfill for the disposal of PCBs and PCB Items, unless he finds that the landfill meets all of the requirements of paragraph (b) of this section.

(ii) In addition to the requirements of paragraph (b) of this section, the Regional Administrator may include in an approval any other requirements or provisions that the Regional Administrator finds are necessary to ensure that operation of the chemical waste landfill does not present an unreasonable risk of injury to health or the environment from PCBs. Such provisions may include a fixed period of time for which the approval is valid.

The approval may also include a stipulation that the operator of the chemical waste landfill report to the Regional Administrator any instance when PCBs are detectable during monitoring activities conducted pursuant to paragraph (b)(6) of this section.

(4) Waivers. An owner or operator of a chemical waste landfill may submit evidence to the Regional Administrator that operation of the landfill will not present an unreasonable risk of injury to health or the environment from PCBs when one or more of the requirements of paragraph (b) of this section are not met. On the basis of such evidence and any other available information, the Regional Administrator may in his discretion find that one or more of the requirements of paragraph (b) of this section is not neces-

sary to protect against such a risk and may waive the requirements in any approval for that landfill. Any finding and waiver under this paragraph will be stated in writing and included as part of the approval.

(5) Persons approved. Any approval will designate the persons who own and who are authorized to operate the chemical waste landfill, and will apply only to such persons, except as provided by paragraph (c)(7) of this section.

(6) Final approval. Approval of a chemical waste landfill will be in writing and will be signed by the Regional Administrator. The approval will state all requirements applicable to the ap-

proved landfill.

(7) Transfer of property. Any person who owns or operates an approved chemical waste landfill must notify EPA at least 30 days before transferring ownership in the property or transferring the right to conduct the chemical waste landfill operation. The transferor must also submit to EPA, at least 30 days before such transfer, a notarized affidavit signed by the transferee which states that the transferee will abide by the transferor's EPA chemical waste landfill approval. Within 30 days of receiving such notification and affidavit, EPA will issue an amended approval substituting the transferee's name for the transferor's name, or EPA may require the transferee to apply for a new chemical waste landfill approval. In the latter case, the transferee must abide by the transferor's EPA approval until EPA issues the new approval to the transferee.

[44 FR 31542, May 31, 1979, Redesignated at 47 FR 19527, May 6, 1982, and amended at 48 FR 5730, Feb. 8, 1983]

§ 761.79 Decontamination.

(a) Any PCB Container to be decontaminated shall be decontaminated by flushing the internal surfaces of the container three times with a solvent containing less than 50 ppm PCB. The solubility of PCBs in the solvent must be five percent or more by weight. Each rinse shall use a volume of the normal diluent equal to approximately ten (10) percent of the PCB Container capacity. The solvent may be reused for decontamination until it contains 50 ppm PCB. The solvent shall then be disposed of as a PCB in accordance with § 761.60(a). Non-liquid PCBs resulting from the decontamination procedures shall be disposed of in accordance with the provisions of § 761.60(a)(4).

(b) Movable equipment used in storage areas shall be decontaminated by swabbing surfaces that have contacted PCBs with a solvent meeting the criteria of paragraph (a) of this section.

Note: Precautionary measures should be taken to ensure that the solvent meets safety and health standards as required by applicable Federal regulations.

[44 FR 31542, May 31, 1979, Redesignated at 47 FR 19527, May 6, 1982]

Subparts E-I--[Reserved]

Subpart J-Records and Reports

§ 761.180 Records and monitoring.

(a) PCBs and PCB Items in service or projected for disposal. Beginning July 2, 1978, each owner or operator of a facility using or storing at one time at least 45 kilograms (99.4 pounds) of PCBs contained in PCB Container(s) or one or more PCB Transformers, or 50 or more PCB Large High or Low Voltage Capacitors shall develop and maintain records on the disposition of PCBs and PCB Items. These records shall form the basis of an annual document prepared for each facility by July 1 covering the previous calendar year. Owners or operators with one or more facilities that use or store PCBs and PCB Items in the quantities described above may maintain the records and documents at one of the facilities that is normally occupied for 8 hours a day, provided the identity of this facility is available at each facility using or storing PCBs and PCB Items. The records and documents shall be maintained for at least five years after the facility ceases using or storing PCBs and PCB Items in the prescribed quantities. The following information for each facility shall be included in the annual document:

(1) The dates when PCBs and PCB Items are removed from service, are

placed into storage for disposal, and are placed into transport for disposal. The quantities of the PCBs and PCB Items shall be indicated using the following breakdown:

(i) Total weight in kilograms of any PCBs and PCB Items in PCB Containers including the identification of container contents such as liquids and capacitors;

(ii) Total number of PCB Transformers and total weight in kilograms of any PCBs contained in the transformers; and

(iii) Total number of PCB Large High or Low Voltage Capacitors.

(2) For PCBs and PCB Items removed from service, the location of the initial disposal or storage facility and the name of the owner or operator of the facility.

(3) Total quantities of PCBs and PCB Items remaining in service at the end of the calendar year using the following breakdown:

(i) Total weight in kilograms of any PCBs and PCB Items in PCB Containers, including the identification of container contents such as liquids and capacitors;

(ii) Total number of PCB Transformers and total weight in kilograms of any PCBs contained in the transformers; and

(iii) Total number of PCB Large High or Low Voltage Capacitors.

(b) Disposal and storage facilities. Each owner or operator of a facility (including high efficiency boiler operations) used for the storage or disposal of PCBs and PCB Items shall by July 1, 1979 and each July 1 thereafter prepare and maintain a document that includes the information required in paragraph (b)(1) thru (4) of this section for PCBs and PCB Items that were handled at the facility during the previous calendar year. The document shall be retained at each facility for at least 5 years after the facility is no longer used for the storage or disposal of PCBs and PCB Items except that in the case of chemical waste landfills. the document shall be maintained at least 20 years after the chemical waste landfill is no longer used for the disposal of PCBs and PCB Items. The documents shall be available at the facility for inspection by authorized representatives of the Environmental Protection Agency. If the facility ceases to be used for PCB storage or disposal, the owner or operator of such facility shall notify within 60 days the EPA Regional Administrator of the region in which the facility is located that the facility has ceased storage or disposal operations. The notice shall specify where the documents that are required to be maintained by this paragraph are located. The following information shall be included in each document:

(1) The date when any PCBs and PCB Items were received by the facility during the previous calendar year for storage or disposal, and identification of the facility and the owner or operator of the facility from whom

the PCBs were received;

(2) The date when any PCBs and PCB Items were disposed of at the disposal facility or transferred to another disposal or storage facility, including the identification of the specific types of PCBs and PCB Items that were

stored or disposed of;

(3) A summary of the total weight in kilograms of PCBs and PCB Articles in containers and the total weight of PCBs contained in PCB Transformers, that have been handled at the facility during the previous calendar year. This summary shall provide totals of the above PCBs and PCB Items which have been:

(i) Received during the year;

(ii) Transferred to other facilities

during the year; and

(iii) Retained at the facility at the end of the year. In addition the contents of PCB Containers shall be identified. When PCB Containers and PCBs contained in a transformer are transferred to other storage or disposal facilities, the identification of the facility to which such PCBs and PCB Items were transferred shall be included in the document.

(4) Total number of any PCB Articles or PCB Equipment not in PCB Containers, received during the calendar year, transferred to other storage or disposal facilities during the calendar year, or remaining on the facility site at the end of the calendar year. The identification of the specific types of PCB Articles and PCB Equipment

received, transferred, or remaining on the facility site shall be indicated. When PCB Articles and PCB Equipment are transferred to other storage or disposal facilities, the identification of the facility to which the PCB Articles and PCB Equipment were transferred must be included.

NOTE: Any requirements for weights in kilograms of PCBs may be calculated values if the internal volume of containers and transformers is known and included in the reports, together with any assumptions on the density of the PCBs contained in the containers or transformers.

(c) Incineration facilities. Each owner or operator of a PCB incinerator facility shall collect and maintain for a period of 5 years from the date of collection the following information, in addition to the information required in paragraph (b) of this section:

(1) When PCBs are being incinerated, the following continuous and

short-interval data:

(i) Rate and quantity of PCBs fed to the combustion system as required in § 761.70(a)(3);

(ii) Temperature of the combustion process as required in § 761.70(a)(4);

(iii) Stack emission product to include O1, CO, and CO2 as required in § 761.70(a)(7).

(2) When PCBs are being incinerated, data and records on the monitoring of stack emissions as required in

§ 761.70(a)(6).

(3) Total weight in kilograms of any solid residues generated by the incineration of PCBs and PCB Items during the calendar year, the total weight in kilograms of any solid residues disposed of by the facility in chemical waste landfills, and the total weight in kilograms of any solid residues remaining on the facility site.

(4) When PCBs and PCB Items are being incinerated, additional periodic data shall be collected and maintained as specified by the Regional Administrator pursuant to \S 761.70(d)(4).

(5) Upon any suspension of the operation of any incinerator pursuant to § 761.70(a)(8), the owner or operator of such an incinerator shall prepare a document. The document shall, at a minimum, include the date and time

of the suspension and an explanation of the circumstances causing the suspension of operation. The document shall be sent to the appropriate Regional Administrator within 30 days of any such suspension.

(d) Chemical waste landfill facilities. Each owner or operator of a PCB chemical waste landfill facility shall collect and maintain until at least 20 years after the chemical waste landfill is no longer used for the disposal of PCBs the following information in addition to the information required in paragraph (b) of this section:

 Any water analysis obtained in compliance with § 761.75(b)(6)(iii); and

(2) Any operations records including burial coordinates of wastes obtained in compliance with § 761.75(b)(8)(ii).

(e) High efficiency boiler facilities. Each owner or operator of a high efficiency boiler used for the disposal of liquids between 50 and 500 ppm PCB shall collect and maintain for a period of 5 years the following information, in addition to the information required in paragraph (b) of this section:

(1) For each month PCBs are burned in the boiler the carbon monoxide and excess oxygen data required in § 761.60(a)(2)(iii)(A)(8) and § 761.60(a)(3)(iii)(A)(8);

(2) The quantity of PCBs burned each month as required in § 761.60(a)(2)(iii)(A)(7) and § 761.60(a)(3)(iii)(A)(7); and

(3) For each month PCBs (other than mineral oil dielectric fluid) are burned, chemical analysis data of the waste as required in § 761.60(a)(3) (iii)(B)(6).

(f) Retention of special records by storage and disposal facilities. In addition to the information required to be maintained under paragraphs (b), (c), (d) and (e) of this section, each owner or operator of a PCB storage or disposal facility (including high efficiency boiler operations) shall collect and maintain for the time period specified in paragraph (b) of this section the following data:

(1) All documents, correspondence, and data that have been provided to the owner or operator of the facility by any State or local government agency and that pertain to the storage

or disposal of PCBs and PCB Items the facility.

(2) All documents, correspondence and data that have been provided by the owner or operator of the facility to any State or local government agency and that pertain to the storagor disposal of PCBs and PCB Items at the facility.

(3) Any applications and related co respondence sent by the owner or of erator of the facility to any loca State, or Federal authorities in regar to waste water discharge permits, solwaste permits, building permits, cother permits or authorizations such as those required by §§ 761.70(d) ar 761.41(c).

[44 FR 31542, May 31, 1979, Redesignated 47 FR 19527, May 6, 1982, and 47 FR 3736 Aug. 25, 1982]

\$ 761.185 Certification program and rete tion of special records by persons ge erating PCBs in closed manufacturin processes and controlled waste man facturing processes.

(a) In addition to meeting the bas requirements of § 761.1(f), PCB-gene ating manufacturing processes shall the considered processed manufacturing processes or "controlled waste manufacturing processes" (and thus, be earlied from the TSCA section 66 ban on manufacture), only if the control of the manufacturing facility:

(1) Performs either a theoretic analysis of PCB levels in releases conducts actual sampling of PC levels in releases.

(2) Determines that the disposal facility is qualified for the disposal controlled wastes under § 761.3(m) (for controlled waste processes only).

(3) Maintains (for a period of 3 year after a process ceases operations or for years, whichever is shorter) record containing the following informatic on the processes:

(i) Theoretical analysis. (A) The raction or reactions believed to be producing the PCBs, the levels of PCB generated, and the levels of PCBs released.

(B) The basis for all estimations (PCB concentrations.

(C) The name and qualifications of the person or persons performing the theoretical analysis.

(ii) Actual monitoring. (A) The

method of analysis.

(B) The results of the analysis, including data from the Quality Assurance Plan.

(C) The name of the analyst or ana-

lvsts.

(D) The date and time of the analy-

(iii) Qualifications of the disposal facility. (A) The type of disposal facility.

(B) The name of the disposal facili-

(C) The location of the disposal facility.

(D) If the disposal facility is a RCRA-approved incinerator, the basis for the determination that the incinerator qualifies for the destruction of the PCB wastes to be destroyed.

(b) The data collected, and the analysis performed under paragraph (a) of this section must support the following certification if the processes are to be excluded under the closed manufacturing process and controlled waste manufacturing process exclusion. Persons desiring exclusion of a PCB-generating process under the closed and controlled waste process exclusion shall certify that:

(1) An analysis of the manufacturing process for PCB levels and releases (either theoretical or through actual monitoring for PCBs) has been com-

pleted.

(2) The analysis of the manufacturing process is on record at the facility.

(3) The concentration of PCBs in air emissions is below 10 micrograms per cubic meter per resolvable gas chromatographic peak: in water effluents, below 100 micrograms per liter per resolvable gas chromatographic peak; and in products, below 2 micrograms per gram per resolvable gas chromatographic peak.

(4) Either:

(i) The concentration of PCBs in process wastes is below 2 micrograms per gram resolvable gas chromatographic peak.

(ii) All process wastes are either incinerated in a qualified incinerator (see § 761.3(nn)), landfilled in a landfill approved under § 761.75, or stored

for such incineration or landfilling in accordance with the requirements of § 761.65(b)(1).

(c) The certification must be signed by a responsible corporate officer. This certification must be filed at each facility in which a closed or controlled waste process is operating for a period of three years after a process ceases operation or for seven years, whichever is shorter, and must be made available to EPA upon request. For the purpose of this section, a responsible corporate officer means:

(1) A president, secretary, treasurer, or vice president of the corporation in charge of a principal business function, or any other person who performs similar policy or decisionmaking functions for the corporation.

(2) The manager of one or more manufacturing, production, or operating facilities employing more than 250 persons or having gross annual sales or expenditures exceeding \$25,000,000 (in second quarter 1980 dollars), if authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures.

(d) This certification process must be repeated whenever process conditions are significantly modified to make the previous certification no longer valid. Significant modifications include changing disposal mechanisms or facilities for the disposal of controlled wastes.

(e) Any person signing a document under paragraph (b) (1) through (4) of this section shall also make the following certification:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate information. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for falsifying information, including the possibility of fines and imprisonment for knowing violations.

Dated: Signature - (f) Manufacturers operating closed and controlled waste manufacturing processes shall transmit a letter to EPA notifying EPA of:

(1) The number, the type, and the location of the closed and controlled waste manufacturing processes.

(2) Whether the determinations that the processes qualify for exclusion are based on theoretical assessments or on actual monitoring of PCB levels in releases.

(3) The type, the name, and the location of the waste disposal facility, if the process is a controlled waste manufacturing process.

[47 FR 46996, Oct. 21, 1982]

PART 762—FULLY HALOGENATED CHLOROFLUOROALKANES

Subpart A—General Provisions

Sec.

762.1 Scope.762.3 Definitions.

Subpart B-[Reserved]

Subpart C—Prohibitions, Exemptions, and Certification Requirements

762.45 Manufacturing.

762.50 Processing.

762.55 Distribution in commerce.

762.58 Essential use exemptions.

2.59 Special exemptions.

Subpart D—Records and Reports

762.60 General reporting requirements.
762.65 Manufacturers of fully halogenated chlorofluoroalkanes for aerosol propellant uses.

762.70 Processors of fully halogenated chlorofluoroalkanes for aerosol propellant uses.

AUTHORITY: Toxic Substances Control Act, 15 U.S.C. 2605, 2607, and 2611.

Source: 45 FR 43721, June 30, 1980, unless otherwise noted.

Subpart A—General Provisions

§ 762.1 Scope.

This part prohibits the manufacture, processing, and distribution in commerce of fully halogenated chlorofluoroalkanes for those aerosol propellant uses which are subject to the Toxic Substances Control Act (TSCA).

requires submission of annual reports and lists the exemptions to the prohibitions.

§ 762.3 Definitions.

For the purposes of this part:

(a) The term "aerosol propellant" means a liquefied or compressed gas in a container where the purpose of the liquefied or compressed gas is to expel from the container liquid or solid material different from the aerosol propellant.

(b) The term "person" includes any natural person. corporation, firm, company, joint venture, partnership, sole proprietorship, association, or any other business entity, any State or political sub-division thereof, any municipality, any interstate body and any department, agency, or instrumentality of the Federal Government.

(c) The term "nonconsumer article" means any article subject to TSCA which is not a "consumer product" within the meaning of the Consumer Product Safety Act (CPSA), 15 U.S.C. 2052.

(d) The terms "Administrator," "chemical substance," "commerce," "distribute in commerce," "manufacture," "process," "processor," "State," and "United States" have the same meanings as in 15 U.S.C. 2602.

Subpart B—[Reserved]

Subpart C—Prohibitions, Exemptions, and Certification Requirements

§ 762.45 Manufacturing.

(a) After October 15, 1978, no person may manufacture. except to import any fully halogenated chlorofluoroal-kane for any aerosol propellant use except as follows:

(1) For use in an article which is a food, food additive, drug, cosmetic, or device exempted under 15 U.S.C. 2602; or

(2) For those essential uses listed in § 762.58.

^{&#}x27;The Food and Drug Administration has promulgated separate regulations on use of fully halogenated chlorofluoroalkanes in these articles at 21 CFR 2.125.

MOSIGHWEDISON

To

Plant Managers

Date

August 14, 1985

From

Internal Correspondence

cc: W. Graessle

R. Barton

Regional Managers

William Kaikis

Subject

Service Group

Compliance with EPA Regulations Regarding Polychlorinated Biphenyls (PCBs)

The Spokane facility of the Service Division was recently the subject of an EPA inspection pertaining to compliance with the PCB regulations of the Toxic Substance Control Act (TSCA), 40 CFR Part 761 (attached). As a result of this inspection, penalties amounting to \$3825 were issued and collected for improper inspection of PCB Transformers (i.e., containing 500 parts per million PCB or greater), improper marking of said transformers, and failure to prepare an appropriate annual report regarding the inventory and disposition of PCB items. Furthermore, EPA stated that any similar violations occurring in other Service Division facilities could result in "repeat" violations, which may warrant even more stringent monetary penalties.

Based on the above information, it is imperative that you review your operations and insure that all PCB containing equipment comply with the TSCA regulations. In particular, insure that all transformers containing 500 parts per million (ppm) PCB or more are visually inspected at least once every three months if they are in use or stored for reuse. Records of this inspection and a maintenance history should be maintained for at least three (3) years after disposing of the transformer. In addition, insure that all PCB Containers, PCB Transformers, PCB Capacitors, electric motors containing PCB coolants, (hydraulic systems using PCB*), PCB article containers (as defined by the regulation) and all PCB and PCB item pre-disposal storage areas, are properly marked with the formal six (6) inch PCB mark illustrated in 40 CFR Part 761.45. Only if the equipment being marked is too small to accommodate the 6 inch mark may the smaller 2 inch mark be used. Finally, insure that all of the appropriate information, as described in 40 CFR 761.180 (a), is maintained on site and a formal annual report is maintained at your facility.

A brief summary of the PCB regulations is attached. If you have any questions, contact Mr. Michael J. O'Brien, Manager, Environmental Affairs at (713) 739-5612. Thank you for your cooperation in this matter.

William Karkers William Kaikis

WK:jh

att.

^{*}Effective July 2, 1984, the use of hydraulic systems containing greater than 50 parts per million PCBs is not authorized.



NATIONAL ELECTRIC COLL WORTHINGTON SERVICE

Service Group McGraw-Edison Company 941 Chatlam Level Post Otace Box 21590 Columbus, OH 43221

614 450 110. TV:X E5 61 1106.

Mr. D. Henry Elsen Assistant Regional Counsel U.S. Environmental Protection Agency Region 10 1200 Sixth Avenue Seattle, Washington 98101

August 15, 1985

Re: P.C.B. Complaint at Spokane Facility
Docket No. 1085-03-20-2615P

Dear Mr. Elsen:

Please find enclosed a copy of our letter which was sent to all locations within the McGraw-Edison Service Division advising compliance with EPA Regulations regarding Polychlorinated Biphenyls (PCBs)

I have included a copy of same for you to pass on to Mr. Gil Haselberger.

Very truly yours,

William Kaikis, Director Industrial Relations

WK:jh

enç.

AUG 1 © 1985

DEFICE OF RECONAL COUNSEL
EPA - REGION X

CERTIFIED MAIL 5186157
RETURN RECEIPT REQUESTED



HEASINES CLERK EPA-REGION &

Jico oirtoeje jakoitan Edivree notokihtrow

Environmental Protection Agency, Region 10 Regional Hearing Clerk P.O. Box 360903M Pittsburgh, Pennsylvania 15251 Service Group McGraw-Edison Company 941 Chatham Lane Post Office Box 21396 Columbus, OH 43221

July 15, 1985

614 459 1200 TWX 810 482 1634

Docket No. 1085-03-20-2615P

Dear Sir:

In compliance with the order dated June 20, 1985, enclosed please find McGraw-Edison Service's check in the amount of \$3,825.00 constituting payment in full of the stipulated penalty.

very truly yours,

William Kaikis, Director Industrial Relations

WK:jh

enc.

CC: Regional Hearing Clerk
Office of Regional Counsel
Environmental Protection Agency
1200 Sixth Avenue, M/S 613
Seattle, Washington 98101

J. Holm, Spokane

s. Waldbaum

PESTICIDES & TONIC SUBSTANCES BRANCH
EPA, REGION 10

DECEIVED

FPA REGION X

Voucher	Invoice	Purchase Order	Invoice Date	Amount	Discount	Net Amount
	Settlement o	E EPA	7/1/85	\$3,825.00		\$3,825.00
	25.	ţ 			F/F	tn 🗴
						2
0.9			•	=		
			¥			

:Graw-Edison Service rision of McGraw-Edison Company D. Box 21396 ilumbus, Ohio 43221

National Electric Coll Worthington Service

McGRAW+DISON 2000-615289

By

Date

Check No.

Amount

7/2/85

615289

\$3,825.00

*THREE THOUSAND EIGHT HUNDRED TWENTY-FIVE DOLLARS AND 00/100 CENTS

) the order of

United States Treasurer

McGraw-Edison Servica Division of McGraw-Edison Company P.O. Box 21396

Columbus, Ohio 43221

Vachovia Bank & Trust Company, N.A. Vinston-Salem, NC 27102 (b) (6)

National Electric Coll/Worthington Service

U.S. ENVIRONMENTAL PROTECTION DENCY

REGION X



1200 SIXTH AVENUE SEATTLE, WASHINGTON 98101

REPLY TO M/S 524

JUL 1 1 1985

William Kaikis, Director Industrial Relations McGraw-Edison Service Service Group P.O. Box 21396 Columbus, Ohio 43221

RE: Docket No. 1085-03-20-2615P

Dear Mr. Kaikis:

We have now had an opportunity to review the Annual Reports submitted for National Electric Coil, Spokane, Washington. The format of the reports is good and appears to have all of the required information. We would make the following suggestions:

- 1. PCBs and PCB Items disposed of in one year should not be carried over onto the Annual Reports for subsequent years. For example, the PCBs disposed of on June 10, 1982, do not need to appear on your 1983 and 1984 Annual Reports.
- 2. For the 55-gallon drum disposed of on January 30, 1984, the date removed from service and the date placed into storage are both listed as January 30, 1984. This seems unlikely, since you had submitted a Disposal Request to the Department of Environmental Quality on January 5, 1984. You must include all three dates on the Annual Report if they are different.

We have also reviewed your proposed memorandum to McGraw-Edison Service Division Plant Managers. We have indicated some changes and are enclosing this revised version for your use. For your information, I want to provide a little context for two of the changes. First, concerning Annual Reports, we wanted to stress that these reports are basically a "birth-to-death" document, and so must contain information on current inventory, as well as information on disposal activities, as outlined in 40 C.F.R. 761.180(a). Second, as a result of a prohibition effective July 2, 1984, if any of your facilities have hydraulic systems containing 50 parts per million PCB or greater, it is incumbent on you to immediately take steps to reduce the PCB concentration through retrofilling, followed up by retesting after three months of in-service use to verify that the systems contain less than 50 parts per million PCB. You may want to address this point in more detail in the memorandum or some subsequent communication to your plant managers since any current use of hydraulic systems above this concentration constitutes a violation of the regulations.

Generally speaking, the memorandum looks good, and we are satisfied with it as it now reads (aside from the point on hydraulic systems). Please send us a copy of the final memorandum and a list of the facilities it has been sent to.

If you have any future questions regarding this matter, please contact me (telephone (206)442-1094) or William Hedgebeth of my staff.

Sincerely,

Gil Haselberger, Chief Toxic Substances Section

Enclosure

cc: D. Henry Elsen/ORC

JUN 1 0 1915.

DATE:

June 13, 1985

TO:

All McGraw-Edison Service Division

YL

Plant Managers

FROM:

Bill Kaikis

RE:

Compliance with EPA Regulations Regarding Polychlorinated

Biphenyls (PCB's)

The Spokane facility of the Service Division was recently the subject of an EPA inspection pertaining to compliance with the PCB regulations of the Toxic Substance Control Act (TSCA), 40 CFR Part 761 (attached). As a result of this inspection, penalties amounting to \$3825 were located for improper inspection of (i.e., containing too pasts pen multin PCDn quarta)

PCB containing transformers, improper marking of said transformers and failure to inventory and prepare an appropriate annual report regarding the disposition of PCB items. Furthermore, EPA stated that any similar violations occurring in other Service Division facilities could result in "repeat" violations, which may warrant even more stringent monetary penalties.

Based on the above information, it is imperative that you review your operations and insure that all PCB containing equipment comply with the TSCA regulations. In particular, insure that all transformers containing 500 parts per million (ppm) PCB or more are visually inspected at least once every three months if they are in use or stored for reuse. Records of this inspection and a maintenance history should be maintained for at least three (3) years after disposing of the transformer. In addition, insure that all PCB Containers, PCB containing. Transformers, PCB Capacitors, electric motors containing PCB coolants, hydraulic systems using PCB,

effective July 2, 1984, the use of hydraulic systems containing greater than 50 parts per million PiBes not authorized. (This information should be included in your memorandum).

PCB article containers (as defined by the regulation) and all PCB and PCB item pre-disposal storage areas, are properly marked with the formal six (6) inch PCB mark illustrated in 40 CFR Part 761.45. Only if the equipment being marked is too small to accommodate the 6 inch mark may the smaller 2 inch mark be used. Finally, insure that all of the appropriate information, as described in 40 CFR 761.180 (a), is maintained on site and a formal annual report is maintained at your facility.

A brief summary of the PCB regulations is also attached. If you have any questions contact Mr. Michael J. O'Brien, Manager, Environmental Affairs at (713) 739-5612. Thank you for your cooperation in this matter.

Sincerely,

Bill Kaikis

MJ01/d/bs

Attachment

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
BEFORE THE REGIONAL ADMINISTRATOR
Region 10
Seattle, Washington

IN THE MATTER OF)	
)	Docket No. 1085-03-20-2615P
MCGRAW EDISON SERVICE)	
NATIONAL ELECTRIC COIL,)	CONSENT AGREEMENT
)	AND FINAL ORDER
	Respondent.)	
	•)	

This administrative proceeding for the assessment of civil penalties was initiated by complaint issued May 17, 1985, pursuant to Section 16(a) of the Toxic Substances Control Act (15 U.S.C. §2615(a)), hereinafter "TSCA."

After an informal telephone conference held on June 5, 1985, the following Consent Agreement has been entered into by McGraw Edison Company, McGraw Edison Service Division ("McGraw"), 1 and the Environmental Protection Agency ("EPA").

FINDINGS OF FACT

1. Three PCB transformers are maintained in active, in-service use by McGraw's Spokane facility, located at North 415 Fancher Road in Spokane, Washington.

At or near the time of the issuance of the complaint in this matter, McGraw Edison, Inc. was purchased by Cooper Industries of Houston, Texas. McGraw Edison, Inc. agrees and warrants that all obligations described in this agreement and order are binding upon this new owner.

CONSENT AGREEMENT AND FINAL ORDER - Page 1 of 4

Form CBD-183 12-8-76 DOJ

.

:

2

2.	No	quarterly inspections, as defined in 40 C.F.R.
§761.30(a)(1),	of	the three PCB Transformers described in paragraph 1 above
were performed	bу	McGraw between April 1 and June 30, 1984.

- 3. On August 3, 1984, the three PCB Transformers described in paragraph 1 above were not labeled with a six inch by six inch label, as required by 40 C.F.R. §761.40(a)(2), and described in 40 C.F.R. §761.45.
- 4. As of August 3, 1984, no annual reports were developed or maintained for the years of 1978-1983, for the facility described in paragraph 1 above, as the term "annual report" is defined in 40 C.F.R. §761.180(a).

CONCLUSIONS OF LAW

- 1. McGraw's activities, as stated in the Findings of Fact, constitute violations of Section 15 of TSCA, 15 U.S.C. §2614, and the following regulations:
 - a. 40 C.F.R. §761.30(a)(1) (use without quarterly inspections)
 - b. 40 C.F.R. §761.40(a)(2) (labeling)
 - c. 40 C.F.R. §761.180(a) (recordkeeping).

AGREEMENT

- EPA has jurisdiction pursuant to TSCA over respondent and this proceeding.
- 2. In full and complete settlement of this matter, including all counts and allegations contained in the Complaint, McGraw will do the following:
 - a. McGraw Edison Service Division will submit the annual reports for McGraw's Spokane facility (as described in Findings of Fact, paragraph 1) for the year 1983 to Mr. Bill Hedgebeth, EPA Region 10, 1200 Sixth Avenue, M/S 524, Seattle, Washington 98101. EPA will review the report for technical compliance with 40 C.F.R. §761.180(a)(1).

- McGraw will pay a civil penalty totalling Three Thousand Eight Hundred and Twenty-Five Dollars (\$3.825.00) to EPA. This amount represents the originally assessed penalty less a fifteen percent (15%) credit to McGraw for the "attitude" of McGraw, as provided in the TSCA penalty policy, 45 F.R. 59770 (Sept. 10, 1980). The attitude credit is given in recognition of the above-described activities, and McGraw's efforts to correct the violations described in this agreement.
- By agreement herein, McGraw waives its rights to a hearing on 3. the facts, and its right of appeal of the complaint or this agreement and order.

By:

McGraw Edison Service Division

McGraw Edison Co.

6/13/85 Dated:

D. Henry Elsen Assistant Regional Counsel Environmental Protection Agency

Region 10

28 CONSENT AGREEMENT AND FINAL ORDER - Page 3 of 4

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

1

2

4

5 6

7 8

9

10

11 12

13

14 15

16

17

18

19

20 21

22

23

24

25

26

27

28

<u>ORDER</u>

1. McGraw Edison Service Division, McGraw Edison Company shall pay the total of Three Thousand Eight Hundred and Twenty-Five Dollars (\$3,825.00) within thirty (30) days of the date of this ORDER.

Payment of this penalty shall be made by check payable to the United States Treasurer, remitted to the following:

Environmental Protection Agency, Region 10 (Regional Hearing Clerk)
P.O. Box 360903M
Pittsburgh, Pennsylvania 15251

with a copy to the

Regional Hearing Clerk Office of Regional Counsel Environmental Protection Agency 1200 Sixth Avenue, M/S 613 Seattle, Washington 98101

- 2. McGraw Edison Service Division, McGraw Edison Company shall submit any annual reports for the year 1983, as the term "annual reports" is defined by 40 C.F.R. §761.180(a), for its Spokane, Washington facility, to EPA, within thirty (30) days of the date of this ORDER.
- 3. McGraw Edison Service Division, McGraw Edison Company shall submit a draft of a letter advising other McGraw Edison Service Division facilities of the potential ramifications of liability for similar violations to EPA within thirty (30) days of the date of this ORDER. After the content of this letter is agreed upon between McGraw and EPA, McGraw will send this letter to its Service Division facilities which may use PCB Items or Transformers.

DATED this 30 day of June 1985.

ERNESTA B. BARNES

Regional Administrator

U.S. Environmental Protection Agency



NATIONAL ELECTRIC COIL WORTHINGTON SERVICE

Service Group McGraw-Edison Company 941 Chatham Lane Post Office Box 21396 Columbus, OH 43221

614 459 1200 TWX 810 482 1634

Mr. William Hedgebeth Environmental Protection Agency Region 10 1200 Sixth Avenue Seattle, Washington 98101

June 19, 1985

Re: Docket No. 1085-03-202615P

Dear Mr. Hedgebeth:

In accordance with our recent telephone conversation, I have enclosed copies of both the annual PCB reports and the quarterly transformer inspection reports from our Spokane facility. In our settlement conference, Mr. Elsen requested that I mail you copies of these reports for your files.

As you can see, these reports are in order and will be kept up to date hereafter. Mr. Jon Holmes, our Plant Manager at Spokane, will be responsible for maintaining and seeing that all PCB regulations are met.

I trust that you will find these records in order. It is my understanding that Mr. Elsen will be sending Mr. Waldbaum a settlement agreement on this matter.

Very truly yours,

William Kaikis, Director Industrial Relations

WK:jh

enc.

cc: J. Holmes

S. Waldbaum

DEGLIVED N JUN 24 1985

PESTICIDES & C SUBSTANCES DRANCH EPA, REGION 10

PESTICIDES & SUBSTANCES BRANCH

DECENVED SON

TRANSFORMER INSPECTION RECORD

Owner/User:

Mc Graw-Edison Service

Address:

N. 415 Fancher Road / Spokane, WA 99212

Transformer Location:

south east part of building

Date entered Plant or Storage:

unknown

Stock #

UNIT #

as marked, only ID

available Serial # unknown

Make

unknown

Voltage

unknown

Oil Capacity 476.19 kilograms

P.C.B. Concentration 58,100 P.P.M.

		- ;						P.P.M.
	Month	Year	Inspected BXP	Observe Leaks	If yes,	state size	and	
	June 30,	1981_	I martin	NO		periormed	7.00	1 .
	Sept.31,	1981_	2 mutis	NO			<i>(</i> *	
-	Dec. 31.	1981-	- I mentin	N.0			•	
	March 31	1982	& Martin	No		• • • •		• • • • •
	June 30,	1982_	I martin	No		·	*	
	Sept.30,	-	L Mitie	NO	0 2			
	Dec. 31,	1982_	L Maitin	NO	553	:		
			7.7					

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PFM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week. 2.
- All other PCB transformers must be inspected for leaks at least once every three months.
- Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following:
 - The location of each transformer subject to the program.
 - The date of each inspection and the name of the inspector.
 - All leaks observed.
 - A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

P.C.B. TRANSFORMER INSPECTION RECORD

Owner/User:

Stock # UNIT # 1

Address:

Serial #

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Concentration 58,100 P.P.M.


Month	Year	Inspected By	Observe Leaks	-	state size and performed		1.
June	198	8	_	• 13			,
Sept.	198			(6)		•	
Dec	198 -			·			• • • • •
March	30, 1985_	I mailin	NO				
June 30	1983_	L mater	No				<u> </u>
Sept.3	0, 1983_	L mathe	110	3 4			- 19
Dec.	0, 1983_	Lyjasten	NO		<u>.</u>		

INSPECTION PROCEDURE

- 1. PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

PESTICIDES & C SUBSTANCES BRANCH



TRANSFORMER INSPECTION RECORD

Own	er	/U:	se	r	:
~ W 1		, -		_	•

Stock # Unit # 1

Address:

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity 476.19 Kg.

P.C.B. Concentration 8/160 P.P.M.

Month	Year	Inspected By	Observe Leaks		state size	and	
June	198	·		•			
Sept.	198				20	₹.	*
				•	•	1.0	*****

·- Dec. --- 198 --

March 1984	In	NO	, p. 25			
June 1984		. (inspected &	Jarry M.	estin Inst o	radid)
Sept. 1984	IRB	NO		/ / / /		p ²
	ARB	NO				

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once 2. every three months.
- Any "moderate leak" discovered by the inspection must be repaired and 3. cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

PESTICIDES & SPESTANCES DRANCH

OBULLURED SOL

TRANSFORMER INSPECTION RECORD

Owner/User:

Stock # Unit # 1

Address:

Serial # no nameplate

cerknown

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Comcentration 8,100 P.P.M

Inspected Observe If yes, state size and Βv

Leaks service performed


January 3/,	1, 1985 & Benning 40	
February	198	
March 29	9 1985 & Welch No	
April	198	To the second se
May	198 198	
June	198	
July.	198	
August	198 198	
September	198	
October	198	
November	198	
December	198	

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once 2. every three months.
- Any "moderate leak" discovered by the inspection must be repaired and 3. cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of cransformer.

PESTICIDES & C SUBSTANCES BRANCH



P.C.B. TRANSFORMER INSPECTION RECORD

Owner/User:

Mc Graw-Edison Service

Address:

N. 415 Fancher Road Spokane, WA 99212 Transformer Location:

south-east part of building

Date entered Plant or Storage:

unknown

Stock #, UNIT # 2

as marked, only ID

Serial #

unknown

Make

unknown

Voltage unknown

Oil Capacity

. 476.19 kilograms

P.C.B. Concentration P.P.M

Month	Xear	Inspected By	Observe Leaks	If yes, state size and service performed		. 1
June 30	1981	L'Matin	No			
Sept. 31 ,	1981	L mati	NO		•	
 Dec. 31	- 1981 -	- I Mater	No		•	
 March 3	1.1982	L'Martin	No	20 1		
June 30	1982_	Matin	NO:	·		
Sept .30	, 198 ₂	& Martin	NO	F6 (6)		
Dec. 31	<u>.</u> 1982_	L martin	No			

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- 2. All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of

P.C.B. TRANSFORMER INSPECTION RECORD

Owner/User:

Stock # UNIT # 2

Address:

Serial # Linksmun

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity 476.19 Kg

P.C.B. Concentration 46,900 P.P.M.

Month	Äear	Inspected By	Observe Leaks	If yes, state size service performed	and	• •
June	198		-	• 95	43	53
Sept.	198			· .	•	V.
Dec	198 -			· · · · · · · · · · · · · · · · · · ·		
	;	Small		, x 650 40	- PSF -	

March 30,1983 & Matu

June 30, 1983 L Matin

Sept. 30, 1983 X


Dec. 30, 1983_

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once 2. every three months.
- Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

PESTICIDES & C SUBSTANCES BRANCH
OF HOMES, REGION TO



P.C.B. TRANSFORMER INSPECTION RECORD

	Owner/User:			Sto					
	Address:		Serial # unknown.				*.5		
	Transformer	Location:		Ma	ke	4	"		
	Date entered	Plant or Stor	Voltage		11				
			-	0i	l Capacity	4.76	5.19		
	*			P.	C.B. Cönce	ntrati	on	P.P.M.	
	Month Year	Inspected By	Observe Leaks		state siz			(E) 2.	
	June 198			•				1.	
	Sept. 198								
e	Dec 198				•• (2)-		.	1	
_	March 198	4 271	20	. A. A.			A	**	
	V.	,	/		1 10 1	47		、	

INSPECTION PROCEDURE

 PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.

ĸD

- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

PESTICIDES & C SUBSTANCES DANCH

DECENNED SSEI PS NOT

P.C.B. TRANSFORMER INSPECTION RECORD

Owner/User:

Stock # Unit # 2

Address:

Serial # no nameplate

Transformer Location:

Make known

Date entered Plant or Storage:

Voltage

Oil Capacity 476.19.

P.C.B. Concentration


Observe If yes, state size and Year Inspected Leaks service performed Βv January 31, 1985 February_ 198 March 291985 April 198 198 May June 198 198 July. 198 August September 198 198 October November 198 December 198

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once 2. every three months.
- Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following:
 - The location of each transformer subject to the program.
 - The date of each inspection and the name of the inspector. (B)
 - All leaks observed.
 - A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

PESTICIDES & C SUBSTANCES DRANCH



P.C.B. TRANSFORMER INSPECTION RECORD

Owner/User: | Mc Graw-Edison Service

Address: N. 415 Fancher Road

Spokane, WA 99212 Transformer Location:

south-east part of building
Date entered Plant or Storage:
unknown

Stock # UNIT # 3

as marked, only ID

Serial # wnknown

Make unknown

Voltage unknown

Oil Capacity 476.19 kilograms

P.C.B. Concentration 90,100 P.P.M.


Month	Xear	Inspected	Observe Leaks		state size performed	and	140	
June 30,	1981_	1 martin	No		, , , , , , , , , , , , , , , , , , , ,			
Sept.31,	1981_	I Martin	NO					
Dec. 31,	1981-	- I Muter.	NO.					•
March 31	,1982	1 mate	No		* 5. *	10	 :	
June 30,	1982_	L marin	No		•			
Sept.30,	1982_	I Mater	NO				 .	- 3
Dec. 31,	1982_	2 Maitin	NO	9.				

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- 2. All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of

PESTICIDES & C SUBSTANCES BRANCH



P.C.B. TRANSFORMER INSPECTION RECORD

Owner/User:

Stock # UNIT #3

Address:

Serial #

Transformer Location:

Make:

Date entered Plant or Storage:

Voltage

Oil Capacity 476.19 Kg

P.C.B. Concentration P.P.M.

Month	Xear	Inspected By	Observe Leaks	_	state size performed	and	
June	198	ts		•			*
Sept.	198	ė				*:	*** 30

Dec. ---- 198

June 30, 1983

Sept.30, 1983

Dec. 30, 1983

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once 2. every three months.
- Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following: 4.
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

P.C.B. TRANSFORMER INSPECTION RECORD

Owner/User:

Stock # Unit # 3

Address:

Serial # no nameplate

Transformer Location:

Make

unknown

Date entered Plant or Storage:

Voltage

Oil Capacity 476.19.

P.C.B. Concentration 90,100 p.p.M

Month	Year	Inspected By	Observe Leaks	state size	and	i. ji Tijo
January 3/	, 1985	Renner	-as			
February	198				10	
March 29	198 5	I wolf				
April 7	198_	0.				
May	198	16			-	
June	198			 1/3		
July _	198					
August	198					
September	198			 		
October	198					
November	198					
December_	198					

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

PESTICIDES & C SUBSTANCES BRANCH

OSCIPTIONS OF 1982

P.C.B. TRANSFORMER INSPECTION RECORD

	Own	er	/U	se	r	:
--	-----	----	----	----	---	---

Stock # Unit # 3

Address:

Serial # unknown

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity 4.76.19

P.C.B. Concentration P.P.M

93	Month	Äesi	Inspected Bv	Observe Leaks		state size performed	and	į.	•	
	June	198			•					Ŧ.,
	Sept.	198	v.					•		
•:•	Dec	198 -					-			
	March	198 4	IM	NO	. ÷: ·	84.9		• • • • • • • • • • • • • • • • • • •	• = •	
حــ	June	1984		P	4.025.000.000	•	-,		,	
	_Sept.	198 <u>4</u>	PRB	NO						
-	_Dec	_198 <u>-/</u>	JAB.	10		•	i.e			
		•	0							

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- 2. All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

PESTICIDES & C SUBSTANCES DRANCH


OBULL NUE

PCB ANNUAL REPORT for year ending Dec. 31, 1984

OUT OF SERVICE

Category	# Identification	Weight(kg)	Action*	Date
	2 ea. 55 gal drums (1 @ 57 gal=134	PPM) 414 kg.	R-S-T	6/10/82
PCBs or PCB Items in Containers	1 ea. 55 gal drum (1 @ 13 gal=80)	PPM) (total) 58.5 kg.	R-S-T	1/30/84
PCB Transformers	1 ea. (less than 1 P	PM) (of PCBs) N/A	R-S-T	6/10/82

PCB Large Capacitor



Identification
Chem-Security Systems, Inc.

Facility Location

Arlington, OR

Facility Owner/Operator

Mr. J. Craig McKenzie Gen. Mgr.

IN SERVICE

Category

PCBs or PCB Items in
Containers

PCB Transformers

Identification

(total)

(total)

(of PCBs)

1428.57 kg

PCB Large Capacitor

⁼ removed from service

⁼ placed into storage for disposal

⁼ transported to disposal

for year ending Dec 31, 19 83

OUT OF SERVICE

Category	#	Identification	Weight(kg)	Action*	Date
PCBs or PCB Items in Containers		2 ea. 55 gal. drums	414 kg . (92 gal) (total)	R-S-T	6/10/82
PCB Transformers		1 ealess than	n 1 ppm (of PCBs) N/A	R-S-T	6/10/82
PCB Large Capacitor		· · · · · · · ·	¹ .		V. **

MOITANITE (

Identification

CHEM-SECURITY SYSTEMS, INC

Facility Location

Arlington, OR

Facility Owner/Operator

Mr. J. Craig McKensie Gen. Mgr.

IN SERVICE

Category

PCBs or PCB Items in
Containers

(total)

B Transformers

3 ea.

Identification

(total)

(of PCBs)

1428.57 kg

PCB Large Capacitor

t = removed from service
5 = placed into storage for disposal

i = transported to disposal



PESTICIDES & C SUBSTANCES BRANCH EPA, REGION 10

for year ending Dec 31, 19 82

OUT OF SERVICE

Category #	Identification	Weight(kg)	Action*	Date
PCBs or PCB Items in Containers	2 ea. 55 gal. drums	414 kg (92 gal.) (total)	R-S-T	6/10/82
PCB Transformers	1 ea less than	1 plet PCBs) N/A	R-S-T	6/10/82
PCB Large Capacitor		 .		

<u>NOITANIT.</u>

IdentificationFacility LocationFacility Owner/OperatorCHEM-SECURITY SYSTEMS, INC.Arlington, ORMr. J. Craig McKenzie
Gen. Mgr.

IN SERVICE

Category	<u>#</u>	Identification	Weight(kg)
PCBs or PCB Items in Containers CB Transformers	3 ea.	333 KVA test transformers	(01 1 CD3)
PCB Large Capacitor			1428.57 kg

removed from service
 placed into storage for d

^{5 =} placed into storage for disposal F = transported to disposal

PCB ANNUAL REPORT for year ending Dec 31 . 19_81

į.	OUT OF SERVICE					• 12	.0
	Category	<u>#</u> Ident	ification	Weight(kg)		Action*	Date
	PCBs or PCB Items in Containers			(total)			
1	PCB Transformers	a		(of PCBs)			**
•	PCB Large Capacitor	V		_	5		4.1
2.	DESTINATION	#1 20					* 1.7.
	Identification		Facility	Location		Facility	Owner/Operator
•							
3.	II: SERVICE		4				\
. emi	Category	<u>#</u>	<u>Ide</u>	ntification		Weigh	t(kg)
0	PCBs or PCB Items in Containers			7	12	(te	otal)
	PCB Transformers	3 ea.	333 K	WA test transfor	rmers		CBs) -57 kg
	PCB Large Capacitor		* *	_			

*R = removed from service
S = placed into storage for disposal
T = transported to disposal



PESTICIDES & C SUBSTANCES DRANCH
EPA, REGION 10

PCB ANNUAL REPORT for year ending Dec 31, 19 80

•	OUT OF SERVICE					•	
	Category	# Iden	tification	Weight(kg)		Action*	Date
	PCBs or PCB Items in Containers	2.		(total)			
	PCB Transformers	25		(of PCBs)		ė	
)	PCB Large Capacitor		-	_	•:	21	
2.	DESTINATION	*	ie.				P. 15
	Identification	ä	Facili	ty Location		Facility Ow	vner/Operator
	er en						
3.	IN SERVICE		(2)	, x		ver to be office	- \
	Category	<u>#</u>	<u>1</u>	dentification		Weight(kg	<u>0</u>
)	PCBs or PCB Items in Containers					tota (tota	1) ==
	PCB Transformers	3 ea.	333	KVA test transfor	mers	(of PCB 1428.57	
	PCB Large Capacitor	31					

R = removed from service
S = placed into storage for disposal
T = transported to disposal

DECK 17 3 1985

PESTICIDES & SUBSTANCES BRANCH
EPA, REGION 10

PCB ANNUAL REPORT for year endingDec31_, 19 79


1.	OUT OF SERVICE					50	
	Category	<u>#</u> <u>Id</u>	entification	Weight(kg)	<u>Ac</u>	tion*	Date
	PCBs or PCB Items in Containers			(total)			
	PCB Transformers			(of PCBs)			
i. O	PCB Large Capacitor			- -;			
2.	DESTINATION						
Š.	Identification		Facili	ty Location		Facility Owner/C	Operator
•							
	*5	+					
ß.	IN SERVICE		÷			٨	
i	Category	<u>#</u>	<u>1</u>	dentification		Weight(kg)	
Ç	PCBs or PCB Items in Containers		5			(tota!)	•
	PCB Transformers	3 ea.	333	KVA test transformers		(of PCBs) 1428.57 kg	
	PCB Large Capacitor		4.				

R = removed from service
S = placed into storage for disposal
T = transported to disposal

PCB ANNUAL REPORT for year ending Dec 31, 19 78

- 1				
l	. OUT OF SERVICE			
	Category	# Identification	Weight(kg)	Action* Date
8	PCBs or PCB Items in Containers		(total)	
	PCB Transformers		(of PCBs)	
	PCB Large Capacitor	_	: :*:	
2	DESTINATION	3		
	Identification	12	Facility Location	Facility Owner/Operator
			*	
7				
3.	IN SERVICE		*1 35	V.
	Category	<u>#</u>	Identification	Weight(kg)
	PCBs or PCB Items in Containers			(total)
	PCB Transformers	3 ea.	333 KVA test transformers	(of PCBs) 1428.57 kg
	PCB Large Capacitor			
1.		•	<u>*</u>	57

^{*}R = removed from service \$ = placed into storage for disposal \$ T = transported to disposal



PESTICIDES & C SUBSTANCES BRANCH EPA, REGION 10 Notes on Settlement Conference: McGraw Edison Service, National Electric Coil, Spokane, Washington --- JUNE 5, 1985 - notes of William M. Hedgebeth

Mr.

(telephone conference call)

EPA employees present:

D. Henry Elsen, ORC, Attorney Gil Haselberger, Chief, Toxic Substances Section William Hedgebeth, Toxic Substances Section

McGraw Edison employees present

William Kaikas, Director, Industrial Relations, worldwide, Columbus, Ohio

Stanley Waldbaum, Divisional Counsel, Fairfield, New Jersey

Waldbaum - Kaikas communicated w/ plant regarding violations - re mitigating circumstances.

Kaikas - communication problem w/i organizations - policies not being communicated effectively - management changes made - plant not doing well - do want to comply w/ regs throughout organization.

Waldbaum - Quarterly Inspection penalty seems to be harsh for type of violation - did miss one quarter. Continued Q.I. afterwards as required - \$3,000 seems hard - no leakage, nothing improper.

Haselberger - explained penalty matrix.

Hedgebeth - Advise that Q.I. violation was use violation, not recordkeeping violation, that transformers could not be used w/o inspections' being performed.

Kaikas - aware of penalty matrix.

Waldbaum - violations now taken care of - Spokane facility cannot afford penalty.

Haselberger - asked what in procedures allowed Q.I. not to take place.

Waldbaum - plant manager switch. new manager not aware of need to remind one person - considering elimination of transformers whether through retrofill or otherwise (no current absolute intentions).

They (Waldbaum, Kaikas) were not aware of previous Notice of Warning.

Marking - No comment - corrected.

Page Two - Settlement Conference (TSCA) - McGraw Edison Service, Spokane, Washington - June 5, 1985

Annual Reports - No comment - reconstructed back to 1979 (will send to Hedgebeth).

Haselberger - advised that complaints at one facility of corporation could result in incremental penalties at other facilities where violations occurred.

McGraw Edison Service acquired by Cooper Industries - McGraw Edison does not now officially exist (although they still use name).

Spokane facility (electrical repair plant) \$875,000 income ('85) - \$5,000

(candidate for closing for some time now)
(penalty would not in itself be basis for closing per McGraw)

Conference (EPA)

offer 15% - good attitude and distribution of regs/blue/book/cover memo to 10-12 facilities on EPA concurrence.
\$3,825 after reduction

Return Call - Settlement offer to Bill Kaikas

15% reduction based on communication to facilities \$3,825 cash penalty

Kaikas said much distribution has already taken place.

Kaikas will submit draft letter for our review - also annual reports for review.

Henry will draft Consent Agreement and communicate w/ Stanley W.

U.S. ENVIR MENTAL PROTECTION ADENCY





1200 SIXTH AVENUE SEATTLE, WASHINGTON 98101

May 17, 1985

REPLY TO M/S 613

CERTIFIED MAIL - RETURNED RECEIPT REQUESTED

Jon Holm, Plant Manager McGraw Edison Service National Electric Coil P.O. Box 3505 T.A. Spokane, Washington 99220

Re: Docket No. 1085-03-20-2615P

Dear Mr. Holm:

Enclosed you will find a Complaint and Notice of Opportunity for Hearing and a copy of the Rules of Practice applicable to this proceeding. You are hereby advised to read this document carefully and communicate your answer within the time limit specified.

The Complaint alleges that your company, McGraw Edison Service, National Electric Coil, Spokane, Washington, violated quarterly inspection, marking, and records provisions of the PCB Regulations issued pursuant to the Toxic Substances Control Act. Accordingly, it is of considerable importance that you attend to this matter forthwith.

If you have any questions regarding this matter, contact D. Henry Elsen, Attorney, at the above address, Mail Stop 613, or telephone number (206) 442-1169.

Sincerely.

lan S. OTlent Gary L. O'Neal, Director Air and Toxics Division

Enclosures:

Regional Hearing Clerk cc:

D. Henry Elsen

John A. Foley, EPA Headquarters Anita Frankel, Air and Toxics Division

William Hedgebeth, Air and Toxics Division



PESTICIDES AND TOXIC SUBSTANCES BRANCH

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
BEFORE THE REGIONAL ADMINISTRATOR
Region 10
Seattle, Washington

In the Matter of
MCGRAW EDISON SERVICE
NATIONAL ELECTRIC COIL,
Respondent.

DOCKET NO. 1085-03-20-2615P

COMPLAINT AND NOTICE OF OPPORTUNITY FOR HEARING

I.

COMPLAINT

This is an administrative action instituted pursuant to Section 16(a) of the Toxic Substances Control Act [15 U.S.C. §2615(a)], hereinafter "the Act," for the assessment of a civil penalty and negotiation of a Consent Agreement and Final Order prescribing a corrective control program. The complainant is Region 10, United States Environmental Protection Agency, hereinafter "EPA." Complainant has reason to believe that the above-named respondent has violated Federal regulations addressing the use and/or disposal of polychlorinated biphenyls (PCBs) (40 C.F.R. Part 761 promulgated under Section 6 of the Act), and thereby has violated Section 15 of the Act, 15 U.S.C. §2614.

On August 3, 1984, an EPA inspection was performed at McGraw Edison Service, National Electric Coil, Spokane, Washington. The purpose of the inspection was to determine compliance with the Toxic Substances Control Act (TSCA) (15 U.S.C. §2601, et seq) and specifically the PCB regulations pursuant to 40 C.F.R. Part 761. The inspection disclosed the following violations:

I. Regulation - Quarterly Inspections

40 C.F.R. §761.30(a)(1) requires that owners of PCB Transformers in use or stored for reuse:

- visually inspect each PCB Transformer at least once every three months;
- record all leaks and conduct servicing within two business days from the date a moderate leak is observed; and
- maintain records of the inspections and servicing history.

The use of PCB Transformers and Capacitors, as outlined in 40 C.F.R. Part 761, is allowed only if the persons using that equipment comply with these steps.

Violation One

There were no quarterly inspections performed of three PCB Transformers in use by respondent during the quarter April-June 1984.

-

II. Regulation - Marking

40 C.F.R. §761.40(a)(2) requires that all PCB Transformers be marked in accordance with 40 C.F.R. §761.45. All marks must be placed in a position on the exterior of the PCB Item so that they can be easily read by any person inspecting or servicing the marked PCB Item.

Violation Two

The three PCB Transformers at your facility were not marked with the required six inch by six inch PCB label.

(Although the equipment did have three inch by three inch labels, such smaller labels are only allowed if the equipment is too small for the six inch by six inch label.

The transformers were of sufficient size as to readily accept the larger label.)

III. Regulation - Records & Monitoring

40 C.F.R. §761.180(a) requires that, beginning July 2, 1978, facilities using or storing at one time at least 45 kilograms (99.4 pounds) of PCBs contained in PCB Container(s) or one or more PCB Transformers or 50 or more PCB Large High or Low Voltage Capacitors develop and maintain records on the disposition of the PCBs and PCB Items. The records shall form the basis of an

annual document prepared by July 1, covering the previous calendar year. The annual document shall include:

a) The dates when PCBs and PCB Items are:
 i) removed from service.

ii) placed into storage for disposal,

iii) placed into transport for disposal; the quantities of PCBs and PCB Items removed from service including:

i) total weight in kilograms of PCBs contained in PCB Containers, with the identification of content in the containers.

ii) total number of PCB Transformers and total weight in kilograms of PCBs contained in the transformers.

iii) total number of PCB Large High or Low Voltage Capacitors;

- c) the location of the initial disposal or storage facility for PCBs and PCB Items removed from service:
- 2) Total quantities of PCBs and PCB Items remaining in service at the end of the calendar year, including:
 - a) total weight in kilograms of any PCBs and PCB Items in PCB Containers, with the identification of content in the container,
 - total number of PCB Transformers and total weight in kilograms of PCBs in the transformers,
 - total number of PCB Large High or Low Voltage Capacitors.

Violation Three

ь)

There were no Annual Reports for 1978-1983 at your facility. At the time of the EPA inspection, there were at least three PCB Transformers in service at your facility. In addition to information regarding these transformers, any 1982 Annual Report should include information regarding three PCB Items shipped to Chem Security Systems, Inc. on June 10, 1982.

28

GENERAL ALLEGATION REGARDING PRIOR VIOLATIONS

II.

This was the second violative TSCA PCB inspection performed by EPA at National Electric Coil in Spokane, Washington. The firm was first inspected on March 12, 1982. A "Notice of Warning" was issued on May 13, 1982, citing the following violations:

- 1. Records and Monitoring (No Annual Reports)
- Marking (PCB Container, storage for disposal area not marked).

PROPOSED CIVIL PENALTY

Section 16 of the Act, 15 U.S.C. §2615, and the regulations promulgated thereunder, 40 C.F.R. §761, et seq., authorize a civil penalty of up to \$25,000.00 per day for each violation of the Act. Based on the facts given in Section I above, the nature, circumstances, extent and gravity of the above-cited violations, as well as the respondent's ability to pay, effect on ability to do business, history of prior violations, and degree of culpability, the following penalties are hereby proposed:

	Regulation	Requirement	Penalty Amount
1. 2. 3.	40 C.F.R. §761.30 40 C.F.R. §761.40(a) 40 C.F.R. §761.180(a)	Quarterly Inspections Marking Annual Reports	\$3,000 \$ 500 \$1,000
		TOTAL	\$4,500

Payment of such penalty shall be by check made payable to the United States Treasurer, remitted to the following:

COMPLAINT AND NOTICE OF OPPORTUNITY FOR HEARING - 5

Form OBD-183 12-8-76 DOJ Environmental Protection Agency, Region 10 P.O. Box 360903M Pittsburgh, Pennsylvania 45251

with a copy sent to:

Regional Hearing Clerk Office of Regional Counsel Environmental Protection Agency 1200 Sixth Avenue, M/S 613 Seattle, Washington 98101

III.

SETTLEMENT CONFERENCE

Whether or not you request a hearing, you may confer informally with EPA concerning: (1) whether the alleged violations in fact occurred as set forth in Section I above, or (2) the appropriateness of the proposed penalty in relation to the size of business, the gravity of the violation and the effect of the proposed penalty on your ability to continue in business.

Although such informal conference concerning possible settlement does not affect the requirement to file a timely answer, the informal conference procedure may be pursued as an alternative to the adjudicatory hearing procedure if you notify this office of your desire to confer informally and if you schedule such conference prior to the expiration of the 20-day period.

proposed to be assessed to pursue the possibilities of settlement as a result of informal conferences. Any such settlement reached as a result of such informal conference shall be completed by the issuance of a written consent agreement and final order by the Regional Administrator, EPA, Region 10. The issuance of such a consent agreement shall constitute a waiver of your right to request a hearing on any matter stipulated to therein.

COMPLAINT AND NOTICE OF OPPORTUNITY FOR HEARING - 6

If you have not scheduled an informal settlement conference or have not requested a hearing within the 20-day period allowed by this notice, the above penalty may be imposed without further proceedings and you will be so notified.

If you wish to explore the possibility of settlement in this matter, please contact D. Henry Elsen, Attorney, at EPA, Office of Regional Counsel, 1200 Sixth Avenue, M/S 613, Seattle, Washington 98101, or by telephone at number (206) 442-1169.

IV.

OPPORTUNITY TO REQUEST A HEARING

A copy of the Consolidated Rules of Practice governing the administrative assessment of penalties under Section 14 of TSCA accompanies this Complaint. As provided by these rules, you have the right to request a hearing to contest any material fact set forth in the Complaint, or the appropriateness of the proposed penalty, or to contend that you are entitled to judgment as a matter of law. In the event that you wish to request a hearing and to avoid being found in default and having the above penalty assessed without further proceedings, it is incumbent upon you to file a written answer to this Complaint with the Region 10 Hearing Clerk, Office of Regional Counsel, EPA, 1200 Sixth Avenue, M/S 613, Seattle, Washington 98101. This written answer must be filed within twenty (20) days of your receipt of this Complaint.

1

Your answer should clearly and directly admit, deny or explain each of the factual allegations contained in the Complaint about which you have any knowledge. Said answer should contain: (1) a definitive statement of the facts which constitute the grounds of defense, and (2) a concise statement of the facts you intend to place at issue in the hearing.

If you fail to file a written request for a hearing or a written answer within 20 days of receipt of this Complaint, such failure shall constitute an admission of all the facts alleged in the Complaint and a waiver of your right to a hearing under TSCA [15 U.S.C. §2615(a)]. A final order upon default will thereafter be issued by the Regional Administrator and filed with the Region 10 Hearing Clerk, and the civil penalty proposed herein shall be imposed without further proceedings.

Any such hearing that you request will likely be held at the Region 10 office of EPA. Hearings held in the assessment of these civil penalties will be conducted in accordance with the provisions of the Administrative Procedure Act (5 U.S.C. §552, et seq.) and the Consolidated Rules of Practice Governing the Administrative Assessment of Civil Penalties and the Revocation or Suspension of Permits (40 C.F.R. Part 22, 45 Fed. Reg. 24,363).

> DATED this 17th day of May

Air and Toxics Division

24

25

26

27

28

ATES ENVIRONMENTAL PROTECTION AGENCY

JAN 29 1985 DATE:

SUBJECT: TSCA Referral for Administrative Civil Penalty: McGraw Edison Service, National Electric Coil, Spokane, Washington

FROM:

Anita J. Franke Pesticides and Toxic Substances Branch

James Moore, Regional Counsel

THRU:

Gary L. O'Neal, Director Law f. O'The Air and Toxics Division

On August 3, 1984, an EPA inspection was performed by Michael R. Hoyles at McGraw Edison Service, National Electric Coil, Spokane, Washington. The inspection was carried out to determine compliance with the PCB Regulations adopted by EPA pursuant to the Toxic Substances Control Act (TŠCA).

During the inspection, the following violations of the regulations were

Regulation - Quarterly Inspections

40 CFR 761.30(a)(1) requires that owners of PCB Transformers in use or stored for reuse:

- visually inspect each PCB Transformer at least once every three months:
- record all leaks and conduct servicing within two business ь) days from the date a moderate leak is observed; and
- maintain records of the inspections and servicing history.

The use of PCB Transformers and Capacitors, as outlined in 40 CFR Part 761, is allowed only if the persons using that equipment comply with these steps. A reduced visual inspection is required annually if containment equaling 100% of the liquid volume in the transformer is present.

Violation

There were no quarterly inspections performed of the three PCB Transformers during the quarter April-June 1984.

Regulation - Marking

40 CFR 761.40(a)(2) requires that all PCB Transformers be marked in accordance with 40 CFR 761.45 unless the equipment is too small to accommodate the 6 X 6 inch PCB label. All marks must be placed in a position on the exterior of the PCB Item so that they can be easily read by any person inspecting or servicing the marked PCB Item.

Violation

The three PCB Transformers at National Electric Coil were marked with three inch by three inch PCB labels but were not marked with the required six inch by six inch PCB label.

Regulation - Records & Monitoring

40 CFR 761.180(a) requires that facilities using or storing at one time at least 45 kilograms (99.4 pounds) of PCBs contained in PCB Container(s) or one or more PCB Transformers or 50 or more PCB Large High or Low Voltage Capacitors develop and maintain records on the disposition of the PCBs and PCB Items beginning July 2, 1978. The records shall form the basis of an annual document prepared by July 1, covering the previous calendar year. The annual document shall include:

- 1) a) The dates when PCBs and PCB Items are:
 - removed from service,
 - ii) placed into storage for disposal,
 - iii) placed into transport for disposal;
 - b) the quantities of PCBs and PCB Items removed from service including:
 - total weight in kilograms of PCBs contained in PCB Containers, with the identification of content in the containers,
 - total number of PCB Transformers and total weight in kilograms of PCBs contained in the transformers,
 - iii) total number of PCB Large High or Low Voltage Capacitors;
 - the location of the initial disposal or storage facility for PCBs and PCB Items removed from service;
- 2) Total quantities of PCBs and PCB Items remaining in service at the end of the calendar year, including:
 - total weight in kilograms of any PCBs and PCB Items in PCB Containers, with the identification of content in the container.
 - total number of PCB Transformers and total weight in kilograms of PCBs in the transformers,
 - c) total number of PCB Large High or Low Voltage Capacitors.

Violation

There were no Annual Reports for 1978-1983 at National Electric Coil. At the time of the EPA inspection, there were three PCB Transformers in service at National Electric Coil. In addition to information regarding these transformers, the 1982 Annual Report should include information regarding the three PCB Items shipped to Chem Security Systems, Inc. on June 10, 1982.

Compliance History

This is the second violative inspection performed at National Electric Coil in Spokane, Washington. The firm was first inspected on March 12, 1982. A "Notice of Warning" was issued on May 13, 1982, citing the following violations:

Records and Monitoring (there were no Annual Reports).

2. Marking (PCB Container, storage for disposal area not marked).

Request for Action

UNITED TATES ENVIRONMENTAL PROTECTION AGENCY

DATE: JAN 2 9 1985

SUBJECT:

PCB Civil Penalty Assessment Compiled in Conjunction with <u>Federal Register</u> Vol. 45, No. 177, September 10, 1980: McGraw Edison Service, National Electric Coil, Spokane, Washington

FROM:

Anita J. Frankel, Chief Pesticides and Toxic Substances Branch

TO:

James Moore, Regional Counsel

THRU:

Gary L. O'Neal, Director Sew L. O'Neal Air and Toxics Division

I. Description of Current Alleged Violations

A. Violation - Incomplete quarterly inspections (3 PCB

Transformers - 20% reduction - unknown gallonage)

Level - Two
Extent - Minor
Penalty - \$3,000

B. Violation - Marking - other than required label - (3 PCB

Transformers - 20 % reduction - unknown gallonage)

Level - Five Extent - Minor Penalty - \$ 500

C. Violation - No Annual Reports (at least 3 PCB Transformers -

20% reduction, unknown gallonage)

Level - Four Extent - Minor Penalty - \$1,000

II. Initial Penalty Assessment

	Regulation	Requirement		Penalty Amount
1. 2. 3.	761.30 761.40(a) 761.180(a)	Quarterly Inspections Marking Annual Reports	TOTAL	\$3,000 \$ 500 \$1,000 \$4,500

SENDER: Complete items 1, 2, 3 and 4. Form Put your address in the "RETURN TO" space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for service(s) requested. 1. Show to whom, date and address of delivery. 2. Restricted Delivery. JON HOLM, PLANT MANAGER

MC GRAW EDISON SERVICE

MATIL ELECTRIC COIL

PI BOX 3505 T.A.

SPOKANE, WA 99220 3. Article Addressed to: 4. Type of Service: Article Number p65262327 Registered
Contified
Express Mail ☐ Insured ☐ COD Always obtain signature of addressee or agent and DATE DELIVERED. DOMESTIC 7. Date of Delivery RETURN 8. Addressee s Address (ONLY if requested and fee paid) RECEIPT

P 652 623 274

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL

(See Reverse)

Street and No.	
P.S., State and ZIP Code	A 993
Postage	S
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to whom and Date Delivered	
Return receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	29/8

REGION X



1200 SIXTH AVENUE SEATTLE, WASHINGTON 98101

REPLY TO

M/S 524

CERTIFIED MAIL

JAN 29 1985

Jon Holm, Plant Manager McGraw Edison Service National Electric Coil P.O. Box 3505 T.A. Spokane, Washington 99220

Dear Mr. Holm:

On August 3, 1984, an inspection of McGraw Edison Service, National Electric Coil located at Spokane, Washington, was performed by Michael R. Hoyles of the United States Environmental Protection Agency (EPA) pursuant to Section 11 of the Toxic Substances Control Act (TSCA). This inspection was conducted to determine whether activities at the facility were in compliance with EPA regulations governing polychlorinated biphenyls (PCBs): 40 CFR Part 761.

A review of the results of that inspection has just been completed. On the basis of this review, it appears that certain violations of EPA regulations exist at the facility. They are as follows:

Regulation - Quarterly Inspections

40 CFR 761.30(a)(1) requires that owners of PCB Transformers in use or stored for reuse:

- a) visually inspect each PCB Transformer at least once every three months;
- b) record all leaks and conduct servicing within two business days from the date a moderate leak is observed; and
- c) maintain records of the inspections and servicing history.

The use of PCB Transformers and Capacitors, as outlined in 40 CFR Part 761, is allowed only if the persons using that equipment comply with these steps. A reduced visual inspection is required annually if containment equaling 100% of the liquid volume in the transformer is present.

Violation

There were no quarterly inspections performed of the three PCB Transformers during the quarter April-June 1984.

Regulation - Marking

40 CFR 761.40(a)(2) requires that all PCB Transformers be marked in accordance with 40 CFR 761.45 unless the equipment is too small to accommodate the 6 X 6 inch PCB label. All marks must be placed in a position on the exterior of the PCB Item so that they can be easily read by any person inspecting or servicing the marked PCB Item.

Violation

The three PCB Transformers at your facility were marked with three inch by three inch PCB labels but were not marked with the required six inch by six inch PCB label.

Regulation - Records & Monitoring

40 CFR 761.180(a) requires that facilities using or storing at one time at least 45 kilograms (99.4 pounds) of PCBs contained in PCB Container(s) or one or more PCB Transformers or 50 or more PCB Large High or Low Voltage Capacitors develop and maintain records on the disposition of the PCBs and PCB Items beginning July 2, 1978. The records shall form the basis of an annual document prepared by July 1, covering the previous calendar year. The annual document shall include:

- 1) a) The dates when PCBs and PCB Items are:
 - i) removed from service,
 - ii) placed into storage for disposal,
 - iii) placed into transport for disposal;
 - b) the quantities of PCBs and PCB Items removed from service including:
 - total weight in kilograms of PCBs contained in PCB Containers, with the identification of content in the containers,
 - ii) total number of PCB Transformers and total weight in kilograms of PCBs contained in the transformers,
 - iii) total number of PCB Large High or Low Voltage Capacitors:
 - Capacitors;
 the location of the initial disposal or storage facility for PCBs and PCB Items removed from service;
- 2) Total quantities of PCBs and PCB Items remaining in service at the end of the calendar year, including:
 - a) total weight in kilograms of any PCBs and PCB Items in PCB Containers, with the identification of content in the container.
 - total number of PCB Transformers and total weight in kilograms of PCBs in the transformers,
 - c) total number of PCB Large High or Low Voltage Capacitors.

Violation

There were no Annual Reports for 1978-1983 at your facility. At the time of the EPA inspection, there were three PCB Transformers in service at your facility. In addition to information regarding these transformers, the 1982 Annual Report should include information regarding the three PCB Items shipped to Chem Security Systems, Inc. on June 10, 1982.

The Agency believes that these conditions constitute a threat to human health and the environment. For this reason, it is recommended that you immediately take the following steps:

- 1. Conduct the required quarterly inspections of PCB Transformers and maintain records of such inspections.
- Label all PCB Transformers with the required six inch by six inch PCB label.
- 3. Develop the required Annual Reports. Reports for past years should be reconstructed from documentation on hand. These records should be a summary of all of the activity involving PCBs and PCB Items at National Electric Coil.

This is the second violative inspection that has been performed at your facility. National Electric Coil was inspected for compliance with the PCB Regulations on March 12, 1982, with violations noted in Recordkeeping and Marking. You should be advised that TSCA authorizes penalties of up to \$25,000 per day for each violation. Criminal penalties are authorized for knowing and willful violations of the law. Correcting the conditions noted in this letter may protect you from liability for future violations. However, it will not protect you from Agency enforcement action for those violations that have already occurred. Nothing in this letter should be construed to waive or limit any remedy available to the United States by virtue of conditions at your facility or the acts or omissions of your company. We are referring this case to EPA Region 10's Office of Regional Counsel for possible enforcement action. In this regard, you will be receiving further correspondence from this Agency in the near future.

Please understand that the aforementioned steps are being recommended to avoid risk to health and the environment. Your company bears the ultimate responsibility for taking all steps necessary to comply with the law. If you wish to discuss this letter or the PCB Regulations, please contact William Hedgebeth, EPA Region 10, 1200 6th Avenue, M/S 524, Seattle, Washington 98101; telephone (206) 442-8282..


Sincerely,

Anita J. Frankel, Chief

Pesticides and Toxic Substances Branch

Air and Toxics Division

+6







William M. Hedgebeth/EPS		
(Name & title of Evalua	tor)	ACTION TAKEN
TSCA X WAS AND THE STEP OF EVALUA		No Action Indicated
FIFRA	<u> </u>	Notice Noncompliance
McGraw Edison Service	Х	Refer for Ad. Civil Penalty
National Electric Coil P.O. Box 3505		Refer for Criminal Penalty
North 415 Fancher Road Spokane, Washington 99220		Refer to State
August 3, 1984	Micha	el R. Hoyles
Date of Inspection	Name of	Inspector
Comments:		15
Previous Compliance Activity:		4
3-12-82 - Inspected - EPA/TSCA/PCB 5-13-82 - Notice of Warning Issued: vic 1. Records (No Annual Repor 2. Marking (PCB Containers: 6-15-82 - Follow-up letter and not specific current Inspection:	rts) , s.f.d. ar ifically re	ea) sport to Notice of Noncomplian
Violation: No Annual Reports for 1978-8 f/ ancillary documents but P Violation: Quarterly Inspection of 3 PC April-June 1984 quarter Violation: 3 PCB Trans. marked w/ 3" X	nad not bee CB Trans. n	n prepared) ot performed in
Recommend referral to ORC for administrative action and their significance.	on due to r	epetition of violations
X.		e e
Concur VIL/85	Do not	Concur
FATES INSPECTION #	DATE ENTE	RED
CASE #	DATE ENTE	RED

	ENCY ACT Y	McGRAW EDISON SERVICE NATIONAL ELECTRIC COIL						
	N IDENTIFICATIO	N 2. Regio	n/Stete	12. Street TO A	304	7 5 6 5	·	
813184 3	P Number Daily Sec		<u> </u>	NORTH 415 FANCHER RO.				
C□ EX S□	act Number 5, Contr		GI.			INCHER	Ŋα.	
8. Facility Function 7. Invest US 61	Type 8. Resso	n for Investigation	10	13. City SPOK 1	ANE	14. State WA	15. ZIP Code 99220	
9, Referral Agency		ent Required M	0	16. DUNS Number 06 402 9		17. SIC Codes		
			MPLE IN	ORMATION				
18. Sample Sequence Numbe	r 19.5mm Dun	Sample Number		18. Sample Sequence Nu	mber .	19, State Sem	ple Number	
20, CAS Number	21. Proje	ct Code		20. CAS Number		21, Project Co	ode	
22. Semple Medium	23. Date	Collected		22. Sample Medium		23. Date Colle	ected	
24. Lot or Other Codes	25, Date	Shipped		24. Lot or Other Codes	•	25. Date Ship	ped	
26. Sample Identification				26. Sample Identification	1		~	
)								
				.7				
27. Amount Before Sampling		(8)		27. Amount Before Same	pling			
28. Sample Description				28. Sample Description				
2								
				ACILITIES				
29, Manufacturer/Processor (Other than aboye)			29. Manufacturer/Process	or (Other tha	n above)		
30. City	31. State	32, ZIP	Code	30. City		31, State	32, ZIP Code	
33. DUNS Number				33. DUNS Number				
			REC	ORDS				
34. Original Records				34. Original Records				
35. Sample Delivered To		36. Date	•	35. Sample Delivered To			36. Date	
37. Remarks		 -		37. Remerks	:			

. 95				Ŷ.				
•								
38. Credentials Presented 3	9. Notice of Inspection			DOCUMENTS	M2 0		42 Badansin -	
, , ,	. House of inspection	on 40. Natice of Confidentia	lity	41. Chain of Custody	42. Receipt 1 Documen		43. Declaration of Confidentiality	
	<u>````</u> \	Z	24				C C	
44. Inspector's Name		11 3		45. Inspector's Signature		967 ₁₈	1984	
[17] ₁	CHAEL R.	HOYLES	,	F	1709			

Mcgraw Edison Serivce National Electric Coil P.O. Box 3505 North 415 Fancher Road Spokane, Washington 99220

August 3, 1984

Michael R. Hoyles Environmental Protection Specialist

Compliance History:

On March 12, 1982 an EPA inspection found no documentation of PCB contaminated waste oil located at the facility. Also neither the barrel containing this liquid nor the location of the barrel was properly labeled. Further, no annual reports were being maintained on PCB items. A "Notice of Warning" was sent by certified mail on May 13, 1982 outlining these deficiencies.

Pre-Inspection Conference:

I arrived at 10:30 a.m. and asked to see the individual responsible for PCB's. I was told that he, Jon Holm, was sick. I indicated I needed to see the records anyway and was directed to Shirley Dubuque in Purchasing. I presented my credentials and filled out a "Notice of Inspection" and gave her the front page. I also filled out, had her sign, and gave her the first page of the "TSCA Inspection Confidentiality Notice." I explained the purpose of my visit and asked to see her PCB records. She had correspondence files for 1982 and 1983. She also had some documents for 1984.

Record Review:

The only annual report as such is the "PCB Transformer Inspection Record" for each of the three PCB transformers in service. No identification such as brand name, serial number, voltage, or capacity were on the records. There are, however, National Electric Coil inventory numbers. The PCB concentration is recorded but no concentration of kilograms PCB is present.

All three units have been, according to the record, inspected each quarter, from the second quarter of 1981 to and including the first quarter in 1984 (March). None of the units have been inspected since March 1984. The month, day and year are indicated for inspections, except March 1984 when no day was recorded. Shirley indicated she has had a lot of medical problems and has missed a lot of work. She has reminders on her calendar for these inspections. Since she was not there, the inspector was not alerted to do it last quarter.

Three PCB items were shipped to Chem-Security Systems, Incorporated on 6/10/82, consisting of two 55 gallon drums (total of 92 gallons of fluid) and a transformer casing. This includes the 134 ppm PCB's referenced in the "Notice of Warning". No reference other than the shipping manifest is in their files.

In 1983 a total of 11 items were sampled and the samples were sent to the company's lab in Franksville, Wisconsin for analysis. The results (received August 17, 1983) showed alluthe three units had less than 3 ppm, with 5 units less than 1 ppm. The three PCB items are the transformers still in service. According to the results these are 2300 V MTC transformers.

On January 30, 1984 a 55-gallon drum was shipped to Chem-Security Systems, Inc., containing 13 gallons of PCB from a transformer "discovered" on the company's property. The shipping manifest and disposal request are attached. Other records indicate this liquid had 80 ppm PCB. I asked about the casing and was told after the liquid had been drained it was steam cleaned and is now being used as a temporary storage vessel for non PCB oil. I asked how it was cleaned and Shirley thought a solvent was used to rinse prior to steam-cleaning and spent solvents went with the liquids to Arlington, Oregon.

Shirley brought to my attention a drastic difference in EPA sample testing results and that from a private testing facility. In the last inspection by EPA (Michael Watson - March 12, 1981) a PCB sample was taken and found to contain 134 ppm PCB by the EPA laboratories. The company also had the liquid tested and found it to be less than 3 ppm!! The lab results are attached. Shirley said that when the sample was taken by Michael Watson, no trichlorobenzene smell was evident to the owner, hence, he ordered his own testing. I was unable to determine if a split sample was used or not.

Inspection of Facility:

I asked to see the transformers and other PCB items on the property. The three PCB transformers are located on a wall about 15 feet above the floor. The PCB labels could be seen from the ground. I asked that a ladder be provided and climbed up to the units. No leaking was apparent. The PCB labels are not six inches on the side but three inches long and wide. Also, the manufacturer's identification plates are not on the units. I asked about that and Shirley said they have "always" been missing. They didn't know they were PCB's until they were tested in 1983.

The units are sitting on girders, one of which is located under the drain valves of the units. No liquid or discoloration was evident on this girder. If there was a small drip from the valve it would land on the girder rather than fall to the floor below. Leaks from other locations on the transformers could drip directly to the floor below. I took two pictures that depict the three transformers.

Sample colection:

There were no samples taken during this inspection.

Closing Discussion:

I told Shirley they needed an annual report that gave the number of PCB items, the kilograms PCB, and references to the PCB's shipped off. I reviewed with her a "Notice of Warning" from EPA dated May 13, 1982, which deliniated these requirements. I told her that if any of the three PCB units started to leak she should take the proper action. I left it to her to learn what that was.



United States Environmental Protection Agency Region 10 I200 Sixth Avenue Seattle WA 98101

Toxic Substances Control Act: Notice of Inspection

Name & Address of Firm:	Date of Inspection:			
by the comprehensive but there's the property of	and the second second of the s			
A Company of the property of the second	Hour:			
A STATE OF A STATE OF THE STATE	Thus,			
Company of the same of the property of the same of the	/ Compression Services			
<u>ार्ग होतु स्कृतिकार के का विश्वविद्यालिक कहा अर्था हो व स्वर्ध का प्रकार पर स्वर्ध है.</u>				
Reason for Inspection:				
For the purpose of inspecting (including taking samp	oles, photographs and other inspection activities) premises			
in which chemical substances or mixtures or articles	containing same are manufactured, processed, or stored,			
or held before or after their distribution in commerce	(including records, files, papers, processes, controls, and e Act applicable to the chemical substances, mixtures or			
articles within or associated with such premises have	heen complied with			
	the state of the s			
☐ For the purpose of inspecting (including taking samp	oles, photographs and other inspection activities) con-			
veyances used to transport chemical substances, mix	ctures, or articles containing same in connection with their			
distribution in commerce (including records, files, pa	pers, processes, controls and facilities, bearing on le chemical substances, mixtures or articles within or			
associated with the conveyances have been complied	d with.			
additional with the conveyances have been complete	in a standard and the second and a second and the s			
 In addition, this inspection extends to (circle appropriate) 	riate letters):			
	unt almar juli antitrateg tammino brug itahir siloat sui antanceg (iti.			
B) Sales Data	e care satisfies as outpring it so information of feature a			
C) Pricing Data D) Personnel Data				
E) Research Data				
The nature and extent of the data to be inspected as	s specified in A through E above is as follows:			
The hadro and extent or the data to be inspected as				
	Signature of EPA Inspector			
Name of Person to Whom Notice of Inspection Was Delivered:	Signature of ECA hispector			

Title

Title & Date



Region 10 I200 Sixth Avenue Seattle WA 98101

TSCA Inspection Confidentiality Notice

Facility Name & Address	This Notice Given To
Ma 6 20 PUMON TE VICE	Name: THIRLEY DUBUGUE
WATTONIAL ELECTRIC COL	
NAME TOUCHER TO	Title: PUPCENING
N 6 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
Name and Address of Chief Officer of Business:	Date This Notice Mailed To Chief Officer of Business:
JENN JON HOLIN	
PO 60X 3101	
SPEKENE JULY 99220	
Inspection Date:	Name of Inspector:
DUGUST 3,1784	MICHIEL 2 HOYCES
	MILLIAN CONTRACTOR

It is possible that EPA will receive public requests for release of data and/or documents obtained by inspectors during inspection of the facility indicated above. Such requests will be handled by EPA in accordance with provisions of the Freedom of Information Act (FOIA), 5 U.S.C. 522, EPA regulations issued thereunder, 40 CFR Part 2, and the Toxic Substances Control Act Section 14. EPA is required to make documents available in response to FOIA requests unless the Administrator of the agency determines that the data or documents are exempt from disclosure.

Please provide us with a statement specifying any information obtained during our inspection you believe should be exempt from disclosure. This will facilitate the Agency's timely response to any public inquiries, and evaluation of your company's claim of confidentiality.

Your statement should be addressed to: Document Control Officer, Pesticides & Toxic Substances Branch, M/S 524, U.S. Environmental Protection Agency, 1200 Sixth Avenue, Seattle, Washington 98101, and should reach this address no later than 7 days after your receipt of this notice. Failure to submit a written request that specified information be characterized as confidential, privileged, or exempt from disclosure within 7 days will be treated by EPA as a waiver of your claims for confidentiality regarding the inspection data. Any non-exempt data may be made available to the public without further notice to you.

Date Received by Facility

Signature of Plant Representative

Owner/User:

Stock # UNIT # 1

Address:

Serial #

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Concentration 58,100 P.P.M.

	Month	Year	Inspected By	Observe Leaks	If yes, state size service performed		2 · · · · · · · · · · · · · · · · · · ·	1
	June 30,	1981	L'martin	NO				-
	Sept.31,	1981	& martin	NO		948		.00
	Dec. 31.	1981	- I minten	NO				
	March 31	1982	& Martin	NO	100 to 10	.0	· · · · · · · · · · · · · · · · · · ·	ï
	June 30,	1982	1 martin	No			= 11	
	Sept.30,	1982	I Mitin	NO	l a se			•
·	Dec. 31,	1982	I Maitin	NO				

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer

TRANSFORMER INSPECTION RECORD

Owner/User:

Stock # UNIT # 1

Address:

Serial #

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Concentration 58,100p

÷	Month	Year	Inspected By	Observe Leaks		state size performed	and
	June	198	3				E
	Sept.	198			. ·		***
• ' •	Dec	198 -		· -	*: *:***		

March 30,1983

June 30, 1983

Sept. 30, 1983 C

Dec. 70, 1983

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and l. PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM (PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- Any "moderate leak" discovered by the inspection must be repaired and 3. cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - The date of each inspection and the name of the inspector. (B)
 - (C) All leaks observed.
 - A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

Owner/User:

Address:

Serial #

Transformer Location:

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Concentration --- P.P.M.

	Month	Year	Inspected By	Observe Leaks	If yes, state s			#*
	June	198	*					iv 5
	Sept.	198			<i>:</i>		•	4
•	Dec	198 -		100	·		·	- 1
	March	1984	Im	NO	. 15 IS	•		
	June	1984	7-1-1-m-y		(A) 95 · · · · · · · · · · · · · · · · · ·	,	М	8 g
_	Sept.	1984			. See			· 8
	Dec.	1984			×	0.412		

INSPECTION PROCEDURE

- 1. PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

Owner,	/User:
--------	--------

Stock #, UNIT # 2

Address:

Serial #

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Concentration P.P.M.

Month	Year	Inspected ∧By	Observe Leaks	If yes, state siz		
June 30,	1981	1 martin	No			
Sept.31,	1981_	2 mati	NO		61	363
Dec. 31.	1981-	I Martin	No			****
 March 31	1982	L'Martin	NO	* * * * * * * * * * * * * * * * * * *		
June 30.	1982_	Mulin	NO	*	fs.	* g
Sept. 30 ,	1982_	L Martin	NO			
Dec. 31,	1982	1 martin	No	*		

INSPECTION PROCEDURE

- 1. PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer

TRANSFORMER INSPECTION RECORD

Owner/	Us	e	r	:
--------	----	---	---	---

Stock # UNIT # 2

Address:

Serial #

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Concentration 46,900 P.P.M.

Month	Year	Inspected By	Observe Leaks		state size	and	5
June	198			•			Ž.
Sept.	198			<i>:</i>			7
Dec	- 198		147				

June 30, 1983

Sept. 30, 1983

Dec. 30, 1983

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- Any "moderate leak" discovered by the inspection must be repaired and 3. cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

Owner/User: Stock #

Address: Serial #

Transformer Location: Make

Date entered Plant or Storage: Voltage

Oil Capacity

P.C.B. Concentration --- P.P.M.

	Month	Year	Inspected By	Observe Leaks	If yes, sta service per		đ	17677 36 - 36 36 - 36
	June	198	19					1.5
	Sept.	198			2	*		
-	Dec	- 198						-1,-1
	March	1984	201	NO	, t	59	0	8.48
	June	1984		:	0 S •	2/		
: ::	Sept.	1984						
	 Dec.	1984	41		9			

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

Owner/User:

Stock # UNIT # 3

Address:

Serial #

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Concentration 90,100 P.P.M.

Month Year Inspected Observe If yes, state size and Leaks service performed June 30, 1981 No Sept.31, 1981 NO NO .. Dec. 31, 1981 NO March 31,1982 110 June 30, 1982 Sept.30, 1982 NO Dec. 31, 1982 NO

INSPECTION PROCEDURE

- PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

TRANSFORMER INSPECTION RECORD

Owner/User:

Stock # UNIT # 3

Address:

Serial #

Transformer Location:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity

P.C.B. Concentration 90,100

Observe If yes, state size and Month Year Inspected Leaks service performed By 198 June 198 Sept.

Dec. ---- 198

March 30,1983

June 30, 1983

NO

Sept.30, 1983

Dec. 30, 1983

INSPECTION PROCEDURE

- ı. PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- Records must be kept of the following:
 - The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.

Stock #

Address:

Serial #

Transformer Location:

cation:

Make

Date entered Plant or Storage:

Voltage

Oil Capacity


P.C.B. Concentration - P.P.M.

	Month	Year	Inspected By	Observe Leaks	If yes, state size service performed		1. A
	June	198	1				((f) -(7)
	Sept.	198				,	2.0
-	Dec	- 198		#		<u>.</u>	
	March	1984	Im	NO		55	
-	June	1984		•	E 90		
	Sept.	1984	Andrews with the second second		* **		70
	Dec.	198 🗸	×		*		

INSPECTION PROCEDURE

- 1. PCB Transformers (those that contain 500 PPM PCB'S or greater) and PCB-contaminated transformers (those that contain between 50 PPM and 500 PPM PCB'S) posing an exposure risk to food and feed products must be inspected for leaks once every week.
- All other PCB transformers must be inspected for leaks at least once every three months.
- 3. Any "moderate leak" discovered by the inspection must be repaired and cleaned or the transformer replaced beginning within 2 days from the time the leak is observed. Moderate leaks from transformers posing an exposure risk to food or feed products must be reported to the EPA within 5 days form the date the leak is observed.
- 4. Records must be kept of the following:
 - (A) The location of each transformer subject to the program.
 - (B) The date of each inspection and the name of the inspector.
 - (C) All leaks observed.
 - (D) A description of all servicing on the transformer after the date of the first inspection.

These records must be kept for a period of 3 years after disposing of transformer.



the state of the

National Electric Coil P.O. Box 3505 T.A. N. 415 Fancher Road Spokane, WA 99220 Att'n: John Holm

McGraw-Edison Company 11131 Adams Road Post Office Box 100 Franksville, WI 53126

Thomas A. Edison Technical Center

414 835 2921

August 10, 1983

REFERENCE: PCB in Oil Analysis ML 7-83-52

	Sample	1242 ppm	1254 ppm	1260 ppm	Total ppm
#1:	1;2300 V MTC			58,100	58,100 (5.81%)
#2:	75VK022003			Less	Less
#3:	2300 V MTC			Than 3 46,900	Than 3 46,900 (4,69%)
#4:	Job #16578			Less	Less
			- 91	Than 3	Than 3
#5:	3-3756-01936-29				
#6:	80 VH016009				
#7:	7309-601-3248				
#8:	2300 V MTC			90,100	90,100 (9.01%)
#9:	Serial #6177			Less	Less
				Than 3	Than 3
#10:	76VJ002001				
#11:	Oil Filter; 8/1/83			"	

- denotes less than the detection limit of 1 ppm.

* Results phoned to Smirley Dubuque on August 8, 1983 as requested.

Analysts:/

Smith/R. A. Harthun

Approved By: R. M. Frey

cc: G. Gauger

bc/216M



CHEMICAL TRANSPORTATION MANIFEST DESIGNATED TSD FACILITY CHEM-SECURITY SYSTEMS, INC. STAR ROUTE, ARLINGTON, OR. 97812

ARLINGTON (503) 454-2777 BELLEVUE (206) 827-0711 PORTLAND (503) 223-1912 VANCOUVER, B.C. (604) 669-2204

CS	SI EPAID NO. C	RD, 08	945-2353							
								EPA ID. NO		
ORIGIN ADDRESS N. 415 Fancher Road SPOKANE, WA 99206								PHONE 509-535-8751		
	BILLING ADDRESS P.O. BOX 3505 TA SPOKANE, WA 99220							PHONE		
Part Model of	SILLING ADDRE	30 <u></u> E	DOT REQUIRED INFORMATION		on a told up to	DEQ/EPA REQUIRED IN	FORMATION		974 CHI 2 CH	
Ç	CONTAINER PHYSIC						PHYSICAL		GAL./LB.	FT ³
QTY.	TYPE	НМ	DOT PROPER SHIPPING NAME	HAZARD CLASS	ID NO.	WASTE DESCRIPTION	STATE	WASTE NO.	GAL./ED.	
)	55 gl.drum	X RQ	Polychlorinated Biphenyl	ORM E	UN2315	1-55 gal size drum containing gallons of Polychlorinated Biphenol contaminated liquid (greater than 50 ppm and less than 500 ppm) (AND AND AND AND APPLICATION 1242-Aroclor 1260	liqůůd	none	13	7•5
SPECIAL Title to a acceptance recovery agreed in SPANER	L INSTRUCTIONS If materials furnishes of such materials I nor any credit for the writing by Chem-St. NAME (PLEASE P.)	d for di-	IN THE EVENT OF A SPILL, CONTA RESPONSE CENTER, U.S. COAST G spotal herein shall be deemed to be vested in Che n-Security Systems, Inc., from the generator or trans- tial value of any substances contained in such material Systems, Inc. Disposal operations by Chem-Security	REVENT FROM ENTER ACT EITHER OF THE CHEN UARD (800) 424-8802, OR (m-Security Systems, Inc., im sporter. The generator shall in the furnished for disposal, exce	A-SECURITY SYCONTACT, IN Contact, IN Contact, IN Contact, IN Contact and Indian	ANADA, TRANSPORT CANADA (613) 996-6666 FOR EMERICATION OF TRANSPORT CANADA (613) 996-6666 FOR EMERICATION OF THE STATE OF	rly classified, de ons of the U.S. t of the generato	y and the Online States to scribed, packaged, marke Department of Transport	nvironmental Protect d, labeled and are in p stion and the U.S. Er	ion Agency roper condi wironments
	ATOR SIGNATUR	E	Jon House			ADDRESS		EPA ID, N	0	
AD	ANSPORTER NO. 1. DRESS 2/42 ANSPORTER SIGNA	E E	enaly Solani WA	EPA ID. NO. (128 - 0) PHONE		ADDRESSSIGNATURE		PHONE_		
TR/	ANSPORTER NO. 2 DRESSANSPORTER SIGNA			EPA ID. NO		CSSI USE ONLY CSSI REQ. NOBILL OF LADING NO DISPOSAL AREASECTION	WEIC	GHT TICKET NO D DEPTH_	GROSS	
TR	ANSPORTER NO. 3.			EPA ID. NO.	_	REC. BY CSSI	DAT	E	NET	
	DRESS			PHONE		COMMENTS				
TR	ANSPORTER SIGNA	TURE								



Department of Environmental Quality

522 S.W. FIFTH AVENUE, BOX 1760, PORTLAND, OREGON 97207 PHONE: (503) 229-5696

January 18, 1984

الألكاك كالآلا

Mr. J. Craig McKenzie, General Manager Chem-Security Systems, Inc. Star Route Arlington, OR 97812

Re: HW File 4.10 M

Dear Mr. McKenzie:

We have reviewed Disposal Request No. D44988, submitted with your January 5, 1984 letter.

WASTE SOURCE

McGraw Edison Service/National Electric Coil PO Box 3505TA Spokane, WA 99220

HATERIAL(S) REQUESTED FOR DISPOSAL

Quantity Hazard Process/Operation For Disposal Description Type Generating Waste Annual PCB-contaminated Toxic (T₁) Removal from service 1 drum

transformer fluid

HATERIAL(S) AUTHORIZED FOR DISPOSAL

Same as above

METHOD OF DISPOSAL

Stabilize, then dispose of stabilized waste in Trench 9 by Procedure 3.

Sincerely,

Eduardo G. Chiong Environmental Engineer Hazardous Waste Operations Solid Waste Division

EGC:c ZC1378 Enclosure

cc: Alex H. Koch, CSSI, Bellevue, WA Jon C. Holm, McGraw Edison Service/National Electric Coil ARLINGTON (503) 454-2777 BELLEVUE (206) 827-0711

PORTLAND (503) 223-1912 VANCOUVER, B.C. (604) 688-7612 42614

1	GENERATO	DR		11:0-	Can	11.6							
ORIGIN ADDRESS - N 415 FANCHEY Rd / Spokane, Wa. 99206									FIPLICA!				
	000: 2222 -0 15								PHONE				
40.50	BILLING ADDRE	20		pokane. Wa	1770			PHONE					
	CONTAINER		DOT REQUIRED INFORMATION		16	DEQ/EPA REQUIRED INFORMATION							
QT	Y. TYPE	НМ	DOT PROPER SHIPPING NAME	HAZARD CLASS	HAZ. MAT	WASTE DESCRIPTION	PHYSICAL STATE	EPA HAZ. WASTE NO.	GAL./LB.	FT ³			
1	signl ar	V	Polychlorum 201 Biphenois RQ	ORM E	นมรวบ	Polyculormater Bephanoi (134pp)	Toget	Not Applicable	379AL	7.5			
1	STSALER	1	HAZAKOLOS WASK, Invit nas	ORM E	NA 9, 89	1254 Arbeiter		/ "		(
7	MANIFEREN	シ	HARRING Wish, Lynd Nos	DRAM 5		LASS TOLAN IPPM POB, TAKE	50 11/11-1	Not Applicable	STEPH	7.5			
					14757	1254 Arodor	Sough My sed	not repositionite					
LABE	LING REQUIREMEN	ITS_	YOB / HATAI dires (1/5/5		PLACARDING REQUIREMENTS							
SPEC	AL INSTRUCTIONS	(HAN	DLING/EMERGENCY)										
recover	y nor any credit for the in writing by Chem-Se	potent curity S	sposal herein shall be deemed to be vested in Chen Security Systems, Inc., from the generator or transpital value of any substances contained in such materials Systems, Inc. Disposal operations by Chem-Security	JAKD (800) 424-8802, OK Con-Security Systems, Inc., importer. The generator shall his furnished for disposal, exce Systems, Inc., will be in a	mediately upon have no right to	STEMS OFFICES AND/OR CONTACT, IN THE UNITED STANADA, TRANSPORT CANADA (613) 996-6666 FOR EMER procedures approved by the Oregon Department of Enviorable This is to certify that the above named materials are propertion for transportation according to the applicable regulated Protection Agency. Signed and dated by the authorized agency.	RGENCY ASSISTANO ronmental Quality an	CE. d the United States Environ					
	R NAME (PLEASE PI			SHIPPING DATE 4	110/82	ALTERNATE DESIGNATED T/S/D FACILITY (IF ANY).							
	RATOR SIGNATUR		Jeff Herry			ADDRESS		EPA ID. NO		`			
	RANSPORTER NO. 1_	25	-/	PA ID. NO. (JAD) 05		INTERMEDIATE FACILITY		EPA ID. NO.					
/ \	DDRESS N/40	,		HONE 938-019	5	ADDRESS		PHONE					
	RANSPORTER SIGNA	TURE_	funially 0	ATE 6-10-82		SIGNATURE		DATE					
	RANSPORTER NO. 2_		EI	PA ID. NO		CSSI USE ONLY							
	DDRESS			HONE		CSSI REO. NOBILL OF LADING NO	WEIGHT	TICKET NO	GROSS				
	RANSPORTER SIGNAT RANSPORTER NO. 3	URE_		ATE		DISPOSAL AREASECTION	QUAD	DEPTH	TARE				
	DDRESS			PA ID. NO		REC. BY CSSI	DATE		NET				
	RANSPORTER SIGNAT	URE		10NE		COMMENTS							
		J.,,_	D.	ATE					,				
*		T/S	S/D RETURNS TO GENERATOR										

Purchase Order

WCPKVAL FRIZAN

Service Grd

McGraw-Edison Company National Electric Coll North 415 Fancher Road P.O. Box 3505 T.A. Spokane, Washington 99220 (509) 535-8751

Tax Certif. No. 409-019-844

Ship To: (Same as above unless noted below)

PURCHASE ORDER NO.

011 - 7372

HAVALES

SATURAL SE

THE ABOVE NUMBER MUST AP-PEAR ON ALL CORRESPONDENCE, INVOICES, BILL OF LADINGS; ETC.

DATE

To: MC GRAW EDISON

POWER SYSTEMS GROUP

DER DATE	DATE REQUIRED	TERMS	TAXS	STATUS	F.O.B.	FREIGH	TTERMS	SHIP VIA	THE HOTE	and the
			TAXABLE	NDN-TAX	DESTN. SP	The second secon	COLLECT DELIVERED	2011 113	17 (M) 17 (D)	PALE JUR 1
23/82	7/23//82	M.D. M. 122	X	THE	promise days	10.2		1000	The Party	
VENDO	R CODE	REQUISION N	UMBER		MARKINGS	- 1 	DIRECT INQUIRIES TO	1 1	CONFI	RMING
SINGSTAT L. P.		1.4	Vol	B so make	Automobile .			1 -13-	YES	- NO
					F.2. T	Gar	y /Shirley	1	XX	
C) OUAN	דוות אוויד	OUR PARTEN	(a) Train por	Prior	(10)	Martin Charge	QTV. 14	11013512.	1000	(9)0)=
			91			ELERDERELL BALL	SMSPER	- Frankling of A		
								a 1		
1.00	1 -	-17 -	+ a [rew	ha to	ated for	PCB content	1,	0.00	ea. //-	-20
	7 60.	OII S	mpre c	G 08 Le	Bred tor	POD CONCENT		0.00	68. (/	20
·							. 1 3.			
24-5		4 4 5				•••	100 100	* 1		
17532	The same					IN BIME WY	.			
2 2				7.		24/2/	١ د			
	n					WEDN.	1 54			
	24.	d Sala				· Cally	11			
×87					~ <	4/12/00				
					2 (5)		r.			- 1
1 _			4 - 5 - 7		2011/2/2		1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	1		* 10
				120	UN.					
_ -	2 2 12 12			10/1/	9					
			~ (P)	V/Zn						
260			[0]	4			T. Karasara		. 12	
1	3		5					1 V		X.
E 20				100				47		A
	4			(i) (i)				50 ,		
							1.2	4		
								18.	1.5	1.4
10.00									100	
									Section 1	
	100 11 10	200	ADIETE	TILIC A	OKNOWI EL	CMENT CODY AS	ID DETUDN		1707	The Section
2 3 3 4		CON	ULTELE	і ПІЗ А	CKINOWLEL	OGMENT COPY A	AD LEIOUN		8 15	
enter transport			eye. Oe	75.54.5		a marina	THE PERSON NAMED IN SOME		/	
SHIP	COMPLE	TE PAR	TIAL OF	N (DATE)	A Three	BALANCE, IF A	NY, WILL BE SHIP	PED (DAT	E)	
	D. A. Hall Co.	A	un needy.	dones l	7	tura e	in the secondary	Select 2011 1 11	His war Hg	EAC.
			1 m	1						
3										
				. 1						

JRM #50-00001 (REV. 9/80)

ONTACT (NAME)

ACKNOWLEDGMENT

PHONE AREA

SIGNED

FOR ADDITIONAL INFORMATION

MCGHAW LUISUN S.O. NONE ower Systems Group McGraw-Edison Company General Offices: Post Office Box 2850, Pittsburgh, PA 15230 46156 D 5000BC SHIP TO SOLD TO NATIONAL ELECTRIC COIL NATIONAL BLECTRIC COLL MS SHIRLEY DUBUQUE MS SHIRLEY DUBUQUE P O BOX 3505 TA P O BOX 3505 TA 99220 SPOKANE MA 99220 SPORANE WA TELD COPIES D MCSTRACK G GAUGER B CIZHOWSKI R FREY C BLAKELY

DATE 6/22/82

UNSHIPPED

ORDERED

OTY. SHIPPED

DEBIT

SEE FURTHER TERMS AND CONDITIONS ON REVERSE SIDE

MEMO NO. MEMO DATE MWD-07552 07/14/82

MONE

AMOUNT

THIS ADJUSTMENT APPLIES TO

INVOICE NO. INVOICE DATE

DATE SHIPPED

MCGRAW-EDISON COMPANY POWER SYSTEMS GROUP AND REMIT TO!

P O BOX 44147

UNIT PRICE*

SAN PRANCISCO CA94144

CUSTOMER ORDER CUST. ORD. DATE REQUISITION MARK PACKAGES C008 CODE PPD/COL. QUOTATION NO. INVOICE 3 BRANCH NAME BRANCH NO. FRANKSVILLE

DESCRIPTION

ONE UNKNOWN OIL SAMPLE FOR PCB ANALYSIS REPORT (ML 7-82-79) SENT TO SHIRLEY DUBUQUE

1 SAMPLE 0 \$40.00/SAMPLE

CATALOG NO.

\$ 40.00

\$40.00 NET DEBIT

Z=SHIPPING POINT S-OTHER S-ORD, & HAN, CHG.

MOTOR FRT. S-YOUR THUCK 2-U.P.S. 8-RAIL 3-PAR. POST 7-OTHER 4-OUR TRUCK

TERMS: NET 30 DAYS


*UNLESS OTHERWISE INDICATED PRICE IS PER EACH

cc: G. A. Gauger

/ac/587I

CC: Sill Lews





National Electric Coil P. O. Box 3505 TA Spokane, Washington 99220 Attn: Ms. Shirley Dubuque Thomas A. Edison Technical Center McGraw-Edison Company 11131 Adams Road Post Office Box 100 Franksville, WI 53126

414 835 2921

June 17, 1982

Re: PCB in Oil Analysis

ML 7-82-79

| 1242 | 1254 | 1260 | Total | | ppm | ppm | ppm | ppm | ppm | ppm | | ppm | ppm | | less | than 3 | than 3

- denotes less than the detection limit of 1 ppm


Analysts, G. C. Smith/R. A. Harthun

Approved by: R. M. Frey

cc: G. A. Gauger

/ac/587I

CC: Sill Lews



.91	
S From 3811, Car., 1980	 SENDER: Complete items 1, 2, 3, and 4. Add your address in the "RETURN TO" space on reverse.
8	(CONSULT POSTMASTER FOR FEES)
12	The following service is requested (check one).
0	Show to whom and date delivered
	Show to whom, date, and address of delivery
	2. RESTRICTED DELIVERY (The restricted delivery fee is charged in addition to the return receipt fee.)
	TOTAL S
MAILIS	National Electric Coil Spokane Service Coulon 45 N Fancher Rd., Spokano, WA 99220
꺆	4. TYPE OF SERVICE: ARTICLE NUMBER
CEINT.	AEGISTERED INSURED P363187928
51	(Always obtain signature of addressee or agent)
٩ſ	I have received the article described above.
ᇍ	SIGNATURE Addressee Authorized agent
2	D Campbell
200	DATE OF DELIVERY
34	/ W // W
RECEIPT, REGISTERED, INCLUDED AND CENTREED	ADDRESSEE'S ADDRESS (Only if requested)
200	7. UNABLE TO DELIVER BECAUSE: 24. EMPLOYER'S
L	
	Heclgebert
	()

P 363 187 928 RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED— NOT FOR INTERNATIONAL MAIL

(See Reverse)

National Elec Coil							
Spokane Service Center							
915 N. Fundhuld. Spokaw, W. 99							
Postage	s						
Certified Fee							
Special Defivery Fee							
Restricted Delivery Fee							
Return Receipt Showing to whom and Date Delivered							
Return Receipt Showing to whom, Date, and Address of Delivery							
TOTAL Postage and Fees	\$						
6-30-83	Ye. +						

PS Form 3800, Feb. 1982

U.S. ENVIR NTAL PROTECTION A





REGION X

1200 SIXTH AVENUE SEATTLE, WASHINGTON 98101

REPLY TO ATTN OF:

M/S 524

JUN 29 1983

Certified Mail

Annual PCB Reports for Calendar

Due Date: July 1, 1983

Bill N. Lewis, Plant Manager National Electric Coil Spokane Service Center 415 N. Fancher road Spokane, Washington 99220

Dear Mr. Lewis:

By means of this letter, EPA Region 10 is reminding Region 10 facilities which we believe may have handled PCB items during the calendar year 1982, that 40 CFR section 761.180 requires that the annual report for that site be available there beginning July 1, 1983. Our inspectors will begin inspecting facilities for compliance with this annual report requirement by visits beginning in July. Please notice that under 15 U.S.C. section 2615 administrative civil penalties can be assessed up to \$25,000 per day for each day the annual report requirement is violated. Also notice that the reports must be complete and accurate or a reporting entity could be subject to criminal statutes such as 18 U.S.C. section 1001. This reminder is being sent out to those facilities in Region 10 at which we believe that PCB transformers and/or PCB capacitors were handled, and which facilities are believed to have experienced irregularities resulting in either improper disposal of PCBs or resulting in gaps in record keeping. A copy of the regulation (40 CFR section 761.180) is enclosed for your convenience.

Sincerely,

Robert A. Poss. Chief

Toxic Substances Control Branch Air and Waste Management Division

Enclosure

called on E/21 about maintaining records for 5 years

MCGRAW EDISON

National Electric Coil

file - Jum File

National Electric Coil Division WcGraw-Edison Company North 415 Fancher Road Post Office Box 3505 TA Spokane, WA 99220

June 15, 1982

509 535 8751

U. S. Environmental Protection Agency Region X 1200 Sixth Avenue Seattle, Washington 98101

Attention: Mr. Donald A. Donaldson,

Chief Compliance Section

Reference: Laboratory Analysis Notice

Dear Mr. Donaldson:

Enclosed please find a copy of the Chemical Transfortation Manifest, reflecting proof that Great Western Chemical has picked up the three drums of hazardous waste that were on our premesis.

I have orders from our Corporate office not to work on any PCB transformers. Hopefully we will not have this problem again.

Sincerely,

Bill Lewis, Plant Manager

bc

enclosure

REGEIVED

COMPLIANCE BRANCH EPA - REGION X

CHEMICAL TRANSPORTATION MANIFEST DESIGNATED TSD FACILITY CHEM-SECURITY SYSTEMS, INC. STAR ROUTE, ARLINGTON, OR. 97812 EPA ID NO. ORD. 08-945-2353

ARLINGTON (503) 454-2777 BELLEVUE (206) 827-0711

PORTLAND (503) 223-1912 VANCOUVER, B.C. (604) 688-7612 42614

	27.75.10.0		NATIONAL QUETIN	- Cari				11-2-	0.00	
GENERATOR CHATCHES CONTRACTOR CON								A ID. NO.		1
ORIGIN ADDRESS N415 Fancher Rd / Spokene, Wa. 99206								PHONE	7-535	-875
	BILLING ADDRE	ss	PO BOX 3505 TA / S	pokane Wa	20		PHONE			
			DOT REQUIRED INFORMATION			DEQ/EPA REQUIRED I	NFORMATION			Fig. 1
071	CONTAINER	НМ	DOT PROPER SHIPPING NAME	HAZARD CLASS	HAZ. MAT	WASTE DESCRIPTION	PHYSICAL	EPA HAZ.	GAL./LB.	FT ³
QTY					ID NO.	The state of the s	STATE	WASTE NO.	GAL./LB.	FI
1	53 gal alr	~	Polychornal Biphenois RO	OBUV F	102311	Polyculorinated Bephanoi (134pp)	Topsel	NoT Applicable	379A1	75
	, agents		400000000000000000000000000000000000000	0046		1254 Arbetor	11/10	7		7.,
	STEAL dr	1	HAZArdou WASE, I much way	OKIN C	NA 9189	1 25 t/210 1 20 Can	, ,			
						Less than ippm PCB, TOKE	50 hijord /	Wet Applicable	5TGAL	7.5
	Trojator	U.	HARROWS MESK, Lyou Nes	OK 111 5		1154 Arcitor		177		
			5		11 969	and a land				
						1254 Aroclor	Solid liquid	not replientle		
						1254 Araclor	liquid	1//		
			/							
LADE	ING REQUIREME	ITC	PCB / HAZARDANIC /	11/5/5						
				17/1/2		PLACARDING REQUIREMENTS				
SPECI	AL INSTRUCTIONS	(HAN	DLING/EMERGENCY)	OT SITUED OF THE OUE	M SECURITY SY	STEMS OFFICES AND OR CONTACT IN THE UNITED OF				
Title to	all materials furnished	l for di	RESPONSE CENTER, U.S. COAST GL	JARD (800) 424-8802. OR (CONTACT. IN C	'STEMS OFFICES AND/OR CONTACT, IN THE UNITED ST ANADA, TRANSPORT CANADA (613) 996-6666 FOR EMEI	RGENCY ASSISTANCE	CE.		
accepta	nce of such materials t	v Chen	sposal herein shall be deemed to be vested in Cher n-Security Systems, Inc., from the generator or trans tial value of any substances contained in such material	norter. The generator chall	have no right to	procedures approved by the Oregon Department of Envi This is to certify that the above named materials are prop tion for transportation according to the applicable regular	ronmental Quality an erly classified, descrit	d the United States Environ ped, packaged, marked, label	mental Protect ed and are in p	ion Agency
ag 3	in writing by Chem-Se	curity S	Systems, Inc. Disposal operations by Chem-Security	Systems, Inc., will be in	accordance with	tion for transportation according to the applicable regular Protection Agency. Signed and dated by the authorized age	tions of the U.S. Dep nt of the generator.	artment of Transportation as	nd the U.S. En	vironmenta
	R NAME (PLEASE P		- 100	SHIPPING DATE <u>6</u>	10/82	ALTERNATE DESIGNATED T/S/D FACILITY (IF ANY).				
GENE	RATOR SIGNATUR	E_2	Sell June			ADDRESS		EPA ID. NO		
2	RANSPORTER NO. 1	كمحصر	Lest Western Chimisal	EPA ID. NO. WAD OS	5605350	3	*****************			
XA	DDRESS N/40	2 7		PHONE 928-019						
<i>_</i>	RANSPORTER SIGNA	-		DATE 6-10-82		_ ADDRESSPHONE SIGNATUREDATE				
T	RANSPORTER NO. 2_			PA ID. NO.		4 CSSI USE ONLY		DATE		
Α	DDRESS			HONE		CSSI REQ. NOBILL OF LADING NO	WEIGHT	TICKET NO	GROSS	
T	RANSPORTER SIGNA	TURE_		ATE		DISPOSAL AREASECTION		DEPTH		
Т	RANSPORTER NO. 3_			PA ID. NO		REC. BY CSSI		-		
Α	DDRESS		Р	HONE		COMMENTS				
Т	RANSPORTER SIGNA	TURE_	C	DATE						
		T/3	S/D RETURNS TO GENERATOR							